

DURING THE FLOWING GRAIDENTS THE WELL WAS BEING FLOWED AT SUCH A RATE THAT THE PRESSURE READINGS WERE FALLING FASTER THAN COULD BE CORRECTLY MEASURED AT THE DEPTHS THAT WERE BEING MEASURED.