	MA OIL COMS	. Coselssion _	Form approved.
Form 3160-5 November 1983) U. JED STA	TEC: 91.	SUBMIT IN TRI JATE*	Budget Bureau No. 1004-0135 Expires August 31, 1985
DEDARTMENT OF TU	FINTERIOR		5. LEASE DESIGNATION AND SERIAL NO.
BUREAU OF LAND MA		, , , , , , , , , , , , , , , , , , , ,	NM 602/1
			NM 69341 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND R (Do not use this form for proposals to drill or to do Use "APPLICATION FOR PERMIT	EPORTS ON eepen or plug back to —" for such propose	WELLS	
1.			7. UNIT AGREEMENT NAME
WELL GAS OTHER Dry Hole		AFR - / 100	
2. NAME OF OPERATOR		SEP 26 '88	8. FARM OR LEASE NAME
BTA OIL PRODUCERS ✓			8710 JV-P Tank
3. ADDRESS OF OPERATOR	•	O. C. D.	9. WELL NO.
104 South Pecos, Midland, Texa	s 79701	ARTESIA, OFFICE	
4. LOCATION OF WELL (Report location clearly and in accordance also space 17 below.)	lance with any State	e requirements.	10. FIELD AND POOL, OR WILDCAT
At surface			Undesignated (Delaware)
5 6 6' FSL & 1,312' FEL			SURVEY OR ARMA
			G 22 M 22 G B 2/ E
- 17 Provence (S	Show whether DF, RT,	CP etc.)	Sec. 33, T-23-S, R-24-E
11. 1000.12 1.51			
3,919' GR	3,933'	К.В.	Eddy N.M.
16. Check Appropriate Box T	o Indicate Natur	re of Notice, Report, or C	Other Data
NOTICE OF INTENTION TO:	1		UBNT REPORT OF:
		W	REPAIRING WELL
TEST WATER SHUT-OFF PULL OR ALTER CASI		WATER SHUT-OFF FRACTURE TREATMENT	ALTERING CARING
FRACTURE TREAT MULTIPLE COMPLETE	$\frac{1}{X}$	SHOOTING OR ACIDIZING	ABANDONMENTS
SHOOT OB ACIDIZE ABANDON*			lug Back
REPAIR WELL CHANGE PLANS (Other)		(Norm: Report results	s of multiple completion on Well eletion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly St proposed work. If well is directionally drilled, give nent to this work.) • Operations 8/9/88 thru 8/12/88	subsurface locations	and measured and true vertic	al depths for all markers and zones perti-
Set CIBP @ 3200' w/ 20' cmt or Perf 2989' - 3057' (28 holes) Acidized w/ 200 gal 10% Acetic Swbd 100% water			in the second se
Proposed			ス m
			C
Set CIBP @ 2900' w/ 20 cmt			
30 sx Plug 2650' - 2550'			
Cut & pull 5 1/2" csg - TOC 1: 45 sx Plug 460' - 360' /c/)10 sx plug at surface	100 spot 100	o'plug(50' in/out) of	
45 sx Plug 460' - 360'	51/2 CS4	stub (TAG)	
(30)	- 0	(50	<u>.</u> ====================================
Installed Dry Hole Marker		(3)2	,
			Post F0-2 9-30-88
			9-30-88
			PXA
			/ & //
1 hereby certify that the foregoing to true and correct			
Xund Same	TITLE Produ	ction Supervisor	DATE <u>9/1/88</u>
SIGNED A STORY			
(This space for Federal or State office use)			- 22 FF
APPROVED BY Conditions of APPROVAL, IF ANY:	TITLE		DATE 9 23 58