				_	10
234567897077				C	(>
			Oil Cons.		
07 3160-5 NEP 2002	UNITED STAT	N. 1001 N	M. DIV-Dis	t. 2	
The RECEIVED	DEPARTMENT OF THI		vv. Granu A sia, NM 84	Venue FORM APPROVED OMB No. 1004-0135 B210 Expires January 31, 2004	
OCD - ARTESIA	BUREAU OF LAND MAI			3. Lease Serial No. NM 32636	•
ాస్తి Do not use t	his form for proposals will. Use Form 3160-3 (A	to drill or to re-enter an		6. If Indian, Allottee or Tribe Name	
	RIPLICATE - Other Ins	buctions on reverse sk	de .	7. If Unit or CA/Agreement, Name and/or No.	
. Type of Well D Oil Well D Gas Well				9 Well Name and Marine I	
. Name of Operator				8. Well Name and No. AMOCO FEDERAL 11-6	
RAM Energy, Inc. 3a. Address 5100 E. Skelly Dr Ste 650 3b. Phone No. (include area code)				9. API Well №. 30-015-26496	•
Tulsa, OK Location of Well (Footage, Sec	74135	918/663-280	<u> </u>	10. Field and Pool, or Exploratory Area	
B 11 23S 28E 8	60FNL & 1651FEL	<i>un;</i>	F	Loving East (Brushy (11. County or Parish, State	any
11 NW NE				Eddy County, NM	
, 12. CHECK AI	PPROPRIATE BOX(ES)	TO INDICATE NATURE	OF NOTICE, REI	PORT, OR OTHER DATA	
TYPE OF SUBMISSION		ТҮРЕ	OF ACTION	•	
XX Notice of Intent	Acidize	Deepen C	Production (Start/R	· _	
_	Akter Casing Casing Repair	K Fracture Treat	Reclamation Recomplete	Well Integrity	
Subsequent Report	Change Plans	Plug and Abandon	Temporarity Aban		
Final Abandonment Notice	Convert to Injection	👾 Plug Back 🗌	Water Disposal		
		ertinent details, including estimate	d starting date of any	proposed work and approximate duration thereof.	
A tach the Bond under which is following completion of the inv testing has been completed. F determined that the site is ready A.) MIRU DDWSU. B.) Set CIBP @ C.) Perforate U D.) TIH w/pkr. Swb & tst. Put well ba	the work will be performed or p volved operations. If the operational distribution of the operation of the o	ertinent details, including estimate ntally, give subsurface locations an provide the Bond No. on file with tion results in a multiple completion l be filed only after all requirement ds. NU BOPE. Re g to 2500 psig (5- 4750-63', 4790-481 Acidize zone w/20 equired. Pull the	ed starting date of any nd measured and true on or recompletion in ents, including reclam 1 tac & TOH -1/2"). 05' & 4813-2 000 gals 7-2 g & pjr. Ru	<pre>vertical depths of all pertinent markers and zones. 4 subsequent reports shall be filed within 30 days a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has w/tbbg. 22' (37' OA, 77 holes). 1/2% HCl & B.S. In tbg,,rods & pump back.</pre>	
Attach the Bond under which is following completion of the inv testing has been completed. F determined that the site is ready A.) MIRU DDWSU. B.) Set CIBP @ C.) Perforate U D.) TIH w/pkr. Swb & tst. Put well ba	the work will be performed or p volved operations. If the operational distribution of the operation of the o	ertinent details, including estimate ntally, give subsurface locations an provide the Bond No. on file with tion results in a multiple completion l be filed only after all requirement ds. NU BOPE. Re g to 2500 psig (5- 4750-63', 4790-481 Acidize zone w/20 equired. Pull the	ed starting date of any nd measured and true on or recompletion in ents, including reclam 1 tac & TOH -1/2"). 05' & 4813-2 000 gals 7-2 g & pjr. Ru	vertical depths of all pertinent markers and zones. I subsequent reports shall be filed within 30 days a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has W/bbg. 22' (37' OA, 77 holes). 1/2% HCl & B.S.	
Attach the Bond under which is following completion of the inv testing has been completed. F determined that the site is ready A.) MIRU DDWSU. B.) Set CIBP @ C.) Perforate U D.) TIH w/pkr. Swb & tst. Put well ba	the work will be performed or p volved operations. If the operational distribution of the operation of the o	ertinent details, including estimate ntally, give subsurface locations an provide the Bond No. on file with tion results in a multiple completion l be filed only after all requirement ds. NU BOPE. Re g to 2500 psig (5- 4750-63', 4790-481 Acidize zone w/20 equired. Pull the	ed starting date of any nd measured and true on or recompletion in ents, including reclam 1 tac & TOH -1/2"). 05' & 4813-2 000 gals 7-2 g & pjr. Ru	<pre>vertical depths of all pertinent markers and zones. 4 subsequent reports shall be filed within 30 days a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has w/tbbg. 22' (37' OA, 77 holes). 1/2% HCl & B.S. In tbg,,rods & pump back.</pre>	
Attach the Bond under which is following completion of the inv testing has been completed. F determined that the site is ready A.) MIRU DDWSU. B.) Set CIBP @ C.) Perforate U D.) TIH w/pkr. Swb & tst. Put well bar The workove	the work will be performed or provided operations. If the operational Abandonment Notices shally for final inspection.) Pull pump & rot±5825'. Test cs / Brushy Canyon Set at ±4700'. Frac treat as rock on production er is scheduled t	ertinent details, including estimate ntally, give subsurface locations an provide the Bond No. on file with tion results in a multiple completion l be filed only after all requirement ds. NU BOPE. Re g to 2500 psig (5- 4750-63', 4790-481 Acidize zone w/20 equired. Pull the	ed starting date of any nd measured and true on or recompletion in ents, including reclam 1 tac & TOH -1/2"). 05' & 4813-2 000 gals 7-2 g & pjr. Ru	<pre>vertical depths of all pertinent markers and zones. 4 subsequent reports shall be filed within 30 days a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has w/tbbg. 22' (37' OA, 77 holes). 1/2% HCl & B.S. In tbg,,rods & pump back.</pre>	
A tach the Bond under which is following completion of the inv testing has been completed. F determined that the site is ready A.) MIRU DDWSU. B.) Set CIBP @ C.) Perforate U D.) TIH w/pkr. Swb & tst. Put well ba The workove	ing is true and correct	ertiment details, including estimate nally, give subsurface locations as provide the Bond No. on file with tion results in a multiple completi Il be filed only after all requirement ds. NU BOPE. Re g to 2500 psig (5- 4750-63', 4790-480 Acidize zone w/20 equired. Pull the begin on August	ed starting date of any nd measured and true on or recompletion in ents, including reclam 1 tac & TOH -1/2"). 05' & 4813-2 000 gals 7-2 g & pjr. Ru	<pre>vertical depths of all pertinent markers and zones. 4 subsequent reports shall be filed within 30 days a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has w/tbbg. 22' (37' OA, 77 holes). 1/2% HCl & B.S. In tbg,,rods & pump back.</pre>	
 A tach the Bond under which is following completion of the invitesting has been completed. F determined that the site is ready A.) MIRU DDWSU. B.) Set CIBP @ C.) Perforate U D.) TIH w/pkr. Swb & tst. Put well bar The workove 4. Thereby certify that the foregoin Name (Printed/Typed) John R. Fri 	the work will be performed or provided operations. If the operational Abandonment Notices shally for final inspection.) Pull pump & rot±5825'. Test cs / Brushy Canyon Set at ±4700'. Frac treat as rock on production or is scheduled t	ertiment details, including estimate nally, give subsurface locations as provide the Bond No. on file with tion results in a multiple completi Il be filed only after all requirement ds. NU BOPE. Re g to 2500 psig (5- 4750-63', 4790-480 Acidize zone w/20 equired. Pull the begin on August	ed starting date of any in measured and true in a BLM/BIA. Required on or recompletion in ents, including reclam 1 tac & TOH -1/2"). 05' & 4813-2 000 gals 7-1 g & pjr. Ru 26, 2002 a	<pre>vertical depths of all pertinent markers and zones. 4 subsequent reports shall be filed within 30 days a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has w/tbbg. 22' (37' OA, 77 holes). 1/2% HCl & B.S. In tbg,,rods & pump back.</pre>	
A tach the Bond under which is following completion of the invites following completion of the invites following completion of the invites following completion of the invites A.) MIRU DDWSU. B.) Set CIBP @ C.) Perforate U D.) TIH w/pkr. Swb & tst. Put well bar The workove 4. I hereby certify that the foregoin Name (Printed/Typed) John R. Fri	ing is true and correct ck	rtinent details, including estimate nally, give subsurface locations an provide the Bond No. on file with ion results in a multiple completion in the filed only after all requirement ds. NU BOPE. Re g to 2500 psig (5- 4750-63', 4790-480 Acidize zone w/20 equired. Pull the obegin on August Title	od starting date of any nd measured and true 'n BLM/BIA. Required on or recompletion in ents, including reclam. 1 tac & TOH -1/2"). 05' & 4813-2 000 gals 7-1 g & pjr. Ru 26, 2002 a 0per. Mgr. 5/02-	<pre>vertical depths of all pertinent markers and zones. 4 subsequent reports shall be filed within 30 days a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has w/tbbg. 22' (37' OA, 77 holes). 1/2% HCl & B.S. In tbg,,rods & pump back.</pre>	
A then the Bond under which is following completion of the in- testing has been completed. F determined that the site is ready A.) MIRU DDWSU. B.) Set CIBP @ C.) Perforate U D.) TIH w/pkr. Swb & tst. Put well ba- The workove 4. Thereby certify that the foregoin Name (Printed/Typed) John R. Fri Signature	ing is true and correct ck	ertiment details, including estimate nally, give subsurface locations an provide the Bond No. on file with ion results in a multiple completion in be filed only after all requirement ds. NU BOPE. Re g to 2500 psig (5- 4750-63', 4790-480 Acidize zone w/20 equired. Pull the obegin on August Title Date S/ FOR FEDERAL OF STAT	ed starting date of any na measured and true 'n BLM/BIA. Required on or recompletion in ents, including reclam 1 tac & TOH -1/2"). 05' & 4813-2 000 gals 7-1 g & pjr. Ru 26, 2002 a	vertical depths of all pertinent markers and zones. I subsequent reports shall be filed within 30 days a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has w/tbg. 22' (37' OA, 77 holes). 1/2% HCl & B.S. In tbg,,rods & pump back. In tbg,,rods & pump back. In d be finished in 10 days	
A then the Bond under which is following completion of the in- testing has been completed. F determined that the site is ready A.) MIRU DDWSU. B.) Set CIBP @ C.) Perforate U D.) TIH w/pkr. Swb & tst. Put well ba- The workove 4. Thereby certify that the foregoin Name (Printed/Typed) John R. Fri Signature	the work will be performed or provided operations. If the operational Abandonment Notices shally for final inspection.) Pull pump & routes shally for final inspection.) Set at ±4700'. Frac treat as routes and correct as scheduled the final state shall be able to be	Title Title Title BODA FOR FEDERAL OF STATE	od starting date of any nd measured and true 'n BLM/BIA. Required on or recompletion in ents, including reclam. 1 tac & TOH -1/2"). 05' & 4813-2 000 gals 7-1 g & pjr. Ru 26, 2002 a 0per. Mgr. 5/02-	vertical depths of all pertinent markers and zones. I subsequent reports shall be filed within 30 days a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has w/tbg. 22' (37' OA, 77 holes). 1/2% HCl & B.S. In tbg,,rods & pump back. In tbg,,rods & pump back. In d be finished in 10 days	