Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088	30-015-26684
DISTRICT III	5. Indicate Type of Lesse STATE FEE X
1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No.
OLINDOV MOTIONS AND TOTAL	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"	7. Lease Name or Unit Agreement Name:
(FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OR. GAS. WELL X WELL GIBER	Brantley
2. Name of Operator MAY 3 1991	
Amoco Production Company	8. Well No.
3 Address of Oceanies	2 0 Parl and a Wilder
P. O. Box 3092, Houston, TX 77253	9. Pool mamme or Wildcat Loving Delaware, East
4. Well Location	Leving belawate, hast
Unit Letter J: 1872 Feet From The South Line and 16	53 Feet From The East Line
22	rest from the Line
Section 22 Township 23-S Range 28-E	NMPM Eddy County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3033.8 GR	
11. Check Appropriate Box to Indicate Nature of Notice, R	
NOTICE OF INTENTION TO:	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING	
Commence braces	
PULL OR ALTER CASING CASING TEST AND C	EMENT JOB
OTHER: Perf. acidize. frac X OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give partinent detes, included	ding estimated date of marring arm reserved
OTHER: Perf. acidize. frac X OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incluwork) SEE RULE 1103.	ding estimated date of starting any proposed
12. Describe Proposed or Completed Operations (Clearly state all persinent details, and give persinent dates, incluwork) SEE RULE 1103.	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incluwork) SEE RULE 1103. Run perf depth control log from PBTD to 5300'. Peforate at intervals: 6106-32, 6136-39, 6160-72, 6194-6202.	4 JSPF w/csg gun the following
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incluwork) SEE RULE 1103. Run perf depth control log from PBTD to 5300'. Peforate at intervals: 6106-32, 6136-39, 6160-72, 6194-6202. RIH w/ 2-7/8" tbg X pkr to 6000' X set pkr X prs test backs	4 JSPF w/csg gun the following
12. Describe Proposed or Completed Operations (Clearly state all persinent datails, and give persinent dates, incluwork) SEE RULE 1103. Run perf depth control log from PBTD to 5300'. Peforate at intervals: 6106-32, 6136-39, 6160-72, 6194-6202. RIH w/ 2-7/8" tbg X pkr to 6000' X set pkr X prs test backs Acidize w/2000 gals 7-1/2% acid w/ corrosion inhibitor, cl.	4 JSPF w/csg gun the following
12. Describe Proposed or Completed Operations (Clearly state all partinent datails, and give partinent datas, incluwork) SEE RULE 1103. Run perf depth control log from PBTD to 5300'. Peforate at intervals: 6106-32, 6136-39, 6160-72, 6194-6202. RIH w/ 2-7/8" tbg X pkr to 6000' X set pkr X prs test backs Acidize w/2000 gals 7-1/2% acid w/ corrosion inhibitor, cl. x 240 perf balls.	4 JSPF w/csg gun the following
12 Describe Proposed or Completed Operations (Clearly state all persisent details, and give persisent dates, inclusively) SEE RULE 1103. Run perf depth control log from PBTD to 5300'. Peforate at intervals: 6106-32, 6136-39, 6160-72, 6194-6202. RIH w/ 2-7/8" tbg X pkr to 6000' X set pkr X prs test backs Acidize w/2000 gals 7-1/2% acid w/ corrosion inhibitor, cl. x 240 perf balls. Frac down 2-7/8" tbg at 10 BPM as follows:	4 JSPF w/csg gun the following
12 Describe Proposed or Completed Operations (Clearly state all persises details, and give persises dates, inclusively) SEE RULE 1103. Run perf depth control log from PBTD to 5300'. Peforate at intervals: 6106-32, 6136-39, 6160-72, 6194-6202. RIH w/ 2-7/8" tbg X pkr to 6000' X set pkr X prs test backs Acidize w/2000 gals 7-1/2% acid w/ corrosion inhibitor, cl. x 240 perf balls. Frac down 2-7/8" tbg at 10 BPM as follows: 12000 gals X-link gel - pad	4 JSPF w/csg gun the following
12 Describe Proposed or Completed Operations (Clearly state all persistent details, and give persistent dates, inclusively) SEE RULE 1103. Run perf depth control log from PBTD to 5300'. Perforate at intervals: 6106-32, 6136-39, 6160-72, 6194-6202. RIH w/ 2-7/8" tbg X pkr to 6000' X set pkr X prs test backs Acidize w/2000 gals 7-1/2% acid w/ corrosion inhibitor, cl. x 240 perf balls. Frac down 2-7/8" tbg at 10 BPM as follows: 12000 gals X-link gel - pad 3000 gals X-link gel w/1 ppg 20/40 OTTAWA SAND	4 JSPF w/csg gun the following
12 Describe Proposed or Completed Operations (Clearly state all persistent details, and give persistent dates, inclusivery) SEE RULE 1103. Run perf depth control log from PBTD to 5300'. Peforate at intervals: 6106-32, 6136-39, 6160-72, 6194-6202. RIH w/ 2-7/8" tbg X pkr to 6000' X set pkr X prs test backs Acidize w/2000 gals 7-1/2% acid w/ corrosion inhibitor, cl. x 240 perf balls. Frac down 2-7/8" tbg at 10 BPM as follows: 12000 gals X-link gel - pad 3000 gals X-link gel w/1 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/2 ppg 20/40 OTTAWA SAND	4 JSPF w/csg gun the following
12 Describe Proposed or Completed Operations (Clearly nate all partinent data)s, and give partinent datas, inclusively). Run perf depth control log from PBTD to 5300'. Peforate at intervals: 6106-32, 6136-39, 6160-72, 6194-6202. RIH w/ 2-7/8" tbg X pkr to 6000' X set pkr X prs test backs Acidize w/2000 gals 7-1/2% acid w/ corrosion inhibitor, cl x 240 perf balls. Frac down 2-7/8" tbg at 10 BPM as follows: 12000 gals X-link gel - pad 3000 gals X-link gel w/1 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/2 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/3 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/3 ppg 20/40 OTTAWA SAND	4 JSPF w/csg gun the following
12 Describe Proposed or Completed Operations (Clearly nate all partinent data)s, and give partinent datas, inclusively) SEE RULE 1103. Run perf depth control log from PBTD to 5300'. Peforate at intervals: 6106-32, 6136-39, 6160-72, 6194-6202. RIH w/ 2-7/8" tbg X pkr to 6000' X set pkr X prs test backs Acidize w/2000 gals 7-1/2% acid w/ corrosion inhibitor, cl x 240 perf balls. Frac down 2-7/8" tbg at 10 BPM as follows: 12000 gals X-link gel - pad 3000 gals X-link gel w/1 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/2 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/3 ppg 20/40 OTTAWA SAND	4 JSPF w/csg gun the following
12 Describe Proposed or Completed Operations (Clearly nate all persinent datails, and give persinent datas, inclusively). Run perf depth control log from PBTD to 5300'. Peforate at intervals: 6106-32, 6136-39, 6160-72, 6194-6202. RIH w/ 2-7/8" tbg X pkr to 6000' X set pkr X prs test backs Acidize w/2000 gals 7-1/2% acid w/ corrosion inhibitor, cl. x 240 perf balls. Frac down 2-7/8" tbg at 10 BPM as follows: 12000 gals X-link gel - pad 3000 gals X-link gel w/1 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/2 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/3 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/3 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/4 ppg 20/40 OTTAWA SAND	4 JSPF w/csg gun the following
12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusively). Run perf depth control log from PBTD to 5300'. Peforate at intervals: 6106-32, 6136-39, 6160-72, 6194-6202. RIH w/ 2-7/8" tbg X pkr to 6000' X set pkr X prs test backs Acidize w/2000 gals 7-1/2% acid w/ corrosion inhibitor, cl. x 240 perf balls. Frac down 2-7/8" tbg at 10 BPM as follows: 12000 gals X-link gel - pad 3000 gals X-link gel w/1 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/2 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/3 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/4 ppg 20/40 OTTAWA SAND 3000 gals X-link gel w/4 ppg 20/40 OTTAWA SAND 3000 gals X-link gel w/5 ppg 16/30 Resin coated sand	4 JSPF w/csg gun the following ide. ay stabilizer, 20 gals xylene
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give partinent dates, inclusively) SEE RULE 1103. Run perf depth control log from PBTD to 5300'. Peforate at intervals: 6106-32, 6136-39, 6160-72, 6194-6202. RIH w/ 2-7/8" tbg X pkr to 6000' X set pkr X prs test backs Acidize w/2000 gals 7-1/2% acid w/ corrosion inhibitor, cl. x 240 perf balls. Frac down 2-7/8" tbg at 10 BPM as follows: 12000 gals X-link gel - pad 3000 gals X-link gel w/1 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/2 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/3 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/4 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/4 ppg 20/40 OTTAWA SAND 3000 gals X-link gel w/5 ppg 16/30 Resin coated sand	4 JSPF w/csg gun the following ide. ay stabilizer, 20 gals xylene See Attachment
12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusively). Run perf depth control log from PBTD to 5300'. Peforate at intervals: 6106-32, 6136-39, 6160-72, 6194-6202. RIH w/ 2-7/8" tbg X pkr to 6000' X set pkr X prs test backs Acidize w/2000 gals 7-1/2% acid w/ corrosion inhibitor, cl. x 240 perf balls. Frac down 2-7/8" tbg at 10 BPM as follows: 12000 gals X-link gel - pad 3000 gals X-link gel w/1 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/2 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/3 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/4 ppg 20/40 OTTAWA SAND 3000 gals X-link gel w/4 ppg 20/40 OTTAWA SAND 3000 gals X-link gel w/5 ppg 16/30 Resin coated sand	4 JSPF w/csg gun the following ide. ay stabilizer, 20 gals xylene See Attachment Analyst DATE 5/1/91
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give partinent dates, inclusively) SEE RULE 1103. Run perf depth control log from PBTD to 5300'. Peforate at intervals: 6106-32, 6136-39, 6160-72, 6194-6202. RIH w/ 2-7/8" tbg X pkr to 6000' X set pkr X prs test backs Acidize w/2000 gals 7-1/2% acid w/ corrosion inhibitor, cl. x 240 perf balls. Frac down 2-7/8" tbg at 10 BPM as follows: 12000 gals X-link gel - pad 3000 gals X-link gel w/1 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/2 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/3 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/4 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/4 ppg 20/40 OTTAWA SAND 3000 gals X-link gel w/5 ppg 16/30 Resin coated sand	4 JSPF w/csg gun the following ide. ay stabilizer, 20 gals xylene See Attachment
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusively.) SEE RULE 1103. Run perf depth control log from PBTD to 5300'. Perforate at intervals: 6106-32, 6136-39, 6160-72, 6194-6202. RIH w/ 2-7/8" tbg X pkr to 6000' X set pkr X prs test backs Acidize w/2000 gals 7-1/2% acid w/ corrosion inhibitor, cl x 240 perf balls. Frac down 2-7/8" tbg at 10 BPM as follows: 12000 gals X-link gel - pad 3000 gals X-link gel w/1 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/2 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/3 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/3 ppg 20/40 OTTAWA SAND 3000 gals X-link gel w/4 ppg 20/40 OTTAWA SAND 3000 gals X-link gel w/5 ppg 16/30 Resin coated sand I hereby certify that the information above is true and complete to the best of my knowledge and belief. SKINATURE Kim A. Column	4 JSPF w/csg gun the following ide. ay stabilizer, 20 gals xylene See Attachment Analyst DATE 5/1/91 713/
12. Describe Proposed or Completed Operations (Clearly state all partinent details, and give partinent dates, inclusivork) SEE RULE 1103. Run perf depth control log from PBTD to 5300'. Peforate at intervals: 6106-32, 6136-39, 6160-72, 6194-6202. RIH w/ 2-7/8" tbg X pkr to 6000' X set pkr X prs test backs Acidize w/2000 gals 7-1/2% acid w/ corrosion inhibitor, cl. x 240 perf balls. Frac down 2-7/8" tbg at 10 BPM as follows: 12000 gals X-link gel - pad 3000 gals X-link gel w/1 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/2 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/3 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/3 ppg 20/40 OTTAWA SAND 3000 gals X-link gel w/4 ppg 20/40 OTTAWA SAND 3000 gals X-link gel w/5 ppg 16/30 Resin coated sand I bereby certify that the information above is true and complete to the best of my knowledge and belief. SKONATURE Asst. Admin. TITLE Asst. Admin.	4 JSPF w/csg gun the following ide. ay stabilizer, 20 gals xylene See Attachment Analyst DATE 5/1/91 713/15/10/10/10/10/10/10/10/10/10/10/10/10/10/
12. Describe Proposed or Completed Operations (Clearly state all persistent details, and give partitional dates, inclinatively. SEE RULE 1103. Run perf depth control log from PBTD to 5300'. Peforate at intervals: 6106-32, 6136-39, 6160-72, 6194-6202. RIH w/ 2-7/8" tbg X pkr to 6000' X set pkr X prs test backs Acidize w/2000 gals 7-1/2% acid w/ corrosion inhibitor, cl x 240 perf balls. Frac down 2-7/8" tbg at 10 BPM as follows: 12000 gals X-link gel - pad 3000 gals X-link gel w/1 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/2 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/3 ppg 20/40 OTTAWA SAND 4000 gals X-link gel w/3 ppg 20/40 OTTAWA SAND 3000 gals X-link gel w/4 ppg 20/40 OTTAWA SAND 3000 gals X-link gel w/5 ppg 16/30 Resin coated sand I hereby certify that the information above is true and complete to the best of my knowledge and ballef. SIGNATURE A. (Olimination by Indianated States Unit) ORIGINAL SIGNED BY	4 JSPF w/csg gun the following ide. ay stabilizer, 20 gals xylene See Attachment Analyst DATE 5/1/91 713/

ATTACHMENT

Flush w/tbg vol less 300' w/base gel.
Pump at 10 BPM. Estimated surface treating pressure is 2500 PSI.
Frac fluid to contain /1000 gal (Western Co.) or equivalent:

```
30# J-4 (Gelling Agent)
2# CL-2 (Crosslinker)
2 gal B-31
2 gal Nine-40 (De-emulsifer)
1 gal Clay Master-4 (clay stabilizer)
5 gal Aquaseal-L (fluid loss additive - first tank)
5 # B-5 (Breaker)
```

Flush 1500 gals base gel.