		_	- · · · · · · · · · · · · · · · · · · ·
		AL.	OIL CONS COMMISSION CIST
		<b>n</b> n	
			tesia, NM 88210
Form 3160-5 (June 1990)		TED STATES	Budget Bureau No. 1004-0135
		T OF THE INTERIOR AND MANAGEMENT	Expires: March 31, 1993 5. Lease Designation and Serial No.
	BUREAU OF I	AND MANAGEMENT	NM-77018
		AND REPORTS ON WELLS	6. If Indian, Allottee or Tribe Name
Do not use t	his form for proposals to dri Use "APPLICATION FOR	III or to deepen or reentry to a different reservoir. R PERMIT—" for such proposals	
	SUBMIT	IN TRIPLICATE	7. If Unit or CA, Agreement Designation
I. Type of Well		······································	- NM NM 85357
	Gas Uther		8. Well Name and No.
2. Name of Operato			Pecos Valley "7" 2
	reyfus Natural Gas Con		9. API Well No.
3. Address and Tele	•	405/749-1300	30-0/5 - 26865
14000 Qu	uail Springs Pkwy., St I (Footage, Sec., T., R., M., or Survey De	te.600, Okla. City, OK 73134	Malaga Atoka
		• •	11. County or Parish, State
	L and 1414' FWL		
Section	7-T24S-R29E	Unit C	Eddy, NM
2. CH	ECK APPROPRIATE BOX(	s) TO INDICATE NATURE OF NOTICE, REPO	DRT, OR OTHER DATA
TYP	PE OF SUBMISSION	TYPE OF ACTION	N
x	Notice of Intent	Abandonment	Change of Plans
_	·		
	Subsequent Report	Plugging Back	Non-Routine Fracturing
		Casing Repair	Water Shut-Off
	Final Abandonment Notice	Altering Casing	Water Shut-Off Conversion to Injection Dispose Water
		Altering Casing Other	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
3. Describe Propos give subsur Recomple	sed or Completed Operations (Clearly state a rface locations and measured and true verti	Altering Casing Other Ill pertinent details, and give pertinent dates, including estimated date of starn cal depths for all markers and zones pertinent to this work.)* sand and commingle with the current	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ing any proposed work. If well is directionally drilled,
13. Describe Propos give subsur Recomple	sed or Completed Operations (Clearly state a rface locations and measured and true verti ete to the Atoka "AD"	Altering Casing Other Ill pertinent details, and give pertinent dates, including estimated date of starn cal depths for all markers and zones pertinent to this work.)* sand and commingle with the current	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well completion or Recompletion Report and Log form.) ting any proposed work. If well is directionally drilled, Atoka Bank Formation.
13. Describe Propos give subsur Recomple	sed or Completed Operations (Clearly state a rface locations and measured and true verti ete to the Atoka "AD"	Altering Casing Other ull pertinent details, and give pertinent dates, including estimated date of start cal depths for all markers and zones pertinent to this work.)* sand and commingle with the current e and schematic. RECE	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well completion or Recompletion Report and Log form.) Ting any proposed work. If well is directionally drilled, Atoka Bank Formation.
3. Describe Propos give subsur Recomple	sed or Completed Operations (Clearly state a rface locations and measured and true verti ete to the Atoka "AD"	Altering Casing Other ull pertinent details, and give pertinent dates, including estimated date of start cal depths for all markers and zones pertinent to this work.)* sand and commingle with the current e and schematic. RECE	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well completion or Recompletion Report and Log form.) Ting any proposed work. If well is directionally drilled, Atoka Bank Formation.
3. Describe Propos give subsur Recomple	sed or Completed Operations (Clearly state a rface locations and measured and true verti ete to the Atoka "AD"	Altering Casing Other ull pertinent details, and give pertinent dates, including estimated date of starn cal depths for all markers and zones pertinent to this work.)* sand and commingle with the current e and schematic.	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well completion or Recompletion Report and Log form.) Ting any proposed work. If well is directionally drilled, Atoka Bank Formation.
3. Describe Propos give subsur Recomple	sed or Completed Operations (Clearly state a rface locations and measured and true verti ete to the Atoka "AD"	Altering Casing Other ull pertinent details, and give pertinent dates, including estimated date of start cal depths for all markers and zones pertinent to this work.)* sand and commingle with the current e and schematic. RECE	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well completion or Recompletion Report and Log form.) Ting any proposed work. If well is directionally drilled, Atoka Bank Formation.
13. Describe Propos give subsur Recomple	sed or Completed Operations (Clearly state a rface locations and measured and true verti ete to the Atoka "AD"	Altering Casing Other ull pertinent details, and give pertinent dates, including estimated date of starn cal depths for all markers and zones pertinent to this work.)* sand and commingle with the current e and schematic.	Conversion to Injection Conversion to Injection Completion or Recompletion Report and Log form.) Completion of Recompletion Report and Log form.) Completion Completion Report and Log form.) Completion Report and Log form.) Completion Report and Log form.) Completion Report and Report and Log form.) Completion Report and Report
<ul> <li>13. Describe Propos give subsur</li> <li>Recomple</li> <li>See atta</li> </ul>	sed or Completed Operations (Clearly state a rface locations and measured and true verti ete to the Atoka "AD" achments for procedure	Altering Casing Other ull pertinent details, and give pertinent dates, including estimated date of starn cal depths for all markers and zones pertinent to this work.)* sand and commingle with the current e and schematic.	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well completion or Recompletion Report and Log form.) Ting any proposed work. If well is directionally drilled, Atoka Bank Formation.
<ul> <li>13. Describe Proposing ive subsurface subsurface subsurface set at the set of the set</li></ul>	sed or Completed Operations (Clearly state a rface locations and measured and true verti- ete to the Atoka "AD" achments for procedure achments is for procedure where the foregoing is true and correct	Altering Casing Other	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well completion or Recompletion Report and Log form.) ting any proposed work. If well is directionally drilled, Atoka Bank Formation.
<ul> <li>13. Describe Proposing ive subsurface subsurface subsurface set at the set of the set</li></ul>	sed or Completed Operations (Clearly state a rface locations and measured and true verti- ete to the Atoka "AD" achments for procedure achments is the procedure whet the foregoing is true and correct	Altering Casing Other	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well completion or Recompletion Report and Log form.) ting any proposed work. If well is directionally drilled, Atoka Bank Formation.

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

# LOUIS DREYFUS NATURAL GAS CORP

# PECOS VALLEY "7" Federal Com #1

### C SEC &-T24S-R29E

#### EDDY COUNTY, NEW MEXICO

# PROCEDURE TO RECOMPLETE THE ATOKA "AD" SAND AND COMMINGLE WITH THE ATOKA BANK FORMATION

- 1. MI & RU Slickline. RIH w/1.81" FWV check valve plug and set same in profile nipple @ 12,048'.
- 2. Load tbg w/ 2% KCL treated water and test standing valve to 8000 psi. Release slickline unit.
- 3. MI & RU workover unit. ND wellhead and NU BOP. Release on/off tool.
- 4. Pickel Tbg w/ 250 gals 15% acid and reverse back acid.
- 5. Spot 250 gals 10% acetic acid over Atoka "AD" sand. TOOH w/ tbg and BHA.
- 6. TIH w/ on/off tool shuck, 4 1/2" OD baker lok-set pkr, 1.87" RF on/off tool and tbg. Set packer at 11,750'.
- 7. RU swab tools and swab well down to 5000'.
- 8 RU wireline and perforate Atoka "AD" sand f/ 12,038'-12,042' w/ 9 holes using a 1 11/16" enerjet gun.
- 9. Flow test well. Breakdown with acetic acid if needed.
- 10. Acidize well per attached recommendation.

