

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

Attn: Ray Smith

WELL API NO. 30-015-26905
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Nymeyer "A"
8. Well No. 3
9. Pool name or Wildcat <del>Undesignated</del> <i>East Loving Pool</i>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) RKB 3011 GR 2999

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER T/A
2. Name of Operator <i>P &amp; P Producing Inc.</i> <del>Parker &amp; Parsley Development Co.</del>
3. Address of Operator P. O. Box 3178 Midland, Texas 79702
4. Well Location Unit Letter <u>K</u> : <u>2130</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>15</u> Township <u>23S</u> Range <u>28E</u> NMPM <u>Eddy</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) RKB 3011 GR 2999

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. (Start 3-28-94)

1. Set CIBP @ 6106 & dump 35' cmt on T/plug w/SW mud.
2. Spot 25 sx cmt 3854-3754' w/mud to cover DVT.
3. Spot 25 sx cmt to cover T/Delaware & B/salt at 2570'.
4. Spot 25 sx cmt 605-505' for 8 5/8" shoe plug. Salvage wellheads.
5. Spot 50 ft plug in surface.
6. Install D.H. marker at edge of pad, w/specific directions to P/A borehole.
7. Clean location, backfill cellar, etc.
8. Leave location & road intact at request of farmer, Mr. C. M. Carrasco, Jr., Loving, NM., (505)745-3343.

NOTE: There will be no salvaged casing. Refer to attached schematic drawing.  
Rods and pump jack have been removed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bob Yeates TITLE Consultant

DATE 2-24-94

TYPE OR PRINT NAME Bob Yeates

TELEPHONE NO. 915-571-1237

(This space for State Use)

APPROVED BY [Signature]

TITLE Dist. Supervisor (Temporary) DATE 3-24-94

CONDITIONS OF APPROVAL, IF ANY:

Notice N.M.O.C.C. in sufficient time to witness

Approval valid for 180 days