- 8/26/93: Lay down ll jts drill pipe. Wait on more cement. Reset Plug #7 (8-5/8"
 (cont) shoe) at 2800' w/ 35 sx Cl "H". Lay down l2 jts. Set Plug #8 (Surface)
 w/ 10 sx Cl "H". Circ'd l sx cmt. Lay down 2 jts. RD lay down machine
 & Dowell.
- 8/27/93: ND stack, cut off wellhead, install dry hole marker, jet and clean all pits. Rig released at 9:00 a.m. MST. Well plugged and abandoned.