	NA .m	CA-Ar	tesia	~ (P.Q. 86	H-CONS, COMMISSION X 1980 NEW MEXICO 88240
21/05	I.	NITED STATES				FORM APPROVED
orm 3160-5 June 1990)	•					Budget Bureau No. 1004-0135
une 19901		ENT OF THE IN				Expires: March 31, 1993
	BUREAU O	F LAND MANA	GEMENT		5.	Lease Designation and Serial No.
Do not use	SUNDRY NOTICE this form for proposals to Use "APPLICATION I	drill or to deepe	n or reentry to a			NM-77046 If Indian. Allottee or Tribe Name
	SUBN	AIT IN TRIPLIC	ATE			If Unit or CA. Agreement Designation
Type or Well	- 6					
XX Vell	Gas Gas Well Other					Well Name and No.
2 Name of Opera			_	MECCIY21		rth Pure Gold 9 Fed
	Fe Energy Operating	<u>, Partners, I</u>	<u>.</u>		· 9.	30-015-2 2229
Address and Te			70701	311 - 5. ' 9	A 10	Field and Pool, or Exploratory Area
	. Texas, Suite 1330, ell (Footage, Sec., T., R., M., or Surv		xas /9/01	UUL <u>3.9</u>		Los Medanos (Delawar
- Location of Wi	en eroouzge, sect. 1., K., M., OF SURV	17 Description		0.00		County or Parish/State
(M).	660' FSL and 660' FW	Л., Sec. 9, 1	-235, R-31E	ARJESIA OFT		Eddy
(),	•••• -••- •••• •••• -•	_,, _	,			Sec. 9, T-23S, R-31E
Cł	HECK APPROPRIATE BO	DX(s) TO INDIC	ATE NATURE C	F NOTICE, R	EPORT.	
	PE OF SUBMISSION			TYPE OF AC	TION	
	→ Notice of Intent		Abandonment			Change of Plans
						New Construction
x	Subsequent Report		Plugging Back			Non-Routine Fracturing
-	_		Casirig Repair			Water Shut-Off
<i>ب</i> ـــ	Final Abandonment Notice		Altering Casing X Other <u>Spud</u> Casin	<u>and set su</u> ng	<u>rf.</u>	Conversion to Injection Dispose Water Note: Report results of multiple completion on V
		tate all pertinent details, a vertical depths for all m	ind give pertinent dates, in	cluding estimated date	of starting any	Completion or Recompletion Report and Log for y proposed work. If well is directionally dr
13. Describe Prop give subs	posed or Completed Operations (Clearly s surface locations and measured and true	·				
 Describe Prop g:ve subs 5/29/94: 	surface locations and measured and true		CST. Drlg.			
give subs	Spud $17-1/2$ " hole a	at 5:30 p.m. 1 ran 10 jts "C" Lite 65: 'd 100 sx to	13-3/8" 48# 1 35:1 w/ 2% Ca pit. Plug de	aCl2 follow	ed by 2	225 sx C1 "C"
g:ve subs 5/29/94:	Spud 17-1/2" hole a Depth 425'. RU and Cemented w/ 126 sx w/ 2% CaCl ₂ . Circ ¹ Back out landing an	at 5:30 p.m. I ran 10 jts "C" Lite 65: 'd 100 sx to nd screw in H casing to 60	13-3/8" 48# 1 35:1 w/ 2% Ca pit. Plug do nead. NU BOP. 00 psi, ok.	aCl2 follow own at 5:45	ed by 2 p.m. (225 sx C1 "C" CST. WOC.
g ve subs 5/29/94: 5/30/94:	Spud 17-1/2" hole a Depth 425'. RU and Cemented w/ 126 sx w/ 2% CaCl ₂ . Circ ¹ Back out landing an WOC. TIH and test	at 5:30 p.m. I ran 10 jts "C" Lite 65: 'd 100 sx to nd screw in H casing to 60	13-3/8" 48# 1 35:1 w/ 2% Ca pit. Plug do nead. NU BOP. 00 psi, ok.	aCl2 follow own at 5:45 PU BHA and	ed by 2 p.m. (TIH. V	225 sx C1 "C" CST. WOC. NOC total of
g ve subs 5/29/94: 5/30/94:	Spud 17-1/2" hole a Depth 425'. RU and Cemented w/ 126 sx w/ 2% CaCl ₂ . Circ ¹ Back out landing an WOC. TIH and test	at 5:30 p.m. I ran 10 jts "C" Lite 65: 'd 100 sx to nd screw in H casing to 60	13-3/8" 48# 1 35:1 w/ 2% Ca pit. Plug do nead. NU BOP. 00 psi, ok.	aCl2 follow own at 5:45 PU BHA and	ed by 2 p.m. (TIH. V	225 sx C1 "C" CST. WOC.
g ve subs 5/29/94: 5/30/94:	Spud 17-1/2" hole a Depth 425'. RU and Cemented w/ 126 sx w/ 2% CaCl ₂ . Circ ¹ Back out landing an WOC. TIH and test	at 5:30 p.m. I ran 10 jts "C" Lite 65: 'd 100 sx to nd screw in H casing to 60	13-3/8" 48# 1 35:1 w/ 2% Ca pit. Plug do nead. NU BOP. 00 psi, ok.	aCl2 follow own at 5:45	ed by 2 p.m. (TIH. V	225 sx C1 "C" CST. WOC. NOC total of
g ve subs 5/29/94: 5/30/94:	Spud 17-1/2" hole a Depth 425'. RU and Cemented w/ 126 sx w/ 2% CaCl ₂ . Circ ¹ Back out landing an WOC. TIH and test	at 5:30 p.m. I ran 10 jts "C" Lite 65: 'd 100 sx to nd screw in H casing to 60	13-3/8" 48# 1 35:1 w/ 2% Ca pit. Plug do nead. NU BOP. 00 psi, ok.	aCl2 follow own at 5:45 PU BHA and	ed by 2 p.m. (TIH. V	225 sx C1 "C" CST. WOC.
g ve subs 5/29/94: 5/30/94:	Spud 17-1/2" hole a Depth 425'. RU and Cemented w/ 126 sx w/ 2% CaCl ₂ . Circ ¹ Back out landing an WOC. TIH and test	at 5:30 p.m. I ran 10 jts "C" Lite 65: 'd 100 sx to nd screw in H casing to 60	13-3/8" 48# 1 35:1 w/ 2% Ca pit. Plug do nead. NU BOP. 00 psi, ok.	aCl2 follow own at 5:45 PU BHA and	ed by 2 p.m. (TIH. V	225 sx C1 "C" CST. WOC.
g ve subs 5/29/94: 5/30/94:	Spud 17-1/2" hole a Depth 425'. RU and Cemented w/ 126 sx w/ 2% CaCl ₂ . Circ ¹ Back out landing an WOC. TIH and test	at 5:30 p.m. I ran 10 jts "C" Lite 65: 'd 100 sx to nd screw in H casing to 60	13-3/8" 48# 1 35:1 w/ 2% Ca pit. Plug do nead. NU BOP. 00 psi, ok.	aCl2 follow own at 5:45 PU BHA and	ed by 2 p.m. (TIH. V	225 sx C1 "C" CST. WOC.
g ve subs 5/29/94: 5/30/94: 5/31/94:	Spud 17-1/2" hole a Depth 425'. RU and Cemented w/ 126 sx w/ 2% CaCl ₂ . Circ ¹ Back out landing an WOC. TIH and test	at 5:30 p.m. I ran 10 jts "C" Lite 65: 'd 100 sx to nd screw in H casing to 60 drilling open	13-3/8" 48# 1 35:1 w/ 2% Ca pit. Plug do nead. NU BOP. 00 psi, ok.	aCl2 follow own at 5:45 PU BHA and	ed by 2 p.m. (TIH. V	225 sx C1 "C" CST. WOC.
g ve subs 5/29/94: 5/30/94: 5/31/94:	Spud 17-1/2" hole a Depth 425'. RU and Cemented w/ 126 sx w/ 2% CaCl ₂ . Circ' Back out landing an WOC. TIH and test 24 hours. Resume of	at 5:30 p.m. I ran 10 jts "C" Lite 65: 'd 100 sx to nd screw in H casing to 60 drilling open	13-3/8" 48# 1 35:1 w/ 2% C pit. Plug do nead. NU BOP. 00 psi, ok. cations.	aCl2 follow own at 5:45 PU BHA and	ed by 2 p.m. (TIH. V	225 sx C1 "C" CST. WOC.
g ve subs 5/29/94: 5/30/94: 5/31/94:	Spud 17-1/2" hole a Depth 425'. RU and Cemented w/ 126 sx w/ 2% CaCl ₂ . Circ ¹ Back out landing an WOC. TIH and test 24 hours. Resume o	at 5:30 p.m. I ran 10 jts "C" Lite 65: 'd 100 sx to and screw in H casing to 60 drilling open	13-3/8" 48# 1 35:1 w/ 2% C pit. Plug do nead. NU BOP. 00 psi, ok. cations.	aCl2 follow own at 5:45 PU BHA and	ed by 2 p.m. (TIH. V	225 sx C1 "C" CST. WOC. NOC total of C (1) C (1
g ve subs 5/29/94: 5/30/94: 5/31/94: 5/31/94:	surface locations and measured and true Spud 17-1/2" hole a Depth 425'. RU and Cemented w/ 126 sx w/ 2% CaCl ₂ . Circ' Back out landing an WOC. TIH and test 24 hours. Resume of the sume of the state office uses	at 5:30 p.m. I ran 10 jts "C" Lite 65: 'd 100 sx to and screw in H casing to 60 drilling open	13-3/8" 48# 1 35:1 w/ 2% C pit. Plug do nead. NU BOP. 00 psi, ok. cations.	aCl2 follow own at 5:45 PU BHA and	ed by 2 p.m. (TIH. V	225 sx C1 "C" CST. WOC. NOC total of

*See instruction on Reverse Side