## Submit 3 Copies to Appropriate District Office

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

## State of New Mexico rgy, Minerals and Natural Resources Department RECEIVED.

## OIL CONSERVATION DIVISION

P.O. Box 2088

WELL API NO. 30-015-27510	· '{
5. Indicate Type of Lease STATEXX	FEE

Form C-103

Revised 1-1-89

DISTRICT II	Canta Fe New Me	xico 875 <b>667208</b> 8.7941		
P.O. Drawer DD, Artesia, NM 88210	Salita 1 c, 110 W 1710		5. Indicate Type of Lease  STATE X FEE	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		O. C. D. ARTESIA, OFFICE	6. State Oil & Gas Lease No. K-6600	
( DO NOT USE THIS FORM FOR PR DIFFERENT RESE	ICES AND REPORTS ON OPOSALS TO DRILL OR TO DE RVOIR. USE "APPLICATION FO:-101) FOR SUCH PROPOSALS.	EPEN OR PLUG BACK TO A PR PERMIT	7. Lease Name or Unit Agreement Name	
1. Type of Well: OL GAS WELL XX WELL	OTHER		Nash Unit	
2. Name of Operator	2201		8. Well No. #14	
Strata Production Comp 3. Address of Operator P.O. Box 1030, Roswell		-	9. Pool name or Wildcat Nash Draw Brushy Canyon	
4. Well Location		Line and 500	Feet From The East Line	
			Fddy _ :	
Section 13	Township 23 South 10. Elevation (Show w	Range 29 East hether DF, RKB, RT, GR, etc.)	NMPM County	
	3004' (		Janest or Other Data	
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	XX ALTERING CASING	
TEMPORARILY ABANDON	ORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT			
PULL OR ALTER CASING	L OR ALTER CASING CASING TEST AND CEMENT JOB		EMENT JOB	
OTHER:		OTHER:		
12. Describe Proposed or Completed Operawork) SEE RULE 1103.	ations (Clearly state all pertinent det	ails, and give pertinent dates, incli	uding estimated date of starting any proposed	
09/14/94: RU pulling unit. Cut paraffin to 1000'. PU and LD 150 joints tubing. Steam and clean tubing. NU BOP. Release packer. TOH with packer. Prep to put on pump. SISD.				
09/15/94: TIH with mud joint, 4' perf sub, SN and TA. Set TA at 6788'. Set SN at 7068'. Pull 18 points on TA. ND BOP. Flange up wellhead. PU and TIH with pump. Prep to TIH with production string. SISD.				
09/16/94: TIH with rods, Tie-in electrici	subs, and liner. Space ty. Check pump action.	well out. Set in 456 I RD.	ovekin Airbalance pumping unit.	
09/17/94: Pumping.				
I hereby certify that the information above is tru	e and complete to the best of my knowled	dge and belief.	10/2/04	
SIGNATURE Carol J.	Parcia	Production Rec	ords Manager DATE 10/3/94 505-622-1127	
TYPEOR PRINT NAME Carol J. Gar	cia		TELEPHONE NO.	
(This space for State Use)				
		TITLE	DATE	

\_ TITLE -

APPROVED BY -