Form 3160-5 (June 1990)

N.M. Oll Conr Sivision

DEPARTMENT OF THE INTERIOR 11 8. 1st Street
BUREAU OF LAND MANAGEMENATION NM 88210-2834

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No.

			NM-43/44
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals			6. If Indian, Allottee or Tribe Name
	SUBMI	T IN TRIPLICATE	7. If Unit or CA, Agreement Designation
1. Type of Well Oil Gas Well Well Other			8. Well Name and No.
2. Name of Operator			Sand Dunes 34 Federal #8
	ducing Company		9. API Well No. 2 30-015-27548
3. Address and Telephone No. P. O. Box 10340, Midland, TX 79702-7340 (915)685-8100			10. Field and Pool, or Exploratory Area
	Well (Footage, Sec., T., R., M., or Survey D		Ingle Wells Delaware
330' FSL	& 1980' FEL, Section 34, T23S, R3	31E	11. County or Parish, State
			Eddy County, NM
2.	CHECK APPROPRIATE BOX((s) TO INDICATE NATURE OF NOTICE, REPORT,	OR OTHER DATA
	TYPE OF SUBMISSION	TYPE OF ACTION	
	Notice of Intent	Abandonment	Change of Plans
		Recompletion	New Construction
	Subsequent Report	☐ Plugging Back	Non-Routine Fracturing
		Casing Repair	
	First Absorber Madies		
	Final Abandonment Notice	Altering Casing	Conversion to Injection
	Proposed or Completed Operations (Clearly	Altering Casing Other Add Delaware Perfs state all pertinet details, and give pertinent dates, including estimated date asured and true vertical depths for all markders and zones pertinent to this	Dispose Water (Note: Report results of muttiple completion on Well Completion or Recompletion Report and Log form.) e of starting any proposed work. If well is
directional 02/06/00 02/08/00 02/09/00 02/10/00 02/11/00 02/12/00	Proposed or Completed Operations (Clearly lly drilled, give subsurface locations and me Perf Delaware 6464'-80' (2 JSPF) Acdz 6464'-80' w/ 1000 gals 7-1/2 Swab. Frac 6464'-80' w/ 19,900# 20/40 s Swab. RIH w/ rods & pump.	Other Add Delaware Perfs state all pertinet details, and give pertinent dates, including estimated date assured and true vertical depths for all markders and zones pertinent to this Set RBP @ 6970' & test to 3000# ok. 2% HCL.	Dispose Water (Note: Report results of muttiple completion on Well Completion or Recompletion Report and Log form.) e of starting any proposed work. If well is
directional 02/06/00 02/08/00 02/09/00 02/10/00 02/11/00 02/12/00 02/13/00	Proposed or Completed Operations (Clearly III) drilled, give subsurface locations and me Perf Delaware 6464'-80' (2 JSPF) Acdz 6464'-80' w/ 1000 gals 7-1/2 Swab. Frac 6464'-80' w/ 19,900# 20/40 s Swab. RIH w/ rods & pump. Return well to production.	Other Add Delaware Perfs state all pertinet details, and give pertinent dates, including estimated date assured and true vertical depths for all markders and zones pertinent to this Set RBP @ 6970' & test to 3000# ok. 2% HCL.	Dispose Water (Note: Report results of muttiple completion on Well Completion or Recompletion Report and Log form.) e of starting any proposed work. If well is
directional 02/06/00 02/08/00 02/09/00 02/10/00 02/11/00 02/12/00 02/13/00	Proposed or Completed Operations (Clearly lly drilled, give subsurface locations and me Perf Delaware 6464'-80' (2 JSPF) Acdz 6464'-80' w/ 1000 gals 7-1/2 Swab. Frac 6464'-80' w/ 19,900# 20/40 s Swab. RIH w/ rods & pump.	other Add Delaware Perfs state all pertinet details, and give pertinent dates, including estimated data asured and true vertical depths for all markders and zones pertinent to this.). Set RBP @ 6970' & test to 3000# ok. 2% HCL. sand.	Dispose Water (Note: Report results of muttiple completion on Well Completion or Recompletion Report and Log form.) e of starting any proposed work. If well is a work.)*
directional 02/06/00 02/08/00 02/09/00 02/10/00 02/11/00 02/12/00 02/13/00	Proposed or Completed Operations (Clearly III) drilled, give subsurface locations and me Perf Delaware 6464'-80' (2 JSPF) Acdz 6464'-80' w/ 1000 gals 7-1/2 Swab. Frac 6464'-80' w/ 19,900# 20/40 s Swab. RIH w/ rods & pump. Return well to production.	Other Add Delaware Perfs state all pertinet details, and give pertinent dates, including estimated date assured and true vertical depths for all markders and zones pertinent to this Set RBP @ 6970' & test to 3000# ok. 2% HCL.	Dispose Water (Note: Report results of muttiple completion on Well Completion or Recompletion Report and Log form.) e of starting any proposed work. If well is
directional 02/06/00 02/08/00 02/09/00 02/10/00 02/11/00 02/12/00 02/13/00	Proposed or Completed Operations (Clearly lly drilled, give subsurface locations and me Perf Delaware 6464'-80' (2 JSPF) Acdz 6464'-80' w/ 1000 gals 7-1/2 Swab. Frac 6464'-80' w/ 19,900# 20/40 s Swab. RIH w/ rods & pump. Return well to production.	other Add Delaware Perfs state all pertinet details, and give pertinent dates, including estimated data asured and true vertical depths for all markders and zones pertinent to this.). Set RBP @ 6970' & test to 3000# ok. 2% HCL. sand.	Dispose Water (Note: Report results of muttiple completion on Well Completion or Recompletion Report and Log form.) e of starting any proposed work. If well is a work.)*

BTEN

WYS 10 500