		M OIL CO L. Aver DE	DNS COMMISSION
65	ECEIVED	Artesia,	NM 88210
		TED STATES	FORM APPROVED
June 1990)	DEPARTMEN	T OF THE INTERIOR	Budget Bureau No. 1004-0135 Expires: March 31, 1993
FEB 16 11 OL MIBUREAU OF I		LAND MANAGEMENT	5. Lease Designation and Serial No.
SUNDRY NOTICES		AND REPORTS ON WELLS	6. If Indian, Allottee or Tribe Name
Do not usari	his form for proposals to dr	III or to deepen or reentry to a different reservoi R PERMIT—" for such proposals	ir.
	SUBMIT	IN TRIPLICATE	1977 If Unit or CA. Agreement Designation
Type of Well Oil Well	Gas Con		8. Well Name and No.
2. Name of Operator			North Pure Gold 8 Fed #
Santa Fe Energy Operating Partners, L.P.			9. API Well No.
3 Address and Telephone No.			30-015-27597
550 W. Texas, Suite 1330, Midland, Texas 79701			10. Field and Pool, or Exploratory Area
+ Location of Well (Footage, Sec., T., R., M., or Survey Description)		escription)	Los Medanos (Delaware
(T) 1000			11. County or Parish, State
(1), 1980	' FSL and 860' FEL,	Sec. 8, T-23S, R-31E	
			Eddy Co., NM
CHE	ECK APPROPRIATE BOX(	s) TO INDICATE NATURE OF NOTICE, REP	PORT, OR OTHER DATA
TYP		TYPE OF ACTIO	0N
م 🗌	Notice of Intent		Change of Plans
		Recompletion	New Construction
LX s	Subsequent Report	Plugging Back	Non-Routine Fracturing
		Casing Repair	Water Charlott
			Water Shut-Off
П я	Final Abandonment Notice	Altering Casing	Conversion to Injection
۲ 🗌	Final Abandonment Notice	Altering Casing Other Ran casing and	Conversion to Injection Dispose Water
		Altering Casing Other Ran casing and released rig	Conversion to Injection Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
13. Describe Propose	d or Completed Operations (Clearly state a	Altering Casing Other Ran casing and	Conversion to Injection Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
13. Describe Propose	d or Completed Operations (Clearly state a ace locations and measured and true vertic Depth 8080'. Ran 19 at 8080'. Cemented tool. Circ'd 50 sx "C" Neat. Plug down	Altering Casing Other Ran casing and released rig I pertinent details, and give pertinent dates, including estimated date of sta	Conversion to Injection Conversion to Injection Completion or Recompletion Report and Log form. arting any proposed work. If well is directionally drilled consisting. Set casing a.m. CST. Open DV ce followed by 400 sx and NUL tubing boad
13. Describe Propose give subsurfa	d or Completed Operations (Clearly state a ace locations and measured and true vertic Depth 8080'. Ran 19 at 8080'. Cemented tool. Circ'd 50 sx "C" Neat. Plug down Test seals to 800 ps	Altering Casing Other Ran casing and released rig I pertinent details, and give pertinent dates, including estimated date of sta ad depths for all markers and zones pertinent to this work.)* O jts 5-1/2" 17# K-55 and 15.5# J-5 w/ 500 sx C1 "H". Plug down at 9:0 to pit. Cemented w/ 800 sx "C" Litt at 1:45 p.m. Set slips. Cut off	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) arting any proposed work. If well is directionally drilled 55 casing. Set casing 00 a.m. CST. Open DV ce followed by 400 sx and NUL tubing boad
13. Describe Propose give subsurfa	d or Completed Operations (Clearly state a ace locations and measured and true vertic Depth 8080'. Ran 19 at 8080'. Cemented tool. Circ'd 50 sx "C" Neat. Plug down Test seals to 800 ps	Altering Casing Other Ran casing and released rig I pertinent details, and give pertinent dates, including estimated date of sta ad depths for all markers and zones pertinent to this work.)* O jts 5-1/2" 17# K-55 and 15.5# J-5 w/ 500 sx C1 "H". Plug down at 9:0 to pit. Cemented w/ 800 sx "C" Litt at 1:45 p.m. Set slips. Cut off	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) arting any proposed work. If well is directionally drilled 55 casing. Set casing 00 a.m. CST. Open DV ce followed by 400 sx and NUL tubing boad
<ul> <li>13. Describe Propose give subsurfa</li> <li>2/11/94:</li> <li>14. I hereby certify</li> <li>Signed</li> </ul>	d or Completed Operations (Clearly state a ace locations and measured and true vertic Depth 8080'. Ran 19 at 8080'. Cemented tool. Circ'd 50 sx "C" Neat. Plug down Test seals to 800 ps WOCU.	Altering Casing Other Ran casing and released rig I pertinent details, and give pertinent dates, including estimated date of sta ad depths for all markers and zones pertinent to this work.)* O jts 5-1/2" 17# K-55 and 15.5# J-5 w/ 500 sx C1 "H". Plug down at 9:0 to pit. Cemented w/ 800 sx "C" Litt at 1:45 p.m. Set slips. Cut off	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) arting any proposed work. If well is directionally drilled 55 casing. Set casing 00 a.m. CST. Open DV ce followed by 400 sx and NUL tubing boad
<ul> <li>13. Describe Propose give subsurfs</li> <li>2/11/94:</li> <li>14. 1 hereby certify</li> <li>Signed</li> <li>(This space for 1</li> </ul>	d or Completed Operations (Clearly state a ace locations and measured and true vertic Depth 8080'. Ran 19 at 8080'. Cemented tool. Circ'd 50 sx "C" Neat. Plug down Test seals to 800 ps WOCU.	Altering Casing Other <u>Ran casing and</u> released rig I pertinent details, and give pertinent dates, including estimated date of sta cal depths for all markers and zones pertinent to this work.)* PO jts 5-1/2" 17# K-55 and 15.5# J-5 w/ 500 sx Cl "H". Plug down at 9:0 to pit. Cemented w/ 800 sx "C" Lit at 1:45 p.m. Set slips. Cut off si = 110,000 psi on slips. Released <u>Tide</u> Sr. Production Clerk	Conversion to Injection Dispose Water Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) arting any proposed work. If well is directionally drilled 55 casing. Set casing 00 a.m. CST. Open DV 56 followed by 400 sx and NU tubing head. 1 rig at 5:00 p.m. CST.
<ul> <li>13. Describe Propose give subsurfa</li> <li>2/11/94:</li> <li>14. I hereby certify</li> <li>Signed</li> </ul>	d or Completed Operations (Clearly state a ace locations and measured and true vertic Depth 8080'. Ran 19 at 8080'. Cemented tool. Circ'd 50 sx "C" Neat. Plug down Test seals to 800 ps WOCU.	Altering Casing Other <u>Ran casing and</u> released rig I pertinent details, and give pertinent dates, including estimated date of sta cal depths for all markers and zones pertinent to this work.)* PO jts 5-1/2" 17# K-55 and 15.5# J-5 W/ 500 sx Cl "H". Plug down at 9:0 to pit. Cemented w/ 800 sx "C" Litt at 1:45 p.m. Set slips. Cut off si = 110,000 psi on slips. Released Sr. Production Clark	Conversion to Injection Dispose Water Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.1 artung any proposed work. If well is directionally drilled. 55 casing. Set casing 00 a.m. CST. Open DV te followed by 400 sx and NU tubing head. 1 rig at 5:00 p.m. CST.

.....

-