		Oll	INSERVATION E	VIV
Form 3160-5 June 1990)	UNITED ST DEPARTMENT OF 1 BUREAU OF LAND 1	ATES AF	S. 1st ST. TESIA, NM 88210-	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals				866 an, Allottee or Tribe Name
SUBMIT IN TRIPLICATE				t or CA, Agreement Designation
1. Type of Well X Oil Well Well O				
2. Name of Operator				ame and No.
MARALO, INC.			9. API We	II "8" FEDERAL #2
3. Address and Telephone No. P. O. BOX *32, MIDLAND, TX 79702				-28618
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				INDECT CHATEO
660' FNL & 1980' FWL, SECTION 8, T24S, R29E, UNIT C				UNDESIGNATED or Parish, State NM
CHECK APPRO	OPRIATE BOX(s) TO IN	DICATE NATURE OF NOTIC	E, REPORT, OR C	OTHER DATA
	TYPE OF SUBMISSION TYPE OF ACTION			
XX Notice of Intent				age of Plans
Subsequent Report		Plugging Back		Construction Routine Fracturing
Final Abandonmen	t Notice	Casing Repair Altering Casing XX Other COMPLETION ATTEMP	T Disp	r Shut-Off rersion to Injection ose Water
			(Note: Ren	ort results of multiple completion on We
Describe Proposed or Completed Op	crations (Clearly state all pertinent det	ails and size partiant data (add t	Completion	or Recompletion Report and Log form.
Describe Proposed or Completed Op give subsurface locations and r PROPOSED	verations (Clearly state all pertinent det measured and true vertical depths for	ails, and give pertinent dates, including estimated all markers and zones pertinent to this work.)*	Completion date of starting any proposed	or Recompletion Report and Log form. work. If well is directionally drill
PROPOSED OPERATION: Open M	liddle Brushy Canyon Pay	ails, and give pertinent dates, including estimated all markers and zones pertinent to this work.)*	Completion date of starting any proposed	or Recompletion Report and Log form. work. If well is directionally drill
PROPOSED OPERATION: Open M 1. RUPU. TOH w/pump,	liddle Brushy Canyon Pay rods, & tbg.	ails, and give pertinent dates, including estimated all markers and zones pertinent to this work.)*	Completion date of starting any proposed	or Recompletion Report and Log form work. If well is directionally dril
PROPOSED OPERATION: Open M 1. RUPU. TOH w/pump, 2. TIH w/ RBP on tbg to +	liddle Brushy Canyon Pay rods, & tbg. -/- 6500'. Set RBP.		Completion date of starting any proposed	or Recompletion Report and Log form work. If well is directionally dril
PROPOSED OPERATION: Open M 1. RUPU. TOH w/pump, 2. TIH w/ RBP on tbg to + 3. PU to 6241'. Spot 200	liddle Brushy Canyon Pay rods, & tbg. -/- 6500'. Set RBP. gals 7 1/2 % "mud clean-out" acid,	triple inhibited. TOH w/tbg.	Completion date of starting any proposed	or Recompletion Report and Log form work. If well is directionally dril
PROPOSED OPERATION: Open M 1. RUPU. TOH w/pump, 2. TIH w/ RBP on tbg to + 3. PU to 6241'. Spot 200 4. RU perforators using 4'	liddle Brushy Canyon Pay rods, & tbg. -/- 6500'. Set RBP. gals 7 1/2 % "mud clean-out" acid, " carrier guns and shoot 1 JSPF @	triple inhibited. TOH w/tbg. 5226 - 6241' (16 total holes).	Completion date of starting any proposed	or Recompletion Report and Log form work. If well is directionally dril
PROPOSED OPERATION: Open M 1. RUPU. TOH w/pump, 2. TIH w/ RBP on tbg to + 3. PU to 6241'. Spot 200 4. RU perforators using 4'	fiddle Brushy Canyon Pay rods, & tbg. -/- 6500'. Set RBP. gals 7 1/2 % "mud clean-out" acid, " carrier guns and shoot 1 JSPF @ ukr & tbg +/- 6150'. Reverse spot ac	triple inhibited. TOH w/tbg. 5226 - 6241' (16 total holes).	date of starting any proposed	or Recompletion Report and Log form work. If well is directionally dril
PROPOSED OPERATION:Open M1.RUPU. TOH w/pump,2.TIH w/ RBP on tbg to +3.PU to 6241'. Spot 2004.RU perforators using 4'5.TIH w/ 5 1/2" treating p6.Breakdown perfs by pu	fiddle Brushy Canyon Pay rods, & tbg. -/- 6500'. Set RBP. gals 7 1/2 % "mud clean-out" acid, " carrier guns and shoot 1 JSPF @ kr & tbg +/- 6150'. Reverse spot ac mping away spot acid.	triple inhibited. TOH w/tbg. 5226 - 6241' (16 total holes).	Completion date of starting any proposed	or Recompletion Report and Log form work. If well is directionally dril
PROPOSED OPERATION: Open M 1. RUPU. TOH w/pump, 2. TIH w/ RBP on tbg to + 3. PU to 6241'. Spot 200 4. RU perforators using 4' 5. TIH w/ 5 1/2" treating p 6. Breakdown perfs by pu 7. Continue treatment by	fiddle Brushy Canyon Pay rods, & tbg. -/- 6500'. Set RBP. gals 7 1/2 % "mud clean-out" acid, " carrier guns and shoot 1 JSPF @ kr & tbg +/- 6150'. Reverse spot ac mping away spot acid. - pumping 500 gals 7 1/2 % "mud /- 3 BPM.	triple inhibited. TOH w/tbg. 5226 - 6241' (16 total holes). id into tbg. Set pkr.	Completion date of starting any proposed ECEIVE JAN 2 3 139	or Recompletion Report and Log form work. If well is directionally dril
PROPOSED Open M 1. RUPU. TOH w/pump, 2. TIH w/ RBP on tbg to + 3. PU to 6241'. Spot 200 4. RU perforators using 4' 5. TIH w/ 5 1/2" treating p 6. Breakdown perfs by pu 7. Continue treatment by down tbg at a rate of +/ 8. Swab back load and ev 9. RU Dowell to frac perfs 6 22,500# 16/30 mesh sa w/an anticipated treatment	fiddle Brushy Canyon Pay rods, & tbg. -/- 6500'. Set RBP. gals 7 1/2 % "mud clean-out" acid, " carrier guns and shoot 1 JSPF @ kr & tbg +/- 6150'. Reverse spot ac mping away spot acid. - pumping 500 gals 7 1/2 % "mud /- 3 BPM. raluate. 6226 - 6241' w/8600 gals "Inverta-frac and + 8,000# 16/30 resin-coated sa ig pressure of 2500 psi, Shut in o	triple inhibited. TOH w/tbg. 5226 - 6241' (16 total holes). id into tbg. Set pkr.	Completion date of starting any proposed 3 ECEIVE JAN 2 3 139	or Recompletion Report and Log form. work. If well is directionally drill
PROPOSED Open M 1. RUPU. TOH w/pump, 2. TIH w/ RBP on tbg to + 3. PU to 6241'. Spot 200 4. RU perforators using 4' 5. TIH w/ 5 1/2" treating p 6. Breakdown perfs by pu 7. Continue treatment by down tbg at a rate of +/ 8. Swab back load and ev 9. RU Dowell to frac perfs 6 22,500# 16/30 mesh sa w/an anticipated treating 10. Swab back load and ev	fiddle Brushy Canyon Pay rods, & tbg. -/- 6500'. Set RBP. gals 7 1/2 % "mud clean-out" acid, " carrier guns and shoot 1 JSPF @ kr & tbg +/- 6150'. Reverse spot acid mping away spot acid. • pumping 500 gals 7 1/2 % "mud /- 3 BPM. raluate. 6226 - 6241' w/8600 gals "Inverta-frac and + 8,000# 16/30 resin-coated sa ig pressure of 2500 psi, Shut in o aluate.	triple inhibited. TOH w/tbg. 5226 - 6241' (16 total holes). id into tbg. Set pkr. clean-out" acid carrying +/- 30 ball sealers " followed by 10,000 gats X-link get carrying nd. Pump down tbg @ a rate of +/- 6 BPM remight to allow get to break.	Completion date of starting any proposed SECEIVE JAN 2 3 199 DIL CON.	or Recompletion Report and Log form. work. If well is directionally drill
 PROPOSED OPERATION: Open M RUPU. TOH w/pump, TIH w/ RBP on tbg to + PU to 6241'. Spot 200 RU perforators using 4' TIH w/ 5 1/2" treating p Breakdown perfs by pu Continue treatment by down tbg at a rate of +/ Swab back load and ev RU Dowell to frac perfs 6 22,500# 16/30 mesh ss w/an anticipated treatin Swab back load and ev TOH w/tbg & pkr (if well 	fiddle Brushy Canyon Pay rods, & tbg. -/- 6500'. Set RBP. gals 7 1/2 % "mud clean-out" acid, " carrier guns and shoot 1 JSPF @ kr & tbg +/- 6150'. Reverse spot ac mping away spot acid. " pumping 500 gals 7 1/2 % "mud /- 3 BPM. valuate. 6226 - 6241' w/8600 gals "Inverta-frac and + 8,000# 16/30 resin-coated sa ing pressure of 2500 psi, Shut in o aluate. I does not flow). TIH w/pumping eq	triple inhibited. TOH w/tbg. 5226 - 6241' (16 total holes). id into tbg. Set pkr.	Completion date of starting any proposed SECEIVE JAN 2 3 199 DIL CON.	or Recompletion Report and Log form. work. If well is directionally drill
 PROPOSED OPERATION: Open M RUPU. TOH w/pump, TIH w/ RBP on tbg to + PU to 6241'. Spot 200 RU perforators using 4' TIH w/ 5 1/2" treating p Breakdown perfs by pu Continue treatment by down tbg at a rate of +/ Swab back load and ev RU Dowell to frac perfs 6 22,500# 16/30 mesh ss w/an anticipated treatin Swab back load and ev TOH w/tbg & pkr (if well) 	fiddle Brushy Canyon Pay rods, & tbg. -/- 6500'. Set RBP. gals 7 1/2 % "mud clean-out" acid, " carrier guns and shoot 1 JSPF @ kr & tbg +/- 6150'. Reverse spot ac mping away spot acid. " pumping 500 gals 7 1/2 % "mud /- 3 BPM. valuate. 6226 - 6241' w/8600 gals "Inverta-frac and + 8,000# 16/30 resin-coated sa ing pressure of 2500 psi, Shut in o aluate. I does not flow). TIH w/pumping eq	triple inhibited. TOH w/tbg. 5226 - 6241' (16 total holes). id into tbg. Set pkr. Clean-out" acid carrying +/- 30 ball sealers " followed by 10,000 gals X-link gel carrying nd. Pump down tbg @ a rate of +/- 6 BPM remight to allow gel to break. Jipment and place well on production	Completion date of starting any proposed SECEIVE JAN 2 3 199 DIL CON.	or Recompletion Report and Log form. work. If well is directionally drill
 PROPOSED OPERATION: Open M RUPU. TOH w/pump, TIH w/ RBP on tbg to + PU to 6241'. Spot 200 RU perforators using 4' TIH w/ 5 1/2" treating p Breakdown perfs by pu Continue treatment by down tbg at a rate of +/ Swab back load and ev RU Dowell to frac perfs (22,500# 16/30 mesh ss w/an anticipated treatin Swab back load and ev TOH w/tbg & pkr (if well I hereby certify that the foregoing is Signed 	fiddle Brushy Canyon Pay rods, & tbg. -/- 6500'. Set RBP. gals 7 1/2 % "mud clean-out" acid, " carrier guns and shoot 1 JSPF @ kr & tbg +/- 6150'. Reverse spot ac mping away spot acid. " pumping 500 gals 7 1/2 % "mud /- 3 BPM. raluate. 6226 - 6241' w/8600 gals "Inverta-frac and + 8,000# 16/30 resin-coated sa ing pressure of 2500 psi, Shut in o aluate. I does not flow). TIH w/pumping eq true and correct	triple inhibited. TOH w/tbg. 5226 - 6241' (16 total holes). id into tbg. Set pkr. clean-out" acid carrying +/- 30 ball sealers " followed by 10,000 gats X-link get carrying nd. Pump down tbg @ a rate of +/- 6 BPM remight to allow get to break.	Completion date of starting any proposed JAN 2 3 139 DIL CON. DIST. 2	or Recompletion Report and Log form. work. If well is directionally drill
 PROPOSED OPERATION: Open M RUPU. TOH w/pump, TIH w/ RBP on tbg to + PU to 6241'. Spot 200 RU perforators using 4' TIH w/ 5 1/2" treating p Breakdown perfs by pu Continue treatment by down tbg at a rate of +/ Swab back load and ev RU Dowell to frac perfs (22,500# 16/30 mesh sa w/an anticipated treatin Swab back load and ev TOH w/tbg & pkr (if well TOH w/tbg & pkr (if well 	Aiddle Brushy Canyon Pay rods, & tbg. -/- 6500'. Set RBP. gals 7 1/2 % "mud clean-out" acid, " carrier guns and shoot 1 JSPF @ kr & tbg +/- 6150'. Reverse spot acid mping away spot acid. • pumping 500 gals 7 1/2 % "mud /- 3 BPM. valuate. 6226 - 6241' w/8600 gals "Inverta-frad and + 8,000# 16/30 resin-coated sa ing pressure of 2500 psi, Shut in o aluate. I does not flow). TIH w/pumping eq true and correct	triple inhibited. TOH w/tbg. 5226 - 6241' (16 total holes). id into tbg. Set pkr. Clean-out" acid carrying +/- 30 ball sealers " followed by 10,000 gats X-link get carrying d. Pump down tbg @ a rate of +/- 6 BPM remight to allow get to break. upment and place well on production	Completion date of starting any proposed JAN 2 3 139 DIL CON. DIST. 2	or Recompletion Report and Log form. work. If well is directionally drill
PROPOSED OPERATION: Open M 1. RUPU. TOH w/pump, 2. TIH w/ RBP on tbg to + 3. PU to 6241'. Spot 200 4. RU perforators using 4' 5. TIH w/ 5 1/2" treating p 6. Breakdown perfs by pu 7. Continue treatment by down tbg at a rate of +/ 8. Swab back load and ev 9. RU Dowell to frac perfs 6 22,500# 16/30 mesh sa w/an anticipated treatin 10. Swab back load and ev 11. TOH w/tbg & pkr (if well I hereby certify that the foregoing is Signed	Aiddle Brushy Canyon Pay rods, & tbg. -/- 6500'. Set RBP. gals 7 1/2 % "mud clean-out" acid, " carrier guns and shoot 1 JSPF @ kr & tbg +/- 6150'. Reverse spot acid mping away spot acid. • pumping 500 gals 7 1/2 % "mud /- 3 BPM. valuate. 6226 - 6241' w/8600 gals "Inverta-frad and + 8,000# 16/30 resin-coated sa ing pressure of 2500 psi, Shut in o aluate. I does not flow). TIH w/pumping eq true and correct	triple inhibited. TOH w/tbg. 5226 - 6241' (16 total holes). id into tbg. Set pkr. Clean-out" acid carrying +/- 30 ball sealers " followed by 10,000 gals X-link gel carrying nd. Pump down tbg @ a rate of +/- 6 BPM remight to allow gel to break. uipment and place well on production ttc	Completion date of starting any proposed JAN 2 3 139 DIL CON. DIST. 2	or Recompletion Report and Log form. work. If well is directionally drill
 PROPOSED OPERATION: Open M RUPU. TOH w/pump, TIH w/ RBP on tbg to + PU to 6241'. Spot 200 RU perforators using 4' TIH w/ 5 1/2" treating p Breakdown perfs by pu Continue treatment by down tbg at a rate of +/ Swab back load and ev RU Dowell to frac perfs 6 22,500# 16/30 mesh sa w/an anticipated treatin Swab back load and ev TOH w/tbg & pkr (if well I hereby certify that the foregoing is Signed Continue for the foregoing is Signed for Federal or State of fic Approved by ORNG, Sol 	Aiddle Brushy Canyon Pay rods, & tbg. -/- 6500'. Set RBP. gals 7 1/2 % "mud clean-out" acid, " carrier guns and shoot 1 JSPF @ what & tbg +/- 6150'. Reverse spot acid mping away spot acid. • pumping 500 gals 7 1/2 % "mud /- 3 BPM. raluate. 6226 - 6241' w/8600 gals "Inverta-frace and + 8,000# 16/30 resin-coated sa ig pressure of 2500 psi, Shut in o aluate. I does not flow). TIH w/pumping eq true and correct	triple inhibited. TOH w/tbg. 5226 - 6241' (16 total holes). id into tbg. Set pkr. Clean-out" acid carrying +/- 30 ball sealers " followed by 10,000 gals X-link gel carrying nd. Pump down tbg @ a rate of +/- 6 BPM remight to allow gel to break. uipment and place well on production ttc	Completion date of starting any proposed JAN 2 3 199 DIL COM. DIST. 2 Date Date -	ECEMBER 7, 1995