

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

OCT 06 '87

O. C. D.
ARTESIA OFFICE

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. LG-1171	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name Flower Draw Unit
2. Name of Operator Parker & Parsley Petroleum Co.	8. Farm or Lease Name Flower Draw Unit
3. Address of Operator P.O. Box 3178, Midland, TX 79702	9. Well No. 4
4. Location of Well UNIT LETTER <u>H</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>3</u> TOWNSHIP <u>26S</u> RANGE <u>28E</u> NMPM.	10. Field and Pool, or Wildcat Und. Delaware
15. Elevation (Show whether DF, RT, GR, etc.) 2940' GR	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Approximate starting date: 11-5-87

Proposed plugging procedure w/perfs @ 2552-2560':

1. Set 100' plug @ 2500' & tag. - mud hole w/mud - minimum 25 SX plugs
2. Set 100' plug @ 400'.
3. Set 10 sx plug @ surface w/marker.
4. Clean location.

Mud will be used between all plugs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Larry Brown

SIGNED Larry Brown TITLE Agent DATE 9-28-87

APPROVED BY Mike Williams TITLE OIL AND GAS INSPECTOR DATE OCT 07 1987

CONDITIONS OF APPROVAL, IF ANY:

Notify N.A.D.C. in sufficient time to witness

Flowering