

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on
reverse side)Form approved
Budget Bureau No. 42-R1424
5. LEASE DESIGNATION AND SERIAL NO.

NM-036379

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR TEXACO Inc.		8. FARM OR LEASE NAME Cotton Draw Unit	
3. ADDRESS OF OPERATOR P. O. Box 728, Hobbs, New Mexico 88240		9. WELL NO. 67	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FSL & 660' FWL of Section 35, T-24-S, R-31-E, Unit Letter 'L', Eddy County, New Mexico		10. FIELD AND POOL, OR WILDCAT Paduca Morrow Gas	
14. PERMIT NO. Regular		15. ELEVATIONS (Show whether DE, EE, or, etc.) 3506' (DF)	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 35, T-24-S, R-31-E
		12. COUNTY OR PARISH Eddy	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) Plug Back & Recomplete ☒PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface location, and measured and true vertical depths for all markers and zones pertinent to this work.) *

1. Rig up. Kill Well, Install BOP. Pull production equipment.
2. Run CIBP & set @ 14,550'. Dump 5 sx. Class 'H' Cement on plug. Abandon Morrow Zone.
3. Set packer @ 13,950'. Run production string & load tubing annulus w/treated water. Swab tubing dry.
4. Perforate 5½" csg. in Atoka Zone w/1-JSPF @ 14,025', 14,030', & 14,067'.
5. Acidize 5½" csg perforations 14,025', -14,067' w/2000 gal. 20% super retarded Acid. Flush w/1000 gal. 2% KCL water.
6. Swab.
7. Test & place on production.

RECEIVED

JUN 1 1976

D. C. S.
REGIONAL OFFICE

RECEIVED

MAY 26 1976

U. S. GEOLOGICAL SURVEY
ALBUQUERQUE, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Asst. Dist. Supt.

DATE 5-25-76

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: