



ORIGINAL WELL CONDITIONS

Tubing was intact at this point as evidenced by the fact that 1,400 psi was placed on it in an effort to kill the well and no pressure increase occurred on the 2 7/8"-5 1/2" annulus. This is evidence that the upper charged zone was not charged from the Morrow Formation in this well; however since the gas from this zone had properties similar to those of the Morrow, it possibly came from the Morrow in another well.

FIGURE #1. Well conditions on March 3, 1995, when workover commenced.