

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-21-81
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	LG-9681
7. Lease Name or Unit Agreement Name	CHELSEI
8. Well No.	1
9. Pool name or Wildcat	Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator H. E. LEE ✓
3. Address of Operator 1306 Meadow Lane Roswell, New Mexico 88201	4. Well Location Unit Letter <u>J</u> : <u>1980'</u> Feet From The <u>South</u> Line and <u>1980'</u> Feet From The <u>East</u> Line Section <u>2</u> Township <u>26 South</u> Range <u>25 East</u> NMPM <u>Eddy</u> County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3687' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>Continuous Operations</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-8-91 thru 11-17-91

Drill out cement from 655' down to 700' and fall free. Go in hole with bit to 1100'. Pull out of hole with bit, break out cable tools.

11-18-91

Move in and clean off location. Dig pit and set anchors.

11-19-91

Dig out cement out of cellar to expose casings. Nipple up 10" 3000# Hydraulic BOP. Rig down cable tool rig and move in Real Well Service pulling unit.

11-20-91

Make up 8 1/2" bit and drill collars and go in hole. Tag at 1462'. Drill to 1480'. Go in hole and tag at 2441'. Drill cement from to 2680' and fall free. Circ. Gas.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE H. E. Lee TITLE Owner DATE 11-20-91
TYPE OR PRINT NAME H. E. Gene Lee TELEPHONE NO. 622-7355

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS

APPROVED BY SUPERVISOR, DISTRICT I TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: