

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-21-81
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG-9681
7. Lease Name or Unit Agreement Name CHELSI
8. Well No. 1
9. Pool name or Wildcat Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator H. E. LEE /
3. Address of Operator 1306 Meadow Lane Roswell, New Mexico 88201
4. Well Location Unit Letter J : 1980' Feet From The South Line and 1980' Feet From The East Line Section 2 Township 26 South Range 25 East NMPM Eddy County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3687' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Continuous Operations <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-21-91

Drill cement and clean out hole to 4962'.

11-22-91

Drill out cement plugs and clean out to 6265'.

11-23-91

Tag cement at 7680' Drill cement down to 7915' and fall free. Circ. out gas at 7994'. Go in hole and tag at 9530'. Drill cement to 9645' and fall free. Run in hole with tubing to 9686' and circulate clean.

11-24-91

Go in hole to 10,010'. Drill cement down to 10,285'. Circulate hole clean.

11-25-91

Go in hole and tag cement at 10,585'. Drill cement down to 10,780' and fall free. Go in hole to 11,293'. Drill cement down to 11,410' and fall free. Clean out well down to 12,043'. Circulate and condition hole.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE H. E. LEE TITLE Owner DATE 11-25-91
TYPE OR PRINT NAME H. E. Gene LEE TELEPHONE NO. 622-7355

(This space for State Use)

OR CHIEF SIGNED BY
AND DATE
3-15-92

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

DEC 2 1991