

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/ ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL C-101 FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator <b>C. E. LaRue and B. N. Muncy, Jr.</b>	8. Form or Lease Name <b>Pecos Irrigation</b>
3. Address of Operator <b>P.O. Box 196, Artesia, New Mexico 88210</b>	9. Well No. <b>1 1</b>
4. Location of Well UNIT LETTER <b>J</b> <b>1980</b> FEET FROM THE <b>South</b> LINE AND <b>1980</b> FEET FROM THE <b>East</b> LINE, SECTION <b>20</b> TOWNSHIP <b>25S</b> RANGE <b>28E</b> N.M.P.M.	10. Field and Pool, or Wildcat <b>Wildcat Delaware</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3008' GL</b>	12. County <b>Eddy</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug well by pumping 25 sacks cement plug from 4400' to 4500', 25 sack cement plug from 3300' to 3400', \*75 sack cement plug from 2365-2465' and 15 sack cement plug at surface with heavy mud between all plugs. Set dry hole marker, fill pits and clean up location.

*\* cut & pull approximately 2500' of 7" casing*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <i>[Signature]</i>	TITLE <b>Operator</b>	DATE <b>September 13, 1977</b>
APPROVED BY <i>[Signature]</i>	TITLE <b>SUPERVISOR, DISTRICT II</b>	DATE <b>SEP 16 1977</b>
CONDITIONS OF APPROVAL, IF ANY:		