

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	0
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

N.M.O.C.C.
ALBUQUERQUE OFFICE

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-3536
7. Unit Agreement Name
8. Farm or Lease Name State GQ Com.
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat Morrow
11. Elevation (Show whether DF, RT, GR, etc.) 3089.2 RDB
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
(SEE APPLICATION FOR PERMIT ON FORM C-101 FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/>	GAS WELL <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>
Operator Amoco Production Company ✓		
Address P. O. Box 68, Hobbs, NM 88240		
Section 14-1	1980	South 1980
UNIT LETTER J	FEET FROM THE	LINE AND FEET FROM
THE East	LINE, SECTION 7	TOWNSHIP 25-S RANGE 28-E N.M.P.M.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
REPAIR OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

13. Describe in brief and in complete detail operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE #103.

Propose to P X A by spotting 50 SX Class H cement at 12,450', 45 SX Class H cement at 12,150', 45 SX Class H cement at 11,400'. Run cast iron bridge plug to 8890' and cap with 35' cement. Run free point and cut and pull 7-5/8" casing at approx. 4490'. Spot 40 SX Class H cement 4440'-4540' in and out of 7-5/8" casing stub. Spot 50 SX Class H cement 2375'-2475' across 10-3/4" casing shoe. Spot 10 SX Class H cement surface plug and erect P X A marker.

14. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Kay Cox TITLE Admin. Supervisor DATE 7-31-79

APPROVED BY W. A. Gussert TITLE SUPERVISOR, DISTRICT II DATE AUG 3 1979

CONDITIONS OF APPROVAL, IF ANY:

Notify N.M.O.C.C. in sufficient time to witness

0+4-NMOCD,A; 1-Hou; 1-Susp; 1-BD; 1-Pecos Irr; 1-Southland Royalty