C15F NM OIL CONS COMMISSION Drawer DD Form 3160-5 Artesia Budgel Bureau No. 1004-0135 UNITED STATES $\mathfrak{Z}_{\mathfrak{D}}$ department of the interior (June 1990) Expires: March 31, 1993 BUREAU OF LAND MANAGEMENT 5. Lease Designation and Serial No. NM 28172 SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE 1. Type of Well Oil Well X Gas Well 8. Well Name and No. 2. Name of Operator Delta Federal #1 9. API Well No. Unit Petroleum Company 3. Address and Telephone No. 30-015-23147 P. O. Box 702500, Tulsa, OK 74170-2500 10. Field and Pool, or Exploratory Area (918) 493-7700 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Wildcat Wolfcamp 1,980' FNL & 1,980' FEL 11. County or Parish, State SW/4 NE/4 Section 7-T25S-R26E Eddy County, New Mexico CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 12. TYPE OF SUBMISSION TYPE OF ACTION X Notice of Intent Abandonment Change of Plans Recompletion **New Construction** Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Water Shut-Off Final Abandonment Notice Altering Casing Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 1) MIRU pumping unit. Install 3000# W.P. BOP's. 2) POH w/ production tbg & Baker lok-set pkr set @ 9,450'. (If pkr won't release, POH w/ tbg only & cap pkr w/ 50' cmt.) Set CIBP @ 9,500' & cap w/ 35' cmt. 3) Spot 150' cmt plug from 9,180' to 9,030'. 4) Cut & pull 7-5/8" csg from 5,200' +. 5) Spot 100' stub plug 50' in and 50' out of cut-off 7-5/8" (estimated interval from 5,250' to 5,150'). Tag & verify top of plug. 6) Spot 100' stub plug 50' in and 50' out of 10-3/4" surface csg shoe @ 1,700'. Tag & verify top of plug.

7) Spot 50' surface plug. 8) Rig down & clean up loc.

4. I hereby certify the the foregoing is true and correct Signed	Title _	District Engineer	Date <u>May 22, 1995</u>
(This space for Federal or State office use) Approved by Conditions of approval, if any:	Title _	PETROLEUM ENGINEER	Date 6/29/95

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.