

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	<input checked="" type="checkbox"/>
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

JUN 08 1983

O. C. D.

ARTESIA OFFICE

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-6426
7. Unit Agreement Name
8. Farm or Lease Name NORTHERN NATURAL GAS
9. Well No. 1
10. Field and Pool, or Wildcat (WILDCAT) BONE SPRING
12. County

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator DINERO OPERATING COMPANY
3. Address of Operator POST OFFICE DRAWER 10505, MIDLAND, TEXAS 79702
4. Location of Well UNIT LETTER B 660 FEET FROM THE NORTH LINE AND 1980 FEET FROM THE EAST LINE, SECTION 32 TOWNSHIP 25-S RANGE 29-E N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Spot 5 sacks Class C. with 2% CaCl at top of bridge plug at 5,500 ft.
- *25
Set plug (15 sacks Class C. with 2% CaCl) from 4690-4840' to cover perfs from 4754-4780'.
- *25
Set plug (15 sacks Class C. with 0% CaCl) from 4455-4605' to cover perfs. from 4522-40'.
- Cut casing at 2,200 ft. and pull 4 1/2" out of hole.
- *25
Set plug (17 sacks Class C. with 2% CaCl) from 2150-2250'. (50' in 4 1/2"-50' in 8 5/8" casing). WOC 4 hours. Tag top of cement.
- Set plug (27 sacks Class C. with 2% CaCl) from 1000'-1100'. WOC 4 hours. Tag top of plug.
- Set marker in 10 sacks Class C. at surface.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

Lanada D. Luna

TITLE

PRODUCTION SUPERVISOR

DATE

June 5, 1983

APPROVED BY

Mr. Walker

TITLE

OIL AND GAS INSPECTOR

DATE

JUN 15 1983

CONDITIONS OF APPROVAL, IF ANY

As noted Above.