NH OIL CHIE, COMMISSION Drawer DD Artesia, W. FED STATES (November 1983) RECEIVED BY DEPARTMENT OF THE INTERIO BUREAU OF LAND MANAGEMENT		Form approved. Budget Bureau N Expires August ( 5. LEASE DESIGNATION A NM 0557561 6. IF INDIAN, ALLOTTEE	ND BREIAL NO.
16 SUDDRY NOTICES AND REPORTS ON Use "APPLICATION FOR PERMIT_" for such prop . O. C. D. 	t to a different reservoir.	7. UNIT AGREEMENT NAM	(8
WEAKTEDIA, WEEKCH		8. FARM OR LEADE NAME	
Marline Petroleum Corp.		Hay B Federa	
8. ADDREAS OF OPERATOR		9. WELL NO.	L
4900 Capitol Bank Plaza, Houston, TX 77002		1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. <sup>9</sup> See also space 17 below.)		10. FIELD AND POOL, OR WILDCAT	
At surface		Welch-Bone Spring	
		11. BBC., T., R., M., OB BLK. AND BURVEY OR ARMA	
1980' FSL & 1980' FWL, K, Sec. 9, T26S, R27E		0-260-275	
1960* FSL & 1960* FWL, K, SEC. 9, 1205, K27E           14. PERMIT NO.         15. BLEVATIONS (Show whether DP, BT, GR, etc.)		9-265-27E 12. COUNTY OR PARISE	18. STATE
3274.3 GR		Eddy	N.M.
Check Appropriate box to indicate train			
NOTICE OF INTENTION TO :	ENT REPORT OF:	<b></b>	
TEST WATER SHUT-OFF PULL OR ALTER CASING	WATER SHUT-OFF	ESPAIRING WI	
FRACTURE TREAT MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CAR	<u> </u> −−−
SHOOT OR ACIDIZE ABANDON <sup>®</sup> X	SHOOTING OR ACIDIZING	ABANDONMEN	"
(Nors: Report results of multiple completion on Well			
(Other) Change (1) Operator & (2) Manger 1 Completion or Recompletion Befort and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any			
<ul> <li>purchased by and assigned to Marline P</li> <li>(2). Previous lease name, Hay Federal "B",</li> <li>(3). Intent to abandon procedure is amended Quanah Petroleum, Inc.</li> <li>For present wellbore condition see attached</li> <li>Proposed plugging procedure to start on appr</li> <li>(a). Set C.I.B.P. @ 5350' and cap with 35'</li> <li>(b). Run tbg to 5315' and displace hole wit</li> <li>(c). Spot 100' plug (25 sx) @ 4850', 100' p</li> <li>@ 2700', &amp; a 100' plug (25 sx) @ 2450'</li> <li>(d). Cut 5<sup>1</sup>/<sub>2</sub>" casing at free point, @ approx</li> <li>(e). Spot 100' plug (50 sx) @ 370'.</li> <li>(g). Remove wellhead, place a 15 sk surface Restore location.</li> </ul>	corrected as above. from procedure appr sketch. oval: of cement to 5315'. h mud. lug (25 sx) @ 4150', imately 1800', and p g. Spot 100' plug	, a 100' plug (1 pull casing. g@/200'(H	25 sx)
18. I hereby cortify that the setegoing is the and correct SIGNED AMAGNAL TITLE DA (This space for Federal or State office use) APPROVED BY AMAGNAL CONDITIONS OF APPROVAL, IF ANY,	auctant		-85 585
*See Instructions on Reverse Side			