

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

MAR 22 '90

WELL API NO. 3001524305
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Clark
8. Well No. 1
9. Pool name or Wildcat Red Bluff Delaware

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator Wayne Moore	
3. Address of Operator 403 N. Marienfeld, Midland, Texas 79701	
4. Well Location Unit Letter <u>HC</u> : <u>1650</u> Feet From The <u>N</u> Line and <u>2310</u> Feet From The <u>E</u> Line Section <u>11</u> Township <u>26</u> Range <u>28</u> NMPM <u>Eddy</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3222.0 GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP @ 2650

2. Set cement plug @ 2650' - 2475' + 100' ~~to cover Bottom Salt~~ *Now plug @ 1220-1270 Top Salt*

3. Cut and pull 1400' +- 8-5/8 & 9-1/2" pipe

4. Set cement plug @ 1450' - 1350'

5. Set 35 sx cement plug @ 475'

6. Surface plug & marker

Mud in hole and required plugs will be tagged. To be plugged in April 1990.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tom E. Moore TITLE Operations Manager DATE 3-20-90

TYPE OR PRINT NAME Tom E. Moore TELEPHONE NO. 915-682-8695

(This space for State Use)

APPROVED BY Daniel Moore TITLE DATE 4/2/90

CONDITIONS OF APPROVAL, IF ANY: *