form 3160-5 UNITED	N. Dľ	Cons. V-Dist. 2 J S A and Avenue
June 1990) DEPARTMENT O BUREAU OF LAN	$r$ THE INTERIOR $\Delta r to c i a N$	M 8826497 Bureau No. 1004-0135 Expires: March 31, 1993
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals		5. Lease Designation and Serial No. NM-13413A
		6. If Indian, Allottee or Tribe Name ir.
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of Well Gas Gas	14151672	
2. Name of Operator	A3 14 10 10 17 13 10	8. Well Name and No.
Pogo Producing Company		SAM Federal #2
3. Address and Telephone No.	on lit on other	9. API Well No. 30-015-24364
P. O. Box 10340, Midland, TX 79702-7340 (915)64 Location of Well (Footage, Sec., T., R., M., or Survey Description		10. Field and Pool, or Exploratory Area
1980' FNL & 1980' FEL, Section 26, T25S, R28E	ARTECIA BI	Rock Spur Morrow
1000 File & 1000 File, Section 20, 1255, R28E	2 23/4 3	11. County or Parish, State
		Eddy County, NM
	NDICATE NATURE OF NOTICE, REPORT,	OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
X Notice of Intent	Abandonment	Change of Plans
Subsequent Report		New Construction
	Plugging Back     Casing Repair	Non-Routine Fracturing
Final Abandonment Notice	Altering Casing	Water Shut-Off Conversion to Injection
	X other Return well to production	Dispose Water
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
<ol> <li>Describe Proposed or Completed Operations (Clearly state all p directionally drilled, give subsurface locations and measured and Pogo Producing Company plans to return the above</li> <li>Release &amp; POOH pkr @ 7985'.</li> <li>POH w/ existing seal assembly.</li> <li>RIH w/ new seal assembly. ND BOP. Swab test</li> <li>If well does not respond to swab testing, Reperf M</li> <li>If unsuccessful, set CIBP @ 13,120' &amp; cap w/ 35'</li> <li>Perf Morrow 12,722'-730' w/ 4 spf &amp; 0° phase. Sv</li> <li>If swab results are poor, set CIBP @ 12,700'.</li> <li>Perf Morrow 12,632'-638' w/ 4 spf &amp; 0° phase. Sv</li> <li>Swab well in &amp; put well on production.</li> </ol>	Captioned well to production based on the following Morrow perfs @ 13,174'-13,200'. May stimulate w/ forrow perfs 13,174'-200' w/ 4 spf & 0° phase. Swa cmt. vab test. vab test. Frac if necessary.	g procedure.
I hereby certify that the foregoing is true and correct	Title Sr. Operation Tech	Date12/11/01
Accepted for record	gly and willfully to make to any department or agency of the Unit	ed States any false, fictitious or fraudulent
	*See Instruction on Reverse Side	



5001 DEC 13 WH 8: 38

BECEMED