ormerly 9-331) UNITO STATES SUBMIT IN TRIP Department of LAND MANAGEMENT DD BUREAU OF LAND MANAGEMENT DD	S. LEASE DESIGNATION AND SERIAL NO
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reserve Use "APPLICATION FOR PERMIT-" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAM
CIL CAS GAS OTHER	7. UNIT AGREEMENT NAME
NAME OF OPERATOR	8. FARM OR LEASE NAME
J.C. Williamson V	EP-USA 9. WBLL NO.
P.O. Box 16 Midland, Texas 79702	7-Y
LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface	10. FIELD AND POOL, OR WILDCAT
1960' FSL & 1980' FEL	Brushy Draw Delaware 11. SEC., T., E., M., OR BLE, AND
JUN 2 2 1993	SURVEY OR AREA
A. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, CR, efer)	Sec.26-26S-29E
2899.5' GR	12. COUNTY OF PARISH   13. STATE Eddy NM
Check Appropriate Box To Indicate Nature of Notice, Rep	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF :
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMI	
SHOOT OR ACIDIZE X ABANDON* SHOOTING OR ACIDI REPAIR WELL CHANGE PLANS (Other)	IZING ABANDONMENT*
(Other)	
DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertine proposed work. If well is directionally drilled, give subsurface locations and measured and tr nent to this work.)*	ort results of multiple completion on Well or Recompletion Report and Log form.) tent dates, including estimated date of starting an rue vertical depths for all markers and sones peri
<ul> <li>(1) Pull rods, Down-hole pump and tubing out of hole.</li> <li>(2) Set RBP @ 3100', test RBP to 1000#, if holding the</li> </ul>	en continue:
<ul> <li>(1) Pull rods, Down-hole pump and tubing out of hole.</li> <li>(2) Set RBP @ 3100', test RBP to 1000#, if holding the</li> <li>(3) Perforate Ramsey Sand from 2992-3000', 6 holes 0.4</li> </ul>	en continue:
<ul> <li>(1) Pull rods, Down-hole pump and tubing out of hole.</li> <li>(2) Set RBP @ 3100', test RBP to 1000#, if holding the</li> <li>(3) Perforate Ramsey Sand from 2992-3000', 6 holes 0.4</li> <li>(4) Acidize same with 1000 gallons 7-1/2% NEFE.</li> </ul>	en continue:
<ul> <li>(1) Pull rods, Down-hole pump and tubing out of hole.</li> <li>(2) Set RBP @ 3100', test RBP to 1000#, if holding the</li> <li>(3) Perforate Ramsey Sand from 2992-3000', 6 holes 0.4</li> <li>(4) Acidize same with 1000 gallons 7-1/2% NEFE.</li> <li>(5) Swab test well, if favorable then:</li> </ul>	en continue: +2" in diameter.
<ul> <li>DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertine proposed work. If well is directionally drilled, give subsurface locations and measured and trent to this work.)*</li> <li>(1) Pull rods, Down-hole pump and tubing out of hole.</li> <li>(2) Set RBP @ 3100', test RBP to 1000#, if holding the</li> <li>(3) Perforate Ramsey Sand from 2992-3000', 6 holes 0.4</li> <li>(4) Acidize same with 1000 gallons 7-1/2% NEFE.</li> <li>(5) Swab test well, if favorable then:</li> </ul>	en continue: +2" in diameter.
<ul> <li>(1) Pull rods, Down-hole pump and tubing out of hole.</li> <li>(2) Set RBP @ 3100', test RBP to 1000#, if holding the</li> <li>(3) Perforate Ramsey Sand from 2992-3000', 6 holes 0.4</li> <li>(4) Acidize same with 1000 gallons 7-1/2% NEFE.</li> <li>(5) Swab test well, if favorable then:</li> <li>(6) Fracture treat well with 4000 gallons gelled Kcl w</li> </ul>	en continue: 2" in diameter. vater and 8000# sand.
<ul> <li>DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertine proposed work. If well is directionally drilled, give subsurface locations and measured and trenent to this work.)*</li> <li>(1) Pull rods, Down-hole pump and tubing out of hole.</li> <li>(2) Set RBP @ 3100', test RBP to 1000#, if holding the</li> <li>(3) Perforate Ramsey Sand from 2992-3000', 6 holes 0.4</li> <li>(4) Acidize same with 1000 gallons 7-1/2% NEFE.</li> <li>(5) Swab test well, if favorable then:</li> <li>(6) Fracture treat well with 4000 gallons gelled Kcl w</li> <li>(7) Swab back and test well.</li> </ul>	en continue: +2" in diameter.
<ul> <li>DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertine proposed work. If well is directionally drilled, give subsurface locations and measured and trent to this work.)*</li> <li>(1) Pull rods, Down-hole pump and tubing out of hole.</li> <li>(2) Set RBP @ 3100', test RBP to 1000#, if holding the</li> <li>(3) Perforate Ramsey Sand from 2992-3000', 6 holes 0.4</li> <li>(4) Acidize same with 1000 gallons 7-1/2% NEFE.</li> <li>(5) Swab test well, if favorable then:</li> <li>(6) Fracture treat well with 4000 gallons gelled Kcl w</li> <li>(7) Swab back and test well.</li> </ul>	en continue: 2" in diameter. vater and 8000# sand.
<ul> <li>DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertine proposed work. If well is directionally drilled, give subsurface locations and measured and trenent to this work.)*</li> <li>(1) Pull rods, Down-hole pump and tubing out of hole.</li> <li>(2) Set RBP @ 3100', test RBP to 1000#, if holding the</li> <li>(3) Perforate Ramsey Sand from 2992-3000', 6 holes 0.4</li> <li>(4) Acidize same with 1000 gallons 7-1/2% NEFE.</li> <li>(5) Swab test well, if favorable then:</li> <li>(6) Fracture treat well with 4000 gallons gelled Kcl w</li> <li>(7) Swab back and test well.</li> </ul>	en continue: 2" in diameter. vater and 8000# sand.
<ul> <li>DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertine proposed work. If well is directionally drilled, give subsurface locations and measured and trenent to this work.)*</li> <li>(1) Pull rods, Down-hole pump and tubing out of hole.</li> <li>(2) Set RBP @ 3100', test RBP to 1000#, if holding the</li> <li>(3) Perforate Ramsey Sand from 2992-3000', 6 holes 0.4</li> <li>(4) Acidize same with 1000 gallons 7-1/2% NEFE.</li> <li>(5) Swab test well, if favorable then:</li> <li>(6) Fracture treat well with 4000 gallons gelled Kcl w</li> <li>(7) Swab back and test well.</li> </ul>	en continue: 2" in diameter. vater and 8000# sand.
<ul> <li>DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertine proposed work. If well is directionally drilled, give subsurface locations and measured and trenent to this work.)*</li> <li>(1) Pull rods, Down-hole pump and tubing out of hole.</li> <li>(2) Set RBP @ 3100', test RBP to 1000#, if holding the</li> <li>(3) Perforate Ramsey Sand from 2992-3000', 6 holes 0.4</li> <li>(4) Acidize same with 1000 gallons 7-1/2% NEFE.</li> <li>(5) Swab test well, if favorable then:</li> <li>(6) Fracture treat well with 4000 gallons gelled Kcl w</li> <li>(7) Swab back and test well.</li> </ul>	en continue: +2" in diameter. vater and 8000# sand.
<ul> <li>DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertine proposed work. If well is directionally drilled, give subsurface locations and measured and trenent to this work.)*</li> <li>(1) Pull rods, Down-hole pump and tubing out of hole.</li> <li>(2) Set RBP @ 3100', test RBP to 1000#, if holding the</li> <li>(3) Perforate Ramsey Sand from 2992-3000', 6 holes 0.4</li> <li>(4) Acidize same with 1000 gallons 7-1/2% NEFE.</li> <li>(5) Swab test well, if favorable then:</li> <li>(6) Fracture treat well with 4000 gallons gelled Kcl w</li> <li>(7) Swab back and test well.</li> </ul>	en continue: 2" in diameter. vater and 8000# sand.
<ul> <li>DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent ment between the well is directionally drilled, give subsurface locations and measured and trends work.)*</li> <li>(1) Pull rods, Down-hole pump and tubing out of hole.</li> <li>(2) Set RBP @ 3100', test RBP to 1000#, if holding the</li> <li>(3) Perforate Ramsey Sand from 2992-3000', 6 holes 0.4</li> <li>(4) Acidize same with 1000 gallons 7-1/2% NEFE.</li> <li>(5) Swab test well, if favorable then:</li> <li>(6) Fracture treat well with 4000 gallons gelled Kcl w</li> <li>(7) Swab back and test well.</li> <li>(8) Return well to production.</li> </ul>	en continue: +2" in diameter. vater and 8000# sand.
<ul> <li>DESCRIBE PROPOSED ON COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent proposed work. If well is directionally drilled, give subsurface locations and measured and tr nent to this work.)*</li> <li>(1) Pull rods, Down-hole pump and tubing out of hole.</li> <li>(2) Set RBP @ 3100', test RBP to 1000#, if holding the</li> <li>(3) Perforate Ramsey Sand from 2992-3000', 6 holes 0.4</li> <li>(4) Acidize same with 1000 gallons 7-1/2% NEFE.</li> <li>(5) Swab test well, if favorable then:</li> <li>(6) Fracture treat well with 4000 gallons gelled Kcl w</li> <li>(7) Swab back and test well.</li> <li>(8) Return well to production.</li> </ul>	en continue: +2" in diameter. vater and 8000# sand.

## \*See Instructions on Reverse Side