rom 3150-5 (November 1983) (Formérty 9-331)	UN OSTATES DEPARTMEN: OF THE INTE	SUBMIT IN TRIP (Other instruction, re- RIOR verse side) 38210	Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO
	BUREAU OF LAND MANAGEME	NT	LC-071066
	NDRY NOTICES AND REPORTS s form for proposals to drill or to deepen or plu Use "APPLICATION FOR PERMIT-" for suc		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1.		RECEIVED BY	7. UNIT AGREEMENT NAME
OIL GAS WELL	OTHER		
2. NAME OF OPERATOR		FEB 1 1 1987	8. FARM OR LEASE NAME
The Petrole	um Corporation of Delawa		Brushy 12 Federal
3. ADDRESS OF OPERATO	DR	O. C. D.	9. WBLL NO.
4. LOCATION OF WELL (See also space 17 be	Creek Blvd., Suite 350 Report location clearly and in accordance with a low.)		2 10. FIELD AND POOL, OR WILDCAT
At surface			Brushy Draw Delaware
2,310' FSL and 1,892' FWL			11. SEC., T., R., M., OR BLK. AND BURVEY OR AREA
Unit Letter	NE/4 of SW/4		Sec. 12, T-265, R-29E
14. PERMIT NO.	15. ELEVATIONS (Show whether	DF. RT GR. etc.)	12. COUNTY OR PARISH 13. STATE
API No. 30-0		GR 2983,5	
		· · · · · · · · · · · · · · · · · · ·	Eddy New Mexico
^{16.} Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data			
	NOTICE OF INTENTION TO :	80B8#Q	IENT REPORT OF :
TEST WATER SHUT-	OFF PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTUBE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDON MENT*
REPAIR WELL	CHANGE PLANS	(Other)	
(Other)	Recomplete X	(NOTE: Report results Completion or Recoupt	of multiple completion on Well etion Report and Log form.)
17. DESCRIBE PROPOSED (proposed work. I nent to this work.)	R COMPLETED OPERATIONS (Clearly state all pertiped is directionally drilled, give subsurface k	unt dataily and give postinget dates	Including and the data of the
Because t	perforations: 4,066' - 4 his well has become unec and test the Ramsey sand	conomical to produce	,365' - 5,412' (15 holes) e, we wish to move up
1. 5	Set cast-iron bridge pluc	rat 4 020'	, test to
	.,500' psi, and dump 35'		, lest lo
2. Perforate 3,256' - 3,266' with 4 jspf using 4" gun			
3. Set packer at 3,200 psi and frac down tubing using 5000 gal			
gelled diesel and 7,000 lb. 20/40 mesh sand.			
4. S	hut in 12 hours to allow	gell to break.	
 Pull packer from well, run tubing, sucker-rod pumping assembly, and begin pump test of well. 			
ŭ	ma sogin pamp rest of we	· + + •	
18 I harshy an-time at	the foregoing in the second second		
10. 1 hereby certify that	the foregoing is true and correct		
signed Tap	TITLE P	etroleum Engineer	DATE <u>2-6-87</u>
(This space for Finde	ror, State office use)		
			2000
APPROVED BY CONDITIONS OF A	PPROVAL, IF ANY :		DATE

.

*See Instructions on Reverse Side