BUREAU UF LAND MANAGEMEN	6 NO 10 10 10 10 10 10 10 10 10 10 10 10 10	Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL SO NM. 27459
SUNDRY NOTICES AND REPORTS (Do not use this form for proposals to drill or to deepen or plug Use "APPLICATION FOR PERMIT." for such	DACK TO A CHITEFEDI FERETVOIF	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL X GAS OTHER		7. UNIT AGREEMENT NAME
NAME OF OPERATOR		8. FARM OR LEASE NAME
MAX WILSON, INC. $$		MONSANTO FEDERAL
P. O. Drawer 1978 - Roswell, NM 88201		2 10. FIELD AND POOL OR WILDCAT
See also space 17 below.) At surface 2,310' FSL and 990' FEL	RECEIVED BY	Wildcat - Delanaie 11. SEC., T., R., M., OR BLK. AND
2,001	JAN 3 1 1986	SURVEY OR ARMA
PERMIT NO. 15 BLEVATIONS (Show whether I	OF, RT. GR. CO. C. D.	Sec. 22. T. 25S. R. 26E 12. COUNTY OR PARISH 13. STATE Eddy NM
Check Appropriate Box To Indicate	Nature of Notice, Report, or (
NOTICE OF INTENTION TO:		UENT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT MULTIPLE COMPLETE SHOOT OR ACIDIZE ABANDON*	FRACTURE TREATMENT SHOOTING OR ACIDIZING	ALTERING CASING ABANDONMENT*
REPAIR WELL CHANGE PLANS	· (Other)	
DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly State all pertine proposed work. If well is directionally drilled, give subsurface locatent to this work.)* Set 100' plug 1,800' to 1,900'	nt details, and give pertipent dates ations and measured and true vertic	, including estimated date of starting any ai depths for all markers and zones perti-
Set 100' plug 900' to 1000'		
	surface	
Set 100' plug 900' to 1000'	surface	
Set 100' plug 900' to 1000'	surface	
Set 100' plug 900' to 1000'	surface	
Set 100' plug 900' to 1000'	surface	
Set 100' plug 900' to 1000'	surface	
Set 100' plug 900' to 1000'	surface	
Set 100' plug 900' to 1000'	surface	
Set 100' plug 900' to 1000'	surface	
Set 100' plug 900' to 1000'	surface	
Set 100' plug 900' to 1000'	surface	
Set 100' plug 900' to 1000' Circ 50 sx across shoe of 8 8/5 to	President	DATE

*See Instructions on Reverse Side