Submit 3 Copies to Appropriate

CONDITIONS OF APPROVAL, IF ANY:

## State of New Mexico

Form C-103

P.O. Box 1980, Hobbs NM 88241-1980 P.O. Box 2088 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088  DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410  SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)  1. Type of Well: OIL WELL X  GAS WELL API NO. 30. 015 27399 5. Indicate Type of Lease STATE X  FEE  6. State Oil & Gas Lease No. LH2 460  7. Lease Name or Unit Agreement Name POGO 36 STATE  POGO 36 STATE  8. Well No. 2 3. Address of Operator P.O. BOX 11390; MIDLAND, TX 79702  9. Pool name or Wildcat North Brushy Draw Delaware	District Office	Energy, Minerals and Natural R	esources Department	1	Revised 1-1-89 C/
Santa Fe, New Mexico 87504-2088   3.0.15_27.399     Santa Fe, New Mexico 87504-2088   5. Indicate Type of Lease STATE         STATE		OIL CONSERVATIO	N DIVISION	WELLADING	<u>Op</u>
S. Indicate Type of Lease   STATE					
Substitute   Sub				5. Indicate Type of Lease	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO PRILOG BRO DEEPEN OF PLUG BACK TO A DIFFERENT RESERVICIBLUS OF PROPEOSALS.)  1. Type of Well:    Vell				6. State Oil & Gas Lease No.	LAI FEE L.I
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)  1. Type of Well. WELL					
OTHER  2. Name of Operator WELL S WELL OTHER  2. Name of Operator SUDTHMEST ROYALTIES, INC.  3. Address of Operator P.O. BOX 11390; MIDLAND, TX 79702  4. Well Location Unit Letter M 330 Feet From The South Line and 330 Feet From The West Line Section 36 Township 258 Range 29E NMPM Eddy County  10. Elevation (Show whether DP, RKB, RT, GR, etc.)  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO:  ERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS SUBSEQUENT REPORT OF:  CASING TEST AND CEMENT JOB PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB THER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1103.  11-12-96 - PLUG #1 - SET 5-1/2" CIBP @ 3212' & CAP W/ 35' CMT.  11-13-96 - PLUG #2 - SPOT 50 SXS CMT FROM 2350' -2000'; MOC & TAG.  11-13-96 - PLUG #2 - SPOT 15 SXS CMT FROM 50' -SURFACE.  INSTALL DRY HOLE MARKER; P&A COMPLETE 11-13-96.  DEC 18 '96  1-1-16-96  1-1-16-96	DIFFERENT RESEI (FORM C	RVOIR. USE "APPLICATION FOR PERI			ent Name
SOUTHWEST ROYALTIES, INC.  3. Address of Operator  Wint Letter M: 330 Feet From The South Line and 330 Feet From The West Line  Section 36 Township 258 Range 29E NMPM Eddy County  10. Elevation (Show whether DF, RKB, RT, GR, etc.)  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  ERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING  COMMENCE DRILLING OPNS PLUG AND ABANDON CASING TEST AND CEMENT JOB  THERE OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1103.  11-12-96 - PLUG #1 - SET 5-1/2" CIBP @ 3212' & CAP W/ 35' CMT.  11-13-96 - PLUG #2 - SPOT 50 SXS CMT FROM 667' -567'; NOC & TAG.  11-13-96 - PLUG #3 - SPOT 40 SXS CMT FROM 667' -567'; NOC & TAG.  11-13-96 - PLUG #4 - SPOT 15 SXS CMT FROM 667' -567'; NOC & TAG.  11-13-96 - PLUG #4 - SPOT 15 SXS CMT FROM 667' -567'; NOC & TAG.  11-13-96 - PLUG #4 - SPOT 15 SXS CMT FROM 667' -567'; NOC & TAG.  11-13-96 - PLUG #4 - SPOT 15 SXS CMT FROM 667' -567'; NOC & TAG.  11-13-96 - PLUG #4 - SPOT 15 SXS CMT FROM 667' -567'; NOC & TAG.  11-13-96 - PLUG #4 - SPOT 15 SXS CMT FROM 667' -567'; NOC & TAG.  11-13-96 - PLUG #4 - SPOT 15 SXS CMT FROM 667' -567'; NOC & TAG.  11-13-96 - PLUG #4 - SPOT 15 SXS CMT FROM 667' -567'; NOC & TAG.  11-13-96 - PLUG #4 - SPOT 15 SXS CMT FROM 507' -SURFACE.  INSTALL DRY HOLE MARKER; P&A COMPLETE 11-13-96.  DEC 18 '96  Therefore vertify to the log information above is type and specific to the best of my knowledge and beight.	OIL GAS WELL WELL	OTHER			
4. Well Location Unit Letter M 330 Feet From The South Line and 330 Feet From The West Line  36 Township 258 Range 29E NMPM Eddy County  10. Elevation (Show whether DF, RKB, RT, GR, etc.)  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  ERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING  EMPORABILLY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT  ULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB  THER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1103.  11. 12. 96 - PLUG #1 - SET 5-1/2" CIBP @ 3212' & CAP W/ 35' CMT.  11. 13. 96 - PLUG #2 - SPOT 50 SXS CMT FROM 2350' -2000'; WOC & TAG.  11. 13. 96 - PLUG #3 - SPOT 40 SXS CMT FROM 667' -567'; WOC & TAG.  11. 13. 96 - PLUG #4 - SPOT 15 SXS CMT FROM 607' -567'; WOC & TAG.  11. 13. 96 - PLUG #4 - SPOT 15 SXS CMT FROM 50' -SURFACE.  INSTALL DRY HOLE MARKER; P&A COMPLETE 11. 13. 96.  DEC 18 '96  Thereby certify that the information above is type and specifies to the best of my knowledge and beight.  Thereby certify that the information above is type and specifies to the best of my knowledge and beight.	SOUTHWEST ROYA				
4. Well Location Unit Letter M 330 Feet From The South Line and 330 Feet From The West Line  36 Township 258 Range 29E NMPM Eddy County  10. Elevation (Show whether DF, RKB, RT, GR, etc.)  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  ERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING  EMPORABILLY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT  ULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB  THER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1103.  11-12-96 - PLUG #1 - SET 5-1/2" CIBP @ 3212' & CAP W/ 35' CMT.  11-13-96 - PLUG #2 - SPOT 50 SXS CMT FROM 2350' -2000'; WOC & TAG.  11-13-96 - PLUG #3 - SPOT 40 SXS CMT FROM 667' -567'; WOC & TAG.  11-13-96 - PLUG #4 - SPOT 15 SXS CMT FROM 50' -SURFACE.  INSTALL DRY HOLE MARKER; P&A COMPLETE 11-13-96.  DEC 18 '96  Thereby certify that the information above is type and specifies to the best of any knowledge and beight.  Thereby certify that the information above is type and specifies to the best of any knowledge and beight.	3. Address of Operator P.O. BOX 11390	; MIDLAND, TX 79702		9. Pool name or Wildcat North Brushy Draw	Delaware
Section 36 Township 25 Range 29 NMPM Eddy County  10. Elevation (Show whether DF, RKB, RT, GR, etc.)  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  REMEDIAL WORK ALTERING CASING  COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1103.  11-12-96 - PLUG #1 - SET 5-1/2" CIBP @ 3212' & CAP W/ 35' CMT.  11-13-96 - PLUG #2 - SPOT 50 SXS CMT FROM 2350' -2000'; WOC & TAG.  11-13-96 - PLUG #3 - SPOT 40 SXS CMT FROM 667' -567'; WOC & TAG.  11-13-96 - PLUG #4 - SPOT 15 SXS CMT FROM 50' -SURFACE.  INSTALL DRY HOLE MARKER; P&A COMPLETE 11-13-96.  DEC 18 '96  Thereby certify that the information above is tiple and symplete to the best of my knowledge and belief.  Thereby certify that the information above is tiple and symplete to the best of my knowledge and belief.  Thereby certify that the information above is tiple and symplete to the best of my knowledge and belief.  Thereby certify that the information above is tiple and symplete to the best of my knowledge and belief.	4. Well Location		Line and 3	30 Feet From The W	est. Line
10. Elevation (Show whether DF, RKB, RT, GR, etc.)  Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  ERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1103.  11-12-96 - PLUG #1 - SET 5-1/2" CIBP @ 3212' & CAP W/ 35' CMT.  11-13-96 - PLUG #2 - SPOT 50 SXS CMT FROM 2350'-2000'; WOC & TAG.  11-13-96 - PLUG #3 - SPOT 40 SXS CMT FROM 667'-567'; WOC & TAG.  11-13-96 - PLUG #4 - SPOT 15 SXS CMT FROM 50'-SURFACE.  INSTALL DRY HOLE MARKER; P&A COMPLETE 11-13-96.  DEC 18 '96  12-16-96  Thereby certify the the information above is type and perfects to the best of my knowledge and belief.  Thereby certify the the information above is type and perfects to the best of my knowledge and belief.  Thereby certify the the information above is type and perfects to the best of my knowledge and belief.  Thereby certify the the information above is type and perfects to the best of my knowledge and belief.	Section 36	Township 25S Ra	29E	Eddy	
SUBSEQUENT REPORT OF:  ERFORM REMEDIAL WORK				141411 141	Tillillillillillillillillillillillillill
SUBSEQUENT REPORT OF:  ERFORM REMEDIAL WORK  PLUG AND ABANDON  ALTERING CASING  EMPORABILY ABANDON  CHANGE PLANS  COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT  CASING TEST AND CEMENT JOB  THER:    OTHER:			NT A ANY		
ERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING  EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT  ULL OR ALTER CASING CASING CASING TEST AND CEMENT JOB  THER:  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1103.  11-12-96 - PLUG #1 - SET 5-1/2" CIBP @ 3212' & CAP W/ 35' CMT.  11-13-96 - PLUG #2 - SPOT 50 SXS CMT FROM 2350' -2000'; WOC & TAG.  11-13-96 - PLUG #3 - SPOT 40 SXS CMT FROM 667' -567'; WOC & TAG.  11-13-96 - PLUG #4 - SPOT 15 SXS CMT FROM 50' -SURFACE.  INSTALL DRY HOLE MARKER: P&A COMPLETE 11-13-96.  DEC 18 '96  5-1/2" CSG CUT & PULLED FROM 2066'.  HOLE DISPLACED W/ MLF BETWEEN PLUGS 9.5 PPG BRINE W/ 25 PPB SALT GEL.			1	• •	
COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT  CASING TEST AND CEMENT JOB  THER:  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1103.  11-12-96 - PLUG #1 - SET 5-1/2" CIBP @ 3212' & CAP W/ 35' CMT.  11-13-96 - PLUG #2 - SPOT 50 SXS CMT FROM 2350' -2000'; WOC & TAG.  11-13-96 - PLUG #3 - SPOT 40 SXS CMT FROM 667' -567'; WOC & TAG.  11-13-96 - PLUG #4 - SPOT 15 SXS CMT FROM 50' -SURFACE.  INSTALL DRY HOLE MARKER; P&A COMPLETE 11-13-96.  5-1/2" CSG CUT & PULLED FROM 2066'.  HOLE DISPLACED W/ MLF BETWEEN PLUGS 9.5 PPG BRINE W/ 25 PPB SALT GEL.  Thereby certify that the information above is type and symplete to the best of my knowledge and besign.	NOTICE OF IN	TIENTION TO:	Sui	SSEQUENT REPOR	RT OF:
CASING TEST AND CEMENT JOB  THER:  OTHER:  2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1103.  11-12-96 - PLUG #1 - SET 5-1/2" CIBP @ 3212' & CAP W/ 35' CMT.  11-13-96 - PLUG #2 - SPOT 50 SXS CMT FROM 2350'-2000'; WOC & TAG.  11-13-96 - PLUG #3 - SPOT 40 SXS CMT FROM 667'-567'; WOC & TAG.  11-13-96 - PLUG #4 - SPOT 15 SXS CMT FROM 50'-SURFACE.  INSTALL DRY HOLE MARKER; P&A COMPLETE 11-13-96.  DEC 18 '96  1-2-16-96  Thereby certify that the information above is true and symplete to the best of my knowledge and belight.  Thereby certify that the information above is true and symplete to the best of my knowledge and belight.	ERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING O	CASING
2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1103.  11-12-96 - PLUG #1 - SET 5-1/2" CIBP @ 3212' & CAP W/ 35' CMT.  11-13-96 - PLUG #2 - SPOT 50 SXS CMT FROM 2350'-2000'; WOC & TAG.  11-13-96 - PLUG #3 - SPOT 40 SXS CMT FROM 667'-567'; WOC & TAG.  11-13-96 - PLUG #4 - SPOT 15 SXS CMT FROM 50'-SURFACE.  INSTALL DRY HOLE MARKER: P&A COMPLETE 11-13-96.  DEC 18 '96  5-1/2" CSG CUT & PULLED FROM 2066'.  HOLE DISPLACED W/ MLF BETWEEN PLUGS 9.5 PPG BRINE W/ 25 PPB SALT GEL.	EMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	G OPNS. PLUG AND A	ABANDONMENT X
2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1103.  11-12-96 - PLUG #1 - SET 5-1/2" CIBP @ 3212' & CAP W/ 35' CMT.  11-13-96 - PLUG #2 - SPOT 50 SXS CMT FROM 2350' -2000'; WOC & TAG.  11-13-96 - PLUG #3 - SPOT 40 SXS CMT FROM 667' -567'; WOC & TAG.  11-13-96 - PLUG #4 - SPOT 15 SXS CMT FROM 50' -SURFACE.  INSTALL DRY HOLE MARKER; P&A COMPLETE 11-13-96.  DEC 18 '96  5-1/2" CSG CUT & PULLED FROM 2066'.  HOLE DISPLACED W/ MLF BETWEEN PLUGS 9.5 PPG BRINE W/ 25 PPB SALT GEL.	JLL OR ALTER CASING		CASING TEST AND C	<del></del> 1	
11-12-96 - PLUG #1 - SET 5-1/2" CIBP @ 3212' & CAP W/ 35' CMT.  11-13-96 - PLUG #2 - SPOT 50 SXS CMT FROM 2350'-2000'; WOC & TAG.  11-13-96 - PLUG #3 - SPOT 40 SXS CMT FROM 667'-567'; WOC & TAG.  11-13-96 - PLUG #4 - SPOT 15 SXS CMT FROM 50'-SURFACE.  INSTALL DRY HOLE MARKER; P&A COMPLETE 11-13-96.  5-1/2" CSG CUT & PULLED FROM 2066'.  HOLE DISPLACED W/ MLF BETWEEN PLUGS 9.5 PPG BRINE W/ 25 PPB SALT GEL.  Thereby certify that the information above is type and somplete to the best of my knowledge and belief.  Thereby certify that the information above is type and somplete to the best of my knowledge and belief.	THER:		OTHER:		
11-12-96 - PLUG #1 - SET 5-1/2" CIBP @ 3212' & CAP W/ 35' CMT.  11-13-96 - PLUG #2 - SPOT 50 SXS CMT FROM 2350'-2000'; WOC & TAG.  11-13-96 - PLUG #3 - SPOT 40 SXS CMT FROM 667'-567'; WOC & TAG.  11-13-96 - PLUG #4 - SPOT 15 SXS CMT FROM 50'-SURFACE.  INSTALL DRY HOLE MARKER; P&A COMPLETE 11-13-96.  5-1/2" CSG CUT & PULLED FROM 2066'.  HOLE DISPLACED W/ MLF BETWEEN PLUGS 9.5 PPG BRINE W/ 25 PPB SALT GEL.  Thereby certify that the information above is true and somplete to the best of my knowledge and belief.  12-16-96	2. Describe Proposed or Completed Ope	erations (Clearly state all pertinent deta	ails, and give pertinent da	ntes, including estimated date of st	tarting any proposed
11-13-96 - PLUG #2 - SPOT 50 SXS CMT FROM 2350'-2000'; WOC & TAG. 11-13-96 - PLUG #3 - SPOT 40 SXS CMT FROM 667'-567'; WOC & TAG. 11-13-96 - PLUG #4 - SPOT 15 SXS CMT FROM 50'-SURFACE.  INSTALL DRY HOLE MARKER; P&A COMPLETE 11-13-96.  5-1/2" CSG CUT & PULLED FROM 2066'. HOLE DISPLACED W/ MLF BETWEEN PLUGS 9.5 PPG BRINE W/ 25 PPB SALT GEL.  Thereby certify that the information above is type and somplete to the best of my knowledge and belief.  12-16-96	work) SEE RULE 1103.			Pa	st ID-2
11-13-96 - PLUG #3 - SPOT 40 SXS CMT FROM 667'-567'; WOC & TAG. 11-13-96 - PLUG #4 - SPOT 15 SXS CMT FROM 50'-SURFACE.  INSTALL DRY HOLE MARKER; P&A COMPLETE 11-13-96.  5-1/2" CSG CUT & PULLED FROM 2066'. HOLE DISPLACED W/ MLF BETWEEN PLUGS 9.5 PPG BRINE W/ 25 PPB SALT GEL.  Thereby certify that the information above is type and somplete to the best of my knowledge and belief.  12-16-96	11-12-96 - PLUG #1	- SET 5-1/2" CIBP @ 3212' {	& CAP W/ 35' CMT.	1	1-3-96
INSTALL DRY HOLE MARKER; P&A COMPLETE 11-13-96.  5-1/2" CSG CUT & PULLED FROM 2066'. HOLE DISPLACED W/ MLF BETWEEN PLUGS 9.5 PPG BRINE W/ 25 PPB SALT GEL.  Install DRY HOLE MARKER; P&A COMPLETE 11-13-96.  DEC 18 '96  10 CTICE					PXA
5-1/2" CSG CUT & PULLED FROM 2066'. HOLE DISPLACED W/ MLF BETWEEN PLUGS 9.5 PPG BRINE W/ 25 PPB SALT GEL.  / WINCE  Thereby certify that the information above is true and complete to the best of my knowledge and belief.					
5-1/2" CSG CUT & PULLED FROM 2066'.  HOLE DISPLACED W/ MLF BETWEEN PLUGS 9.5 PPG BRINE W/ 25 PPB SALT GEL.  / OFFICE  Thereby certify that the information above is true and complete to the best of my knowledge and belief.	INSTALL DRY H	HOLE MARKER; P&A COMPLETE	11-13-96.	<b>-</b> -:	
HOLE DISPLACED W/ MLF BETWEEN PLUGS 9.5 PPG BRINE W/ 25 PPB SALT GEL.  / OFFICE  Thereby certify that the information above is true and complete to the best of my knowledge and belief.  12-16-96	5-1/2" CSG CUT & PL	JLLED FROM 2066'.		DEC 18.	96
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			RINE W/ 25 PPB SAI	LT GEL.	
12-16-96				/ Dis	riCE
12-16-96	2	į.	<b>.</b>		
12-16-96	I hereby certify that the information above is t	rue and complete to the best of my knowledge	and belief.		10 16 06
SIGNATURE / TITLE FOR SUFERVISOR -SIETTA WS DATE /0/16/12		Chi I late	gie Cil	Cd array IIC	12-16-96
Regulatory Coordinator	SIGNATURE /	THE THE TIME			0/16/10
TYPE OR PRINT NAME JIMMY BAGLEY Beverly Hatfield TELEPHONE NO. (915)563-043	TYPE OR PRINT NAME JIMMY BAGLEY	Beverly Hatfield	<u> </u>	TELEPHONE NO	(915)563-0430
. r = .	APPROVED BY man (5 Collins)	<b>Q.</b> TITI	E Field Rep. I	DATE /-	16 - 97