

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer 610, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-015-28968

5. Indicate Type of Lease
STATE ☒ FEE

6. State Oil & Gas Lease No.
V-3441

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☐ Other ☐

2. Name of Operator
TMBR/Sharp Drilling, Inc.

3. Address of Operator
P. O. Drawer 10970, Midland, TX 79702

4. Well Location
Unit Letter F : 1980 Feet From The North Line and 1980 Feet From The West

Section 3 Township 25S Range 27E NMPM Eddy Co.

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3223' GR 3236' KB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Production in the referenced well has become un-economic. There are no other opportunities in this wellbore for commercial production. The operator proposes that the well be plugged and abandoned as follows:

- 1) Wireline set a CIBP @ $\pm 5626'$ KB and dump bail 35' of cement on top.
- 2) Cut & pull 5-1/2" casing from $\pm 3650'$.
- 3) Spot plug #2 - 3,700' to 3600' w/25 sx CI "C" and tag.
- 4) Plug #3 - 2250-2150' across 8-5/8" shoe and tag.
- 5) Plug #4 - 694 to 584 across 13-3/8" shoe and tag.
- 6) Plug #5 - 10 sx plug at surface.
- 7) Cut off wellhead and install monument.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jeff Phillips TITLE Production Manager DATE 10-9-96
TYPE OR PRINT NAME Jeff Phillips (915) 699-5050 TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

NOV 11 1996