Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM: 88240

OIL CONSERVATION DIVISION P.O. Box 2088

30-015-29271

WELL API NO.

DISTRICT II Santa Fe, New Mexico 87	7504-2088
P.O. Drawer DD, Anceia, NM 88210	5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	STATE X FEE
1000 NO BIZZOS NO., AZEC, 1001 87410	6. State Oil & Gas Lease No. L-896
SUNDRY NOTICES AND REPORTS CHIVELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR	R PLUG BACK TO A 7 Tease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI (FORM C-101) FOR SUCH PROPOSALS.)	2 8 1997
1. Type of Well:	
OIL OAS X OTHER SEA	0gden
2. Name of Operator	8. Well No.
MURCHISON OIL & GAS INC.	3
3. Address of Operator	9. Pool name or Wildcat
1445 ROSS AVE., SUITE 5300, LB 152, DALLAS, 4. Well Location	TX. 75202 WHITE CITY PENN (GAS)
	. 1650 WEST
Unit Letter K.: 1650 Feet From The SOUTH	Line and 1030 Feet From The WEST Line
Section 2 Township 25 S Range	26 E NMPM EDDY County
10. Elevation (Show whether DF.	RKB, RT, GR, etc.)
//////////////////////////////////////	
11. Check Appropriate Box to Indicate Nat	nure of Notice, Report, or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON RE	EMEDIAL WORK ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS C	OMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
	ASING TEST AND CEMENT JOB X
PULL OR ALTER CASING CA	ASING TEST AND CEMENT JOB 🖫
PULL OR ALTER CASING CA	
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give	ASING TEST AND CEMENT JOB THER:
PULL OR ALTER CASING CA	ASING TEST AND CEMENT JOB THER:
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give work) SEE RULE 1103.	ASING TEST AND CEMENT JOB THER: We pertinent dates, including estimated date of starting any proposed
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give work) SEE RULE 1103. Drill 6 1/2" hole from 8604' to 11540'. Set	ASING TEST AND CEMENT JOB THER: THER: THE Perfinent dates, including estimated date of starting any proposed 79 jts 5 1/2" 20 #/FT N-80 FL4S csg from
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give work) SEE RULE 1103. Drill 6 1/2" hole from 8604' to 11540'. Set 8284' to 11540' cement w/ 340 sx Class H & .4	THER: THER: TO jts 5 1/2" 20 #/FT N-80 FL4S csg from % CFR-3 & .6% gas stop & .4% Halad-22A
PULL OR ALTER CASING OTHER: 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give work) SEE RULE 1103. Drill 6 1/2" hole from 8604' to 11540'. Set 8284' to 11540' cement w/ 340 sx Class H & .4 Plug down @ 6:30 PM 1/26/97. Test liner top	ASING TEST AND CEMENT JOB X THER: THE Performed dates, including estimated date of starting any proposed 79 jts 5 1/2" 20 #/FT N-80 FL4S csg from % CFR-3 & .6% gas stop & .4% Halad-22A to 1000 PSI. Held OK. Release drilling
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give work) SEE RULE 1103. Drill 6 1/2" hole from 8604' to 11540'. Set 8284' to 11540' cement w/ 340 sx Class H & .4 Plug down @ 6:30 PM 1/26/97. Test liner top rig 1/28/97. Rig up completion unit 3/3/97.	THER: THER: TO jts 5 1/2" 20 #/FT N-80 FL4S csg from % CFR-3 & .6% gas stop & .4% Halad-22A to 1000 PSI. Held OK. Release drilling Drill out cement to 11463'. Run cement
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give work) SEE RULE 1103. Drill 6 1/2" hole from 8604' to 11540'. Set 8284' to 11540' cement w/ 340 sx Class H & .4 Plug down @ 6:30 PM 1/26/97. Test liner top rig 1/28/97. Rig up completion unit 3/3/97. bond log, Top of cement @ 9830'. Set 2 7/8"	THER:
PULL OR ALTER CASING OTHER: 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give work) SEE RULE 1103. Drill 6 1/2" hole from 8604' to 11540'. Set 8284' to 11540' cement w/ 340 sx Class H & .4 Plug down @ 6:30 PM 1/26/97. Test liner top rig 1/28/97. Rig up completion unit 3/3/97. bond log, Top of cement @ 9830'. Set 2 7/8" VI Packer @ 10,879'. Perf Morrow w/ 2 shots/	THER: THER: TO jts 5 1/2" 20 #/FT N-80 FL4S csg from % CFR-3 & .6% gas stop & .4% Halad-22A to 1000 PSI. Held OK. Release drilling Drill out cement to 11463'. Run cement N-80 tubing on 10,000 PSI Guiberson Un. ft @ 11,392-94 (5 holes), 11373-88' (31
DTHER:	THER: THER: TO jts 5 1/2" 20 #/FT N-80 FL4S csg from % CFR-3 & .6% gas stop & .4% Halad-22A to 1000 PSI. Held OK. Release drilling Drill out cement to 11463'. Run cement N-80 tubing on 10,000 PSI Guiberson Un. ft @ 11,392-94 (5 holes), 11373-88' (31es), 11074-67' (15 holes), 11058-50 (17
DTHER:	THER: THER: THER: TO jts 5 1/2" 20 #/FT N-80 FL4S csg from % CFR-3 & .6% gas stop & .4% Halad-22A to 1000 PSI. Held OK. Release drilling Drill out cement to 11463'. Run cement N-80 tubing on 10,000 PSI Guiberson Un. ft @ 11,392-94 (5 holes), 11373-88' (31 es), 11074-67' (15 holes), 11058-50 (17 es). Swab well down. Acidize w/ 4500 GAL
DTHER:	THER: THER: THER: TO jts 5 1/2" 20 #/FT N-80 FL4S csg from % CFR-3 & .6% gas stop & .4% Halad-22A to 1000 PSI. Held OK. Release drilling Drill out cement to 11463'. Run cement N-80 tubing on 10,000 PSI Guiberson Un. ft @ 11,392-94 (5 holes), 11373-88' (31 es), 11074-67' (15 holes), 11058-50 (17 es). Swab well down. Acidize w/ 4500 GAL
DTHER:	THER: THER: THER: THER: TO jts 5 1/2" 20 #/FT N-80 FL4S csg from % CFR-3 & .6% gas stop & .4% Halad-22A to 1000 PSI. Held OK. Release drilling Drill out cement to 11463'. Run cement N-80 tubing on 10,000 PSI Guiberson Un. ft @ 11,392-94 (5 holes), 11373-88' (31 es), 11074-67' (15 holes), 11058-50 (17 es). Swab well down. Acidize w/ 4500 GAL Pump @ 5.6 BPM & 3640 to 4110 PSI.
DTHER:	THER: TH
DTHER:	THER: TH
DTHER:	THER: TH
DTHER:	THER: THER: THER: TO jts 5 1/2" 20 #/FT N-80 FL4S csg from % CFR-3 & .6% gas stop & .4% Halad-22A to 1000 PSI. Held OK. Release drilling Drill out cement to 11463'. Run cement N-80 tubing on 10,000 PSI Guiberson Un. ft @ 11,392-94 (5 holes), 11373-88' (31 es), 11074-67' (15 holes), 11058-50 (17 es). Swab well down. Acidize w/ 4500 GAL Pump @ 5.6 BPM & 3640 to 4110 PSI. thut down to design frac.
DTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and givered) SEE RULE 1103. Drill 6 1/2" hole from 8604' to 11540'. Set 8284' to 11540' cement w/ 340 sx Class H & .4 Plug down @ 6:30 PM 1/26/97. Test liner top rig 1/28/97. Rig up completion unit 3/3/97. bond log, Top of cement @ 9830'. Set 2 7/8" VI Packer @ 10,879'. Perf Morrow w/ 2 shots/holes), 11252-57' (11 holes), 11147-43 (9 hol holes), 11029-27 (5 holes), 11014-08 (13 hole 7.5% HCL W 25% Methanol and 137 ball sealers. 15 DP 2490, 5 min SI 2210, 10 min SI 2100 PSI Run 72 hr bomb, BHP estimated to be 3450. S Thereby certify that the try terms led above it trice and complete to the best of my knowledge and balled. SKONATURE	THER: THER: THER: TO jts 5 1/2" 20 #/FT N-80 FL4S csg from % CFR-3 & .6% gas stop & .4% Halad-22A to 1000 PSI. Held OK. Release drilling Drill out cement to 11463'. Run cement N-80 tubing on 10,000 PSI Guiberson Un. ft @ 11,392-94 (5 holes), 11373-88' (31 es), 11074-67' (15 holes), 11058-50 (17 es). Swab well down. Acidize w/ 4500 GAL Pump @ 5.6 BPM & 3640 to 4110 PSI. 1.5 min SI 2020 PSI. Swab back load. Shut down to design frac.

CONDITIONS OF APPROVAL, IF ANY:

APPROVED BY-