RONNIE E. SHO ACTING DISTRICT ENG		O. C. C. CONY UBMIT IN TRIPLICAT UNITED STATES MENT OF THE IN SECLOSICAL SURVE	S NTERIOR Y	Approval ex Land Office Link Land No. OG Unit Pok	au No. 42 R338.4 pores 12 d e0 6 Cruces .894 er Lake
SUI					
NOTICE OF INTENTION NOTICE OF INTENTION	TO CHANGE PLANS TO TEST WATER SHUT OFF TO RE-DRILL OR REPAIR WELL TO SHOOT OR ACIDI7E TO PULL OR ALTER CASING	SUBSEQUENT SUBSEQUENT SUBSEQUENT SUBSEQUENT	REPORT OF WATER REPORT OF SHOOTI REPORT OF ALTER REPORT OF RE-DRII REPORT OF ABANDIC ARY WELL HISTORY	NG OR ACIDIZING NG CASING LLING OR REPAIR	
L	(INDICATE ABOVE BY CHE	CK MARK NATURE OF REPOR	NOTICE, OR OTHER	DATA)	
			May 9		, 19 63
.		· · ·	•		
Well No. 2	is located 1980	ft. from S line and	1 660 ft. fr	$\mathbf{w} = \mathbf{w}$ inc. of	sec. 20
SW 1/4 of Sec	tion 20 $T-25-S$	R-30-E N	ew Mexico F	rincipal Me	ridi an
Undesignated	Eddy	County of Subdivision.	Elev. K	DB (Measure L'. GL elev.	
The devation of t	the derrick floor above	DETAILS OF WOR	-		<u>j</u> 210 0
			neths of proposed ca	asiugs; indigate muc	ding jobs, coment-
(Sture matter of and exp			answed work)		
As per telephor	e conversation wi	th Mr. Knauf on	5-8-63, we	propose to	
As per telephon abandon the sub	e conversation wi oject well in the	th Mr. Knauf on following manner	5-8-63, we		plug and
As per telephon abandon the sub Run a free-point free-point is b	the conversation with the object well in the object well in the object of $5\frac{1}{2}$ object with the object of 3262 . Other	th Mr. Knauf on following manner	5-8-63, we	wll 5¹/2" OD	plug and
As per telephon abandon the sub Run a free-point free-point is b cutting and put Spot 50 sx.	the conversation with oject well in the nt indicator on 5 below 3262. Other lling casing. cement on bottom	th Mr. Knauf on following manner "OD casing. Cu wise wait until (3663 PBTD), whi	5-8-63, we toff and p bottom plug	pull 5 ¹ / ₂ " OD g is spotted	plug and F casing if before
As per telephon abandon the sub Run a free-point free-point is t cutting and put Spot 50 sx.	the conversation with oject well in the nt indicator on 5 below 3262. Other lling casing. cement on bottom	th Mr. Knauf on following manner "OD casing. Cu wise wait until (3663 PBTD), whi and pull 54" cas:	5-8-63, we toff and p bottom plug ich will fil	ull 5 ¹ / ₂ " OD 3 is spotted 11 back to a	plug and casing if before pproximately
As per telephon abandon the sub Run a free-point free-point is h cutting and put Spot 50 sx. 3262' in the 55 Spot 50 sx.	ae conversation wi oject well in the nt indicator on 5 below 3262. Other lling casing. cement on bottom 2" casing. Cut a cement in 7-7/8"	th Mr. Knauf on following manner the OB casing. Curwise wait until (3663 PBTD), whi and pull $5\frac{1}{2}$ " case hole from 1970 f	5-8-63, we to off and j bottom plug ich will fil ing. to 2120 (bas	pull $5\frac{1}{2}$ " OD g is spotted il back to a sed on 8" ho	plug and casing if before pproximately ble size).
As per telephon abandon the sub Run a free-point free-point is b cutting and pul Spot 50 sx. 3262' in the 55 Spot 50 sx. Base of Salado Spot 50 sx. casing at 674.	the conversation with object well in the int indicator on 5 below 3262. Other lling casing. cement on bottom 2" casing. Cut a cement in 7-7/8"	th Mr. Knauf on following manner of OD casing. Gu wise wait until (3663 PBTD), whi and pull 5½" cas: hole from 1970 to to 750; to cover nt in top 30; of 11. complete loc;	5-8-63, we to off and p bottom plug ich will fil ing. to 2120 (base 8-5/8" case ation on per	pull $5\frac{1}{2}$ " OD g is spotted il back to a sed on 8" ho of the 8-5/6 ing. Instal manent-type	plug and casing if before pproximately ble size). " surface l 4" pipe sign.
As per telephon abandon the sub Run a free-point free-point is to cutting and put Spot 50 sx. 3262' in the 55 Spot 50 sx. Base of Salado Spot 50 sx. casing at 674. with company na	ae conversation wi oject well in the nt indicator on 5 below 3262. Other lling casing. cement on bottom 2" casing. Cut a cement in 7-7/8" is 2045. cement from 600' Put 10 sx. cemer	th Mr. Knauf on following manner of OD casing. Gu wise wait until (3663 PBTD), whi and pull 5½" cas: hole from 1970 to to 750; to cover nt in top 30; of 11. complete loc;	5-8-63, we to off and p bottom plug ich will fil ing. to 2120 (base 8-5/8" case ation on per	pull $5\frac{1}{2}$ " OD g is spotted il back to a sed on 8" ho of the 8-5/6 ing. Instal manent-type	plug and casing if before pproximately ble size). In surface l 4" pipe sign.
As per telephon abandon the sub Run a free-point free-point is b cutting and pul Spot 50 sx. 3262' in the 59 Spot 50 sx. Base of Salado Spot 50 sx. casing at 674. with company has competed PE	ae conversation wi oject well in the nt indicator on 5 below 3262. Other lling casing. cement on bottom 2" casing. Cut a cement in 7-7/8" is 2045. cement from 6001 Put 10 sx. cement ame, lease and we	th Mr. Knauf on following manner of OD casing. Gu wise wait until (3663 PBTD), whi and pull 5½" cas: hole from 1970 to to 750; to cover nt in top 30; of 11. complete loc;	5-8-63, we to off and p bottom plug ich will fil ing. to 2120 (base 8-5/8" case ation on per	pull $5\frac{1}{2}$ " OD g is spotted il back to a sed on 8" ho of the 8-5/6 ing. Instal manent-type	plug and casing if before pproximately ble size). In surface l 4" pipe sign.
As per telephon abandon the sub Run a free-point free-point is to cutting and put Spot 50 sx. 3262' in the 55 Spot 50 sx. Base of Salado Spot 50 sx. casing at 674. with company na fundersand the free Company PE Address Bo	ae conversation wi oject well in the nt indicator on 5 below 3262. Other lling casing. cement on bottom 2" casing. Cut a cement in 7-7/8" is 2045. cement from 6001 Put 10 sx. cement ame, lease and we herefore work out treeve	th Mr. Knauf on following manner of OD casing. Gu wise wait until (3663 PBTD), whi and pull 5½" cas: hole from 1970 to to 750; to cover nt in top 30; of 11. complete loc;	5-8-63, we it off and p bottom plug ich will fil ing. to 2120 (base ation on per ation on per	pull $5\frac{1}{2}$ " OD g is spotted il back to a sed on 8" ho of the 8-5/8 ing. Instal rmanent-type or operation may be defined.	plug and casing if before pproximately ble size). " surface l 4" pipe sign.
As per telephon abandon the sub Run a free-point free-point is to cutting and put Spot 50 sx. 3262' in the 55 Spot 50 sx. Base of Salado Spot 50 sx. casing at 674. with company na fundersand the free Company PE Address Bo	ae conversation wi oject well in the nt indicator on 5 below 3262. Other lling casing. cement on bottom 2" casing. Cut a cement in 7-7/8" is 2045. cement from 600' Put 10 sx. cemer ame, lease and well herefore work next received RRY R. BASS	th Mr. Knauf on following manner "OD casing. Cu wise wait until (3663 PBTD), whi and pull 5½" cas: hole from 1970 to to 750' to cover nt in top 30' of 11, complete loca	5-8-63, we it off and p bottom plug ich will fil ing. to 2120 (bas r the base 8-5/8" cas ation on per by Walte	pull $5\frac{1}{2}$ " OD g is spotted il back to a sed on 8" ho of the 8-5/6 ing. Instal manent-type	plug and casing if before pproximately ole size). In surface l h" pipe o sign.

Ì.