

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-147
Revised April 3, 2017

Recycling Facility and/or Recycling Containment

Type of Facility: ☒ Recycling Facility ☒ Recycling Containment*
Type of action: ☐ Permit ☐ Registration
☐ Modification ☒ Extension
☐ Closure ☐ Other (explain) _____

* At the time C-147 is submitted to the division for a Recycling Containment, a copy shall be provided to the surface owner.

Be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.

1.

Operator: Enduring Resources, LLC (For multiple operators attach page with information) OGRID #: 372286
Address: 200 Energy Court, Farmington, NM 87401
Facility or well name (include API# if associated with a well): WLU 2309 24N Water Recycle Facility
OCD Permit Number: 3RF-29 (For new facilities the permit number will be assigned by the district office)
U/L or Qtr/Qtr SE/4 SW/4 & SW/4 Section 24 Township 23N Range 9W County: San Juan
Surface Owner: ☒ Federal ☐ State ☐ Private ☐ Tribal Trust or Indian Allotment

2.

☒ **Recycling Facility:**
Location of recycling facility (if applicable): Latitude 36.205958 Longitude -107.740891 NAD83
Proposed Use: ☒ Drilling* ☒ Completion* ☒ Production* ☒ Plugging *
**The re-use of produced water may NOT be used until fresh water zones are cased and cemented*
☐ Other, *requires permit for other uses. Describe use, process, testing, volume of produced water and ensure there will be no adverse impact on groundwater or surface water.*
☒ Fluid Storage
☒ Above ground tanks ☒ Recycling containment ☐ Activity permitted under 19.15.17 NMAC explain type _____
☐ Activity permitted under 19.15.36 NMAC explain type: _____ ☐ Other explain _____
☐ For multiple or additional recycling containments, attach design and location information of each containment
☐ **Closure Report (required within 60 days of closure completion):** ☐ Recycling Facility Closure Completion Date: _____

3.

☒ **Recycling Containment:**
☐ Annual Extension after initial 5 years (attach summary of monthly leak detection inspections for previous year)
Center of Recycling Containment (if applicable): Latitude 36.205958 Longitude -107.740891 NAD83
☐ For multiple or additional recycling containments, attach design and location information of each containment
☐ Lined ☒ Liner type: Thickness 45 mil ☒ LLDPE ☐ HDPE ☐ PVC ☐ Other _____
☒ String-Reinforced
Liner Seams: ☒ Welded ☒ Factory ☐ Other _____ Volume: 265,385 bbl Dimensions: L 350' x W 400' x D 25'
☐ Recycling Containment Closure Completion Date: _____

From: [Smith, Cory, EMNRD](#)
To: [Heather Huntington](#)
Cc: [David Rogers](#); [Enviro, OCD, EMNRD](#)
Subject: RE: RE: Enduring 3RF-29 Subsequent Determination of Cessation of Operation Variance Request
Date: Wednesday, September 30, 2020 2:38:00 PM
Attachments: [image001.png](#)

The Oil Conservation Division (OCD) has reviewed the determination of cessation of operations extension request for WLU 2309-24N 3RF-29, received from ENDURING RESOURCES, LLC OGRID 372286 on 7/31/2020. The cessation for operations extension request is approved with the following conditions of approval.

- WLU 2309-24N 3RF-29 permit expiration date is October 14, 2023
- Enduring Resources must recycle at least 53,077 BBLs of produced water no later than January 1, 2021 to be considered in operations.
- Enduring Resources will maintain a liquid level in the containment that is at least equal to the weight of the liner plus 20%. Enduring Resources may maintain a higher liquid level if they choose. Please provide the minimum liquid level calculation and the minimum liquid level to be maintained to the OCD no later than October 30, 2020
- Any withdrawal of fluid from the containment will negate this determination of the cessation of operations extension. Once the extension is negated and no longer in effect, an incremental fluid level test will be required.
- Enduring Resources will provide written notice to the OCD (email to ocd.enviro@state.nm.us) at least 72 hours, but no more than one week, prior to the incremental fill test and the recommencement of operations. Recommencement of recycling operations means that the operator plans to resume moving fluids through the containment and discharging fluids from the containment. The incremental fill test and notice of the test must be completed before fluids can move through the containment.
 - At the resumption of recycling operations, Enduring Resources is required to perform an incremental fluid level test for containment liquid levels above the minimum liquid level.
 - Enduring Resources will fill the containment. Enduring Resources will pause filling operations at every 10% of total fluid capacity above the minimum level.
 - Enduring Resources will maintain the liquid level for each 10% volume increase for 24 hours and inspect and operation the leak detection system at the end of the 24-hour period.
 - ❖ If there are no liquids present in the leak detection system, Enduring Resources may proceed to fill the next 10% volume and repeat the process until the containment full design capacity minus the 3-feet of freeboard is reached. eat the process until the containment full de reached.
 - ❖ If liquids are present, Enduring Resources should immediately cease the

incremental fill test and perform a liner inspection. Enduring Resources should provide written notice of the fluid detection and liner inspection findings to the OCD (email to ocd.enviro@state.nm.us) using a C-147 (long form) with the "Other" box checked and "Notice of fluid detection" written as the explanation of "Other."

- Upon notification of fluid detection in the leak detection system, the OCD will verify the source of water (condensation versus produced water).
- If the detected fluid is confirmed to be condensation, the OCD will issue a written approval to proceed with the incremental fluid level test.
- If the detected fluid is confirmed to be produced water, Enduring Resources must comply with 19.15.34.13 NMAC. Enduring Resources must provide written notification (email to ocd.enviro@state.nm.us) on the actions taken to comply with 19.15.34.13 NMAC.
- After fluid is detected in the leak detection system, the incremental fill test cannot continue until after a written approval to proceed is issued by the OCD.

❖ Enduring Resources must submit copies of the detailed containment inspection records for the prior three (3) months and a report detailing the incremental fluid level test process and results to the OCD. Enviro mailbox using a C-147 (long form) with the "Other" box checked. "Recommendation of Operations - Incremental Fluid Level Test" should be written as the explanation of "Other." Form C-147 must be completed and include information in sections 1 General Information, 2 Recycling Facility, 3 Recycling Containment, 4 Bonding, and 10 Operator Application Certification. Section 9 Recycling Facility and/or Containment Checklist may also need to be partially completed. Operators should verify that the resumption of operations notification does not result in any changes to the recycling containment operating and maintenance plan or the closure plan. If the recommendation of operations will affect the operating and maintenance plan or closure plan, operators should check those boxes in section 9 and provide updated plans or plan addendums as attachments to the C-147.

- Enduring Resources will continue to operate, maintain, and close the WLU 2309-24N 3RF-29 in compliance with 19.15.34 NMAC, to include but not limited to: detailed inspection records, removal of trash/oil from containment, and monthly C-148 reporting (even if there is zero activity).
- Water reuse and recycling from WLU 2309-24N 3RF-29 is limited to wells owned or operated by Enduring Resources OGRID 372286
- A minimum of 3-feet freeboard must always be maintained in the recycling containment during operations.

- Enduring Resources should notify the surface owner of the cessation of operations extension request by October 30, 2020
- Enduring Resources may request a variance for an additional extension to the determination of cessation of operations, which will be reviewed on a case-by-case basis and evaluated on their merit. Extensions are considered for a maximum length of six months. Additional requests must be submitted to OCD (email to ocd.enviro@state.nm.us) on a Form C-147 (long form) as an Extension request and should include a variance request and summary per 19.15.34.16 NMAC and the detailed inspection records for the prior three (3) months. The extension request should be submitted no later than December 1, 2020

Please keep a copy of this electronic communication for your files, as no paper copy of the approval will be delivered. The signed C-147 will be saved in 3RF-3 electronic file on the OCD website.

Cory Smith
Environmental Specialist
Oil Conservation Division
Energy, Minerals, & Natural Resources
1000 Rio Brazos, Aztec, NM 87410
(505)334-6178 ext 115
cory.smith@state.nm.us

From: James McDaniel <JMcDaniel@enduringresources.com>
Sent: Friday, July 31, 2020 8:42 AM
To: Enviro, OCD, EMNRD <OCD.Enviro@state.nm.us>; Smith, Cory, EMNRD <Cory.Smith@state.nm.us>
Cc: Heather Huntington <Hhuntington@enduringresources.com>; David Rogers <DRogers@enduringresources.com>
Subject: [EXT] RE: Enduring 3RF-29 Subsequent Determination of Cessation of Operation Variance Request

Please find attached a variance request for the WLU 2309 24N Facility, 3RF-29, with the required attachments. Please do not hesitate to contact me with questions regarding this extension request. Thank you.

James McDaniel
HSE Supervisor
Enduring Resources
CSP #30009
CHMM #15676
CIT #13805
Office: 505-636-9731
Cell: 505-444-3004
jmcdaniel@enduringresources.com

4.

Bonding:

- ☒ Covered under bonding pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC (**These containments are limited to only the wells owned or operated by the owners of the containment.**)
- ☐ Bonding in accordance with 19.15.34.15(A)(1). Amount of bond \$ _____ (**work on these facilities cannot commence until bonding amounts are approved**)
- ☐ Attach closure cost estimate and documentation on how the closure cost was calculated.

5.

Fencing:

- ☐ Four foot height, four strands of barbed wire evenly spaced between one and four feet
- ☒ Alternate. Please specify **8' Tall Chain Link Fencing**

6.

Signs:

- ☐ 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers
- ☒ Signed in compliance with 19.15.16.8 NMAC

7.

Variances:

Justifications and/or demonstrations that the proposed variance will afford reasonable protection against contamination of fresh water, human health, and the environment.

Check the below box only if a variance is requested:

- ☐ Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. If a Variance is requested, include the variance information on a separate page and attach it to the C-147 as part of the application.
- If a Variance is requested, it must be approved prior to implementation.**

8.

Siting Criteria for Recycling Containment

Instructions: The applicant must provide attachments that demonstrate compliance for each siting criteria below as part of the application. Potential examples of the siting attachment source material are provided below under each criteria.

General siting**Ground water is less than 50 feet below the bottom of the Recycling Containment.**

NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells

☐ Yes ☒ No
☐ NA

Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended.

☐ Yes ☒ No
☐ NA

- Written confirmation or verification from the municipality; written approval obtained from the municipality

Within the area overlying a subsurface mine.

☐ Yes ☒ No

- Written confirmation or verification or map from the NM EMNRD-Mining and Minerals Division

Within an unstable area.

☐ Yes ☒ No

- Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; topographic map

Within a 100-year floodplain. FEMA map

☐ Yes ☒ No

Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).

☐ Yes ☒ No

- Topographic map; visual inspection (certification) of the proposed site

Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.

☐ Yes ☒ No

- Visual inspection (certification) of the proposed site; aerial photo; satellite image

Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application.

☐ Yes ☒ No

- NM Office of the State Engineer - iWATERS database search; visual inspection (certification) of the proposed site

Within 500 feet of a wetland.

☐ Yes ☒ No

- US Fish and Wildlife Wetland Identification map; topographic map; visual inspection (certification) of the proposed site

9.

Recycling Facility and/or Containment Checklist:*Instructions: Each of the following items must be attached to the application. Indicate, by a check mark in the box, that the documents are attached.*

- ☐ Design Plan - based upon the appropriate requirements.
☐ Operating and Maintenance Plan - based upon the appropriate requirements.
☐ Closure Plan - based upon the appropriate requirements.
☐ Site Specific Groundwater Data -
☐ Siting Criteria Compliance Demonstrations --
☒ **Certify that notice of the C-147 (only) has been sent to the surface owner(s)**

10.

Operator Application Certification:

I hereby certify that the information and attachments submitted with this application are true, accurate and complete to the best of my knowledge and belief.

Name (Print): James McDanielTitle: HSE SupervisorSignature: Date: 7/31/2020e-mail address: jmcDaniel@enduringresources.comTelephone: 505-636-9731

11.

OCD Representative Signature: Approval Date: 9/30/2020Title: Environmental SpecialistOCD Permit Number: 3RF-29☐ OCD Conditions☒ Additional OCD Conditions on Attachment Emailed and Attached

REQUEST FOR EXTENSION

Cory Smith
New Mexico Oil Conservation Division
Aztec Office
1000 Rio Brazos Rd.
Aztec, NM 87410

Re: Variance Request for WLU 2309 24N – 3RF-29

Enduring Resources is requesting variance on the cessation of operation closure requirements in 19.15.31.13 NMAC based on the current climate surrounding the COVID-19 pandemic regarding the WLU 2309 24N Recycling Facility, 3RF-29. The Pandemic has reduced our ability to organize work, receive products and equipment, and receive approvals for activities. Due to these difficulties, Enduring would like to request an extension on the cessation closure date requirements for the WLU 2309 24N Facility. Based on the date of last use of water recycled for beneficial use from the facility of February 29, 2020, the cessation closure date of the site would be August 29, 2020. Enduring would like to request a six-month extension on the August 29, 2020 required closure date to March 1, 2021

Sincerely,



James McDaniel

HSE Supervisor

Enduring Resources, San Juan Operations

ATTACHMENTS:

Form C-147

Weekly Inspection Summary

Weekly Inspections (3 Months)

Laboratory Analysis

Comparison Table

WEEKLY INSPECTION SUMMARY

5/4/2020

- WL @ 16' in Pond
- 3.6" of rainwater in ULD, 3.6" of rainwater water in LLD
- Water unable to be removed. Pumps turned on but no water came to surface.
- Some oil sheen noted on pond, but was removed the next day.

5/11/2020

- WL @ 16' in Pond
- 3.6" of rainwater in ULD, 4.8" of rainwater water in LLD
- Water unable to be removed. Pumps turned on but no water came to surface.

5/20/2020

- WL @ 16' in Pond
- 6" of rainwater in ULD, 7.2" of rainwater water in LLD
- Diaphragm pump used to attempt to pump water from leak detection. No water was able to be recovered.

5/28/2020

- WL @ 15' in Pond
- 7.2" of rainwater in ULD, 6" of rainwater water in LLD
- 2" submersible pump rented to run into leak detection. Unable to get pump deep enough to pump out water from 2" leak detection.

6/1/2020

- WL @ 16' in Pond
- 6" of rainwater in ULD, 6" of rainwater water in LLD
- Unable to remove water from leak detection with pumps installed in leak detection

6/10/2020

- WL @ 16.5' in Pond
- 6" of rainwater in ULD, 7.2" of rainwater water in LLD
- Unable to remove water from leak detection with pumps installed in leak detection

6/16/2020

- WL @ 17' in Pond
- 6" of rainwater in ULD, 7.2" of rainwater water in LLD
- Unable to remove water from leak detection with pumps installed in leak detection
- Small spot of oil seen on pond. Reported to facilities to remove. Oil was removed the next day.

6/23/2020

- WL @ 17' in Pond
- 6.6" of rainwater in ULD, 7.2" of rainwater water in LLD
- Unable to remove water from leak detection with pumps installed in leak detection. Both pumps ran for several minutes, but no water came to surface.

6/30/2020

- WL @ 18' in Pond
- 7.2" of rainwater in ULD, 8.4" of rainwater water in LLD
- Unable to remove water from leak detection with pumps installed in leak detection. Both pumps ran for several minutes, but no water came to surface.
- Turned in ticket to I&E to check pumps to ensure they are working.

7/10/2020

- WL @ 18.5' in Pond
- 9" of rainwater in ULD, 8.4" of rainwater water in LLD
- Unable to remove water from leak detection with pumps installed in leak detection. Both pumps ran for several minutes, but no water came to surface. I&E coming to check pumps today.
- Small amount of muck floating in corner of pond. Facilities notified, and muck removed.

7/17/2020

- WL @ 19' in Pond
- 8.04" of rainwater in ULD, 9" of rainwater water in LLD
- Both submersible pumps removed and checked. Both in working order.
- Once pumps were removed, a 2" submersible pump was ran into the 6" leak detection for both the upper and lower leak detection.
- Approximately 15 gallons of water was removed from both the lower and upper leak detection.
- Samples of the water in the upper and lower leak detection were collected, as well as a sample from the pond water for comparison. The results of this sample analysis is included as **Laboratory Analysis**, and is detailed on a **Sample Comparison Table**.
- Sample results appear to indicate that water in Leak Detection is not produced water from the pond.
- After pumping, water levels were 2.4" in the ULD, and 1.8" in LLD.

7/23/2020

- WL @ 19.5' in Pond
- 2.64" of rainwater in ULD, 1.56" of rainwater water in LLD
- No rebound of water in leak detection after water was removed last week.
- Too little water to remove from leak detection.

7/30/2020

- WL @ 20' in Pond
- 3.6" of rainwater in ULD, 2.4" of rainwater water in LLD
- Too little water to remove
- Pond water level nearly at capacity.

WLU 2309 24N Pond Leak Detection Water Comparision

Sample Description	Date	EC	TDS	pH	Alkalinity	Calcium	Iron	Magnesium	Potassium	Sodium	Flouride	Chloride	Nitrite-N	Nitrate-N	Phosphate	Sulfate
Upper Leak Detection	7/17/2020	7,240	4,380	8.24	454	41.3	ND	12.6	10.3	1,570	ND	1,870	ND	ND	ND	555
Pond Water	7/17/2020	58,200	36,600	7.82	782	314	ND	82.2	88.2	15,200	ND	22,400	ND	ND	ND	357
Lower Leak Detection	7/17/2020	25,600	16,600	7.96	376	263	ND	64.6	35.3	6,480	ND	6,970	ND	ND	ND	3,600

Analytical Report

Report Summary

Client: Enduring Resources, LLC

Samples Received: 7/17/2020

Job Number: 17065-0017

Work Order: P007041

Project Name/Location: WLU 2309 24N

Report Reviewed By:



Date: 7/24/20

Walter Hinchman, Laboratory Director



Envirotech Inc. certifies the test results meet all requirements of TNI unless footnoted otherwise.
Statement of Data Authenticity: Envirotech, Inc. attests the data reported has not been altered in any way.
Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.
Envirotech, Inc. holds the Utah TNI certification NM009792018-1 for the data reported.
Envirotech, Inc. holds the Texas TNI certification T104704557-19-2 for the data reported.



Enduring Resources, LLC
511 16th Street, Suite 700
Denver CO, 80202

Project Name: WLU 2309 24N
Project Number: 17065-0017
Project Manager: James McDaniel

Reported:
07/24/20 13:29

Sample Summary

Client Sample ID	Lab Sample ID	Matrix	Sampled	Received	Container
Upper Leak Detection	P007041-01A	Aqueous	07/17/20	07/17/20	Poly 500mL
Pond Water	P007041-02A	Aqueous	07/17/20	07/17/20	Poly 500mL
Lower Leak Detection	P007041-03A	Aqueous	07/17/20	07/17/20	Poly 500mL

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

Enduring Resources, LLC
511 16th Street, Suite 700
Denver CO, 80202

Project Name: WLU 2309 24N
Project Number: 17065-0017
Project Manager: James McDaniel

Reported:
07/24/20 13:29

**Upper Leak Detection
P007041-01 (Water)**

Analyte	Result	Reporting Limit	Dilution	Prepared	Analyzed	Notes
Wet Chem/Gravimetric by SM2540C	mg/L	mg/L				Batch: 2029024
Total Dissolved Solids	4380	25.0	1	07/17/20	07/21/20	
Wet Chemistry by 9040C/4500H+B	pH Units	pH Units				Batch: 2030027
pH @25°C	8.24		1	07/24/20 07:13	07/24/20 08:37	H5
Wet Chemistry by SM2320B	mg/L	mg/L				Batch: 2030031
Total Alkalinity (as CaCO ₃ at pH 4.5)	454	10.0	1	07/24/20	07/24/20	
Wet Chemistry by 9050A/2510B	uS/cm	uS/cm				Batch: 2030028
Specific Conductance (@ 25 C)	7240	10.0	1	07/24/20	07/24/20	
Dissolved Metals by EPA 6010C	mg/L	mg/L				Batch: 2030011
Calcium	41.3	10.0	10	07/21/20	07/21/20	
Iron	ND	20.0	10	07/21/20	07/21/20	
Magnesium	12.6	10.0	10	07/21/20	07/21/20	
Potassium	10.3	10.0	10	07/21/20	07/21/20	
Sodium	1570	100	50	07/21/20	07/21/20	
Sodium Absorption Ratio	54.9		1	07/22/20	07/22/20	
Anions by EPA 300.0/9056A	mg/L	mg/L				Batch: 2029025
Fluoride	ND	2.50	10	07/17/20	07/20/20	
Chloride	1870	20.0	10	07/17/20	07/20/20	
Nitrite-N	ND	2.50	10	07/17/20 14:42	07/20/20 13:50	H4
Nitrate-N	ND	2.50	10	07/17/20 14:42	07/20/20 13:50	H4
o-Phosphate-P	ND	2.50	10	07/17/20 14:42	07/20/20 13:50	H4
Sulfate	555	20.0	10	07/17/20	07/20/20	

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

Enduring Resources, LLC
 511 16th Street, Suite 700
 Denver CO, 80202

 Project Name: WLU 2309 24N
 Project Number: 17065-0017
 Project Manager: James McDaniel

Reported:
 07/24/20 13:29

Pond Water
P007041-02 (Water)

Analyte	Result	Reporting Limit	Dilution	Prepared	Analyzed	Notes
Wet Chem/Gravimetric by SM2540C						
	mg/L	mg/L				Batch: 2029024
Total Dissolved Solids	36600	200	1	07/17/20	07/21/20	
Wet Chemistry by 9040C/4500H+B						
	pH Units	pH Units				Batch: 2030027
pH @25°C	7.82		1	07/24/20 07:13	07/24/20 08:37	H5
Wet Chemistry by SM2320B						
	mg/L	mg/L				Batch: 2030031
Total Alkalinity (as CaCO ₃ at pH 4.5)	782	10.0	1	07/24/20	07/24/20	
Wet Chemistry by 9050A/2510B						
	uS/cm	uS/cm				Batch: 2030028
Specific Conductance (@ 25 C)	58200	10.0	1	07/24/20	07/24/20	
Dissolved Metals by EPA 6010C						
	mg/L	mg/L				Batch: 2030011
Calcium	314	50.0	50	07/21/20	07/21/20	
Iron	ND	100	50	07/21/20	07/21/20	
Magnesium	82.2	50.0	50	07/21/20	07/21/20	
Potassium	88.2	50.0	50	07/21/20	07/21/20	
Sodium	15200	1000	500	07/21/20	07/21/20	
Sodium Absorption Ratio	197		1	07/22/20	07/22/20	
Anions by EPA 300.0/9056A						
	mg/L	mg/L				Batch: 2029025
Fluoride	ND	25.0	100	07/17/20	07/20/20	
Chloride	22400	200	100	07/17/20	07/20/20	
Nitrite-N	ND	25.0	100	07/17/20 14:42	07/20/20 14:13	H4
Nitrate-N	ND	25.0	100	07/17/20 14:42	07/20/20 14:13	H4
o-Phosphate-P	ND	25.0	100	07/17/20 14:42	07/20/20 14:13	H4
Sulfate	357	200	100	07/17/20	07/20/20	

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

Enduring Resources, LLC
511 16th Street, Suite 700
Denver CO, 80202

Project Name: WLU 2309 24N
Project Number: 17065-0017
Project Manager: James McDaniel

Reported:
07/24/20 13:29

Lower Leak Detection
P007041-03 (Water)

Analyte	Result	Reporting Limit	Dilution	Prepared	Analyzed	Notes
Wet Chem/Gravimetric by SM2540C	mg/L	mg/L				Batch: 2029024
Total Dissolved Solids	16600	100	1	07/17/20	07/21/20	
Wet Chemistry by 9040C/4500H+B	pH Units	pH Units				Batch: 2030027
pH @25°C	7.96		1	07/24/20 07:13	07/24/20 08:37	H5
Wet Chemistry by SM2320B	mg/L	mg/L				Batch: 2030031
Total Alkalinity (as CaCO3 at pH 4.5)	376	10.0	1	07/24/20	07/24/20	
Wet Chemistry by 9050A/2510B	uS/cm	uS/cm				Batch: 2030028
Specific Conductance (@ 25 C)	25600	10.0	1	07/24/20	07/24/20	
Dissolved Metals by EPA 6010C	mg/L	mg/L				Batch: 2030011
Calcium	263	10.0	10	07/21/20	07/21/20	
Iron	ND	20.0	10	07/21/20	07/21/20	
Magnesium	64.6	10.0	10	07/21/20	07/21/20	
Potassium	35.3	10.0	10	07/21/20	07/21/20	
Sodium	6480	100	50	07/21/20	07/21/20	
Sodium Absorption Ratio	92.8		1	07/22/20	07/22/20	
Anions by EPA 300.0/9056A	mg/L	mg/L				Batch: 2029025
Fluoride	ND	12.5	50	07/17/20	07/20/20	
Chloride	6970	100	50	07/17/20	07/20/20	
Nitrite-N	ND	12.5	50	07/17/20 14:42	07/20/20 14:37	H4
Nitrate-N	ND	12.5	50	07/17/20 14:42	07/20/20 14:37	H4
o-Phosphate-P	ND	12.5	50	07/17/20 14:42	07/20/20 14:37	H4
Sulfate	3600	100	50	07/17/20	07/20/20	

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

Enduring Resources, LLC
 511 16th Street, Suite 700
 Denver CO, 80202

Project Name: WLU 2309 24N
 Project Number: 17065-0017
 Project Manager: James McDaniel

Reported:
 07/24/20 13:29

Wet Chem/Gravimetric by SM2540C - Quality Control

Analyte	Result mg/L	Reporting Limit mg/L	Spike Level mg/L	Source Result mg/L	REC % %	REC Limits %	RPD % %	RPD Limit %	Notes
---------	----------------	----------------------------	------------------------	--------------------------	---------------	--------------------	---------------	-------------------	-------

Blank (2029024-BLK1)

Prepared: 07/17/20 1 Analyzed: 07/21/20 1

Total Dissolved Solids ND 10.0

LCS (2029024-BS1)

Prepared: 07/17/20 1 Analyzed: 07/21/20 1

Total Dissolved Solids 99.0 10.0 100 99.0 55-134

Duplicate (2029024-DUP1)

Source: P007030-01

Prepared: 07/17/20 1 Analyzed: 07/21/20 1

Total Dissolved Solids 462 10.0 467 1.08 5

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

Enduring Resources, LLC
511 16th Street, Suite 700
Denver CO, 80202

Project Name: WLU 2309 24N
Project Number: 17065-0017
Project Manager: James McDaniel

Reported:
07/24/20 13:29

Wet Chemistry by 9040C/4500H+B - Quality Control

Analyte	Result	Reporting Limit	Spike Level	Source Result	REC	REC Limits	RPD	RPD Limit	Notes
	pH Units	pH Units	pH Units	pH Units	%	%	%	%	

LCS (2030027-BS1)

Prepared & Analyzed: 07/24/20 0

pH	8.00	8.00	100	98.75-101.25
----	------	------	-----	--------------

Duplicate (2030027-DUP1)

Source: P007057-01 Prepared & Analyzed: 07/24/20 0

pH	8.37	8.07	3.65	20
----	------	------	------	----

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

Enduring Resources, LLC
511 16th Street, Suite 700
Denver CO, 80202

Project Name: WLU 2309 24N
Project Number: 17065-0017
Project Manager: James McDaniel

Reported:
07/24/20 13:29

Wet Chemistry by SM2320B - Quality Control

Analyte	Result mg/L	Reporting Limit mg/L	Spike Level mg/L	Source Result mg/L	REC % %	REC Limits %	RPD % %	RPD Limit %	Notes
---------	----------------	----------------------------	------------------------	--------------------------	---------------	--------------------	---------------	-------------------	-------

LCS (2030031-BS1)

Prepared & Analyzed: 07/24/20 1

Total Alkalinity (as CaCO ₃ at pH 4.5)	262	10.0	250	105	70-130
---	-----	------	-----	-----	--------

Duplicate (2030031-DUP1)

Source: P007041-01 Prepared & Analyzed: 07/24/20 1

Total Alkalinity (as CaCO ₃ at pH 4.5)	446	10.0	454	1.78	20
---	-----	------	-----	------	----

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

Enduring Resources, LLC
 511 16th Street, Suite 700
 Denver CO, 80202

Project Name: WLU 2309 24N
 Project Number: 17065-0017
 Project Manager: James McDaniel

Reported:
 07/24/20 13:29

Wet Chemistry by 9050A/2510B - Quality Control

Analyte	Result	Reporting Limit	Spike Level	Source Result	REC	REC Limits	RPD	RPD Limit	Notes
	uS/cm	uS/cm	uS/cm	uS/cm	%	%	%	%	

Blank (2030028-BLK1)

Prepared: 07/24/20 0 Analyzed: 07/24/20 1

Specific Conductance (@ 25 C) ND 10.0

LCS (2030028-BS1)

Prepared: 07/24/20 0 Analyzed: 07/24/20 1

Specific Conductance (@ 25 C) 1430 10.0 1410 101 98-102

Duplicate (2030028-DUP1)

Source: P007057-01 Prepared: 07/24/20 0 Analyzed: 07/24/20 1

Specific Conductance (@ 25 C) 1270 10.0 1320 4.48 20

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

Enduring Resources, LLC	Project Name:	WLU 2309 24N	Reported: 07/24/20 13:29
511 16th Street, Suite 700	Project Number:	17065-0017	
Denver CO, 80202	Project Manager:	James McDaniel	

Dissolved Metals by EPA 6010C - Quality Control

Analyte	Result	Reporting Limit	Spike Level	Source Result	REC	REC Limits	RPD	RPD Limit	Notes
	mg/L	mg/L	mg/L	mg/L	%	%	%	%	

Blank (2030011-BLK1)

Prepared & Analyzed: 07/21/20 1

Calcium	ND	1.00
Iron	ND	2.00
Magnesium	ND	1.00
Potassium	ND	1.00
Sodium	ND	2.00

LCS (2030011-BS1)

Prepared & Analyzed: 07/21/20 1

Calcium	51.4	1.00	50.0	103	80-120
Iron	103	2.00	100	103	80-120
Magnesium	50.3	1.00	50.0	101	80-120
Potassium	5.07	1.00	5.00	101	80-120
Sodium	18.4	2.00	20.0	92.2	80-120

Matrix Spike (2030011-MS1)

Source: P007050-02

Prepared & Analyzed: 07/21/20 1

Calcium	338	1.00	50.0	283	109	75-125
Iron	103	2.00	100	ND	103	75-125
Magnesium	113	1.00	50.0	65.8	93.6	75-125
Potassium	53.2	20.0	5.00	46.6	132	75-125
Sodium	2770	40.0	20.0	2740	180	75-125

M2

M2

Matrix Spike Dup (2030011-MSD1)

Source: P007050-02

Prepared & Analyzed: 07/21/20 1

Calcium	334	1.00	50.0	283	102	75-125	1.01	20
Iron	102	2.00	100	ND	102	75-125	1.18	20
Magnesium	115	1.00	50.0	65.8	98.4	75-125	2.11	20
Potassium	54.1	20.0	5.00	46.6	150	75-125	1.72	20
Sodium	2830	40.0	20.0	2740	480	75-125	2.14	20

M2

M2

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

Enduring Resources, LLC
 511 16th Street, Suite 700
 Denver CO, 80202

 Project Name: WLU 2309 24N
 Project Number: 17065-0017
 Project Manager: James McDaniel

 Reported:
 07/24/20 13:29

Anions by EPA 300.0/9056A - Quality Control

Analyte	Result	Reporting Limit	Spike Level	Source Result	REC	REC Limits	RPD	RPD Limit	Notes
	mg/L	mg/L	mg/L	mg/L	%	%	%	%	

Blank (2029025-BLK1)

Prepared: 07/17/20 1 Analyzed: 07/20/20 1

Fluoride	ND	0.250							
Chloride	ND	2.00							
Nitrite-N	ND	0.250							
Nitrate-N	ND	0.250							
o-Phosphate-P	ND	0.250							
Sulfate	ND	2.00							

LCS (2029025-BS1)

Prepared: 07/17/20 1 Analyzed: 07/20/20 1

Fluoride	2.58	0.250	2.50		103	90-110			
Chloride	24.8	2.00	25.0		99.2	90-110			
Nitrite-N	2.51	0.250	2.50		100	90-110			
Nitrate-N	2.56	0.250	2.50		102	90-110			
o-Phosphate-P	12.8	0.250	12.5		102	90-110			
Sulfate	24.7	2.00	25.0		98.9	90-110			

LCS Dup (2029025-BSD1)

Prepared: 07/17/20 1 Analyzed: 07/20/20 1

Fluoride	2.59	0.250	2.50		104	90-110	0.387	20	
Chloride	24.9	2.00	25.0		99.4	90-110	0.222	20	
Nitrite-N	2.53	0.250	2.50		101	90-110	0.754	20	
Nitrate-N	2.57	0.250	2.50		103	90-110	0.273	20	
o-Phosphate-P	12.8	0.250	12.5		102	90-110	0.180	20	
Sulfate	24.8	2.00	25.0		99.0	90-110	0.158	20	

QC Summary Report Comment:

Calculations are based off of the raw (non-rounded) data. However, for reporting purposes all QC data is rounded to three significant figures. Therefore, hand calculated values may differ slightly.

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

Enduring Resources, LLC
511 16th Street, Suite 700
Denver CO, 80202

Project Name: WLU 2309 24N
Project Number: 17065-0017
Project Manager: James McDaniel

Reported:
07/24/20 13:29

Notes and Definitions

- M2 Matrix spike recovery was outside quality control limits. The associated LCS spike recovery was acceptable.
- H5 pH is specified to be performed in the field within 15 minutes of sampling. The sample was performed as quickly as possible.
- H4 Initial analysis was within holding time. Re-analysis was past holding time.
- ND Analyte NOT DETECTED at or above the reporting limit
- NR Not Reported
- RPD Relative Percent Difference
- ** Methods marked with ** are non-accredited methods.

Soil data is reported on an "as received" weight basis, unless reported otherwise.

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

Project Information

Chain of Custody

Page 1 of 1

[illegible]



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Recycling Containment: W20 2309 24N Permit Number: 3RB-29
Qtr./Qtr. Or Lot: SE1/4, SW1/4, SW1/4 Section: 24 Township: 23N Range: 9W
Date of Inspection: 5-4-20 Inspector: Chad Sney
Time arrived on location: 11:40 am Time left location: 12:10 pm
General Comments: Oil being removed

General Site Condition	Yes	No ¹	N/A	Comments
Containment currently contains fluids	✓			16'
Fencing is in good condition and functional	✓			
Gates are closed and locked ²	✓			
Signage visible & compliant	✓			
No signs of surface water run on	✓			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below. ² only applicable if site is unattended by authorized personnel.				
Corrective Action				Personnel
				Date

Containment Compliance	Yes	No ¹	N/A	Comments
Containment is free of any visible layer of oil sheen	✓			being removed
Containment has at least three feet of freeboard	✓			
Injection or withdrawal of fluids to/from containment is accomplished through a header, diverter or other hardware	✓			
Oil absorbent booms or other device onsite, in good condition, and available for use for unanticipated release	✓			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action				Personnel
				Date



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Leak Detection System	Yes	No ¹	N/A	Comments
Site is free from evidence of leaks, spills or releases	/			
Liner above waterline shows no evidence of damage	/			
Leak detection system was checked and shows no sign of leak via fluid present	/			Upper @ 98.7 Lower @ 94.7
If fluid is present in leak detection system, it was removed and volume recorded				UPPER: Pond vertical depth (ft): <u>23</u> Leak detection diagonal depth (ft): <u>99</u> Pump run time (hours): <u> </u> Volume removed (gallons): <u> </u> LOWER: Pond vertical depth (ft): <u>23</u> Leak detection diagonal depth (ft): <u>95</u> Pump run time (hours): <u> </u> Volume removed (gallons): <u> </u>
Fluid was not present within leak detection two consecutive days in a row	/			
If fluid is present two consecutive days in a row, it has to be reported to HSE & Regulatory			/	
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action				Personnel Date



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Wildlife/Bird Deterrent System	Yes	No ¹	N/A	Comments
Audio deterrent system in working order and operating	/			
All visual deterrents in good working order and operating	/			
Any repairs or replacements of deterrents from previous inspections have been completed ²	/			
Entire location (perimeter and interior) was walked and inspected for evidence of bird/wildlife mortality or injury	/			
If evidence of bird/wildlife mortality or injury is identified it was immediately reported to HSE & Regulatory			/	
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below. ² Note personnel that completed work and date completed in the Corrective Action section below.				
Corrective Action	Personnel			Date



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name W10 2309 24N Permit Number 3RF-29
Section 24 Township 23N Range 9W County San Juan State NM
Time Inspection Began 12:00pm Time Inspection Ended 12:50pm
Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 16

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)		<u>94.1</u>		
Depth to Water in ULD (ft)		<u>98.8</u>		
Height of Water in ULD				
Gallons of Water Removed		<u>—</u>		

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)		<u>95.7</u>		
Depth to Water in LLD (ft)		<u>95.3</u>		
Height of Water in LLD				
Gallons of Water Removed		<u>—</u>		

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Not enough water to pump out

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Michael S. V.

Date 5-11-20

Name (Signature)

[Signature]

Company

Enduring Resources



Enduring Resources, LLC Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309 24N Permit Number 3RF-29
Section 24 Township 23N Range 9W County San Juan State NM
Time Inspection Began 10:20 am Time Inspection Ended 12:25 pm
Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 16'

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

Need to add more locks on walk through gates.

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header <u>None @ this time</u>	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)		<u>99.1</u>		
Depth to Water in ULD (ft)		<u>98.6</u>		
Height of Water in ULD		<u>6 1/2"</u>		
Gallons of Water Removed		<u>—</u>		

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)		<u>95.7</u>		
Depth to Water in LLD (ft)		<u>95.1</u>		
Height of Water in LLD		<u>6 1/2"</u>		
Gallons of Water Removed		<u>—</u>		

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Tried Pumping out with diaphragm pump and was not able to remove any water.

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

Added Bird Balls

COMMENTS

Name (Print) Chad Snel

Date 5-20-20

Name (Signature) [Signature]

Company Enduring Resources



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLV 2309 24N Permit Number 3RF-29
Section 24 Township 23N Range 9W County San Juan State NM
Time Inspection Began 11:15 am Time Inspection Ended 1:00 pm
Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 15

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header <u>None @ this time</u>	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)		<u>98.1</u>		
Depth to Water in ULD (ft)		<u>95.5</u>		
Height of Water in ULD				
Gallons of Water Removed				

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)		<u>95.7</u>		
Depth to Water in LLD (ft)		<u>95.2</u>		
Height of Water in LLD				
Gallons of Water Removed				

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Rented man soon pump (2 inch sub) from Enviro tech to remove water.
Got pump to 91 ft and wouldn't go any deeper.

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Chad Snell

Date 5-26-20

Name (Signature) [Signature]

Company Enduring Resources



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309 24N Permit Number 3RF-29
Section 24 Township 23N Range 9W County San Juan State NM
Time Inspection Began 11:50 am Time Inspection Ended 12:35 pm
Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 16

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header <u>None @ this time</u>	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)		<u>99.1</u>		
Depth to Water in ULD (ft)		<u>99.6</u>		
Height of Water in ULD				
Gallons of Water Removed		<u>—</u>		

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)		<u>95.7</u>		
Depth to Water in LLD (ft)		<u>95.2</u>		
Height of Water in LLD				
Gallons of Water Removed		<u>—</u>		

If leak detection contained liquid, was it removed?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Not enough to Remove.

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

added Bird Bells.

COMMENTS

Name (Print) Chad Smith

Date 6-1-20

Name (Signature) [Signature]

Company Enduring Resources



Enduring Resources, LLC Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name W2V 2309 24N Permit Number 321-29
Section 24 Township 23N Range 9W County San Juan State NM
Time Inspection Began 12:15pm Time Inspection Ended 2:00pm
Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 16.5

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header <u>water going in</u>	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)		<u>94.1</u>		
Depth to Water in ULD (ft)		<u>98.6</u>		
Height of Water in ULD		<u>---</u>		
Gallons of Water Removed		<u>---</u>		

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)		<u>95.7</u>		
Depth to Water in LLD (ft)		<u>95.1</u>		
Height of Water in LLD		<u>---</u>		
Gallons of Water Removed		<u>---</u>		

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

No way of Removing 6" of water.

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

Added Bird Bells

COMMENTS

Name (Print) Chad Smith

Date 6-10-20

Name (Signature) [Signature]

Company Enduring Resources



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309 - 24N Permit Number 3RF-29
Section 24 Township 23N Range 9W County San Juan State NM
Time Inspection Began 9:30 am Time Inspection Ended 10:55 am
Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 17

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)	<u>99.2</u>			
Depth to Water in ULD (ft)	<u>78.7</u>			
Height of Water in ULD				
Gallons of Water Removed				

Lower Leak Detection (LLD)

Water Present in LLD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<u>95.7</u>			
Depth to Water in LLD (ft)	<u>95.1</u>			
Height of Water in LLD				
Gallons of Water Removed				

If leak detection contained liquid, was it removed?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Some oil on pond will get with Facilities.

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Chad Smith Date 6-16-20

Name (Signature) [Signature] Company Enduring Resources



Enduring Resources, LLC Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309 24N Permit Number 3RF-29
Section 24 Township 23N Range 9W County San Juan State NM
Time Inspection Began 11:50 AM Time Inspection Ended 1:00 PM
Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 17

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)		<u>99.2</u>		
Depth to Water in ULD (ft)		<u>98.65</u>		
Height of Water in ULD		<u>0.55'</u>		
Gallons of Water Removed		<u>—</u>		

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)		<u>95.85</u>		
Depth to Water in LLD (ft)		<u>95.25</u>		
Height of Water in LLD		<u>0.6'</u>		
Gallons of Water Removed		<u>—</u>		

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Pumps turned on, but no water was removed

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

More Bird Balls needed. On order

COMMENTS

Name (Print) James McDaniel

Date 6/23/20

Name (Signature) [Signature]

Company Enduring



Enduring Resources, LLC Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309 24N Permit Number 3RF-29
Section 24 Township 23N Range 9W County San Juan State NM
Time Inspection Began 10:05 Time Inspection Ended 11:27
Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 18

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)		<u>99.2</u>		
Depth to Water in ULD (ft)		<u>98.6</u>		
Height of Water in ULD				
Gallons of Water Removed				

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)		<u>95.8</u>		
Depth to Water in LLD (ft)		<u>95.1</u>		
Height of Water in LLD				
Gallons of Water Removed				

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

*Pumps turned on - unable to pump water.
Turned in ticket to I&E for troubleshooting*

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

**3 Bird balls added*

Name (Print) James McDaniel

Date 6/30/2020

Name (Signature) [Signature]

Company Enduring



Enduring Resources, LLC Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name West Lybrook 2309 24N Permit Number 3RF-29
Section 24 Township 23N Range 9W County San Juan State NM
Time Inspection Began 8:30 Time Inspection Ended 9:25
Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 18.5

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)		<u>49.2</u>		
Depth to Water in ULD (ft)		<u>48.45</u>		
Height of Water in ULD		<u>0.75</u>		
Gallons of Water Removed		<u>—</u>		

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)		<u>45.25</u>		
Depth to Water in LLD (ft)		<u>45.15</u>		
Height of Water in LLD		<u>0.1</u>		
Gallons of Water Removed		<u>—</u>		

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Turned on pumps but no water removed.
I/E coming to trouble shoot pumps today.

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

small amount of oil/muck in corner. Doug notified.

Name (Print)

James McDaniel

Date

7/10/20

Name (Signature)

[Signature]

Company

Enduring



Enduring Resources, LLC Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309 24N Permit Number 3RF-29
 Section 24 Township 23N Range 9W County Sand Juvn State NM
 Time Inspection Began 942 Time Inspection Ended 1135
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 19

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 95.8
 Depth to Water in ULD (ft) 45.13
 Height of Water in ULD 0.67'
 Gallons of Water Removed 15

Lower Leak Detection (LLD)

Water Present in LLD? NO YES ☒ NO ☐
 Total Depth of LLD (ft) 99.2
 Depth to Water in LLD (ft) 98.45
 Height of Water in LLD 0.75'
 Gallons of Water Removed 4015

If leak detection contained liquid, was it removed? YES ☒ NO ☐ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

*Samples collected from ULD, LLD, Pond
 ULD 95.6 after pumping
 LLD Pump out after was 99.05'

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print)

James McDaniel

Date

7/17/2020

Name (Signature)

[Signature]

Company

Enduring



Enduring Resources, LLC Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name West Lybrook Unit 2309 2N Permit Number SRF-29
Section 24 Township 23N Range 9W County San Juan State NM
Time Inspection Began 9:51 Time Inspection Ended 11:40
Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 19.5

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)		<u>99.2</u>		
Depth to Water in ULD (ft)		<u>98.98</u>		
Height of Water in ULD		<u>0.22</u>		
Gallons of Water Removed		<u>—</u>		

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)		<u>95.85</u>		
Depth to Water in LLD (ft)		<u>95.72</u>		
Height of Water in LLD		<u>0.13</u>		
Gallons of Water Removed		<u>—</u>		

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Too little water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) James McDaniel

Date 7/23/20

Name (Signature) [Signature]

Company Enduring



Enduring Resources, LLC Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name West Lybrook Unit 2309 24th Permit Number 3RF-29
 Section 24 Township 23N Range 9W County San Juan State NM
 Time Inspection Began 10/17 Time Inspection Ended 10/18
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 20

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

Pond nearly at capacity

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)	<u>99.2</u>			
Depth to Water in ULD (ft)	<u>98.9</u>			
Height of Water in ULD	<u>0.3</u>			
Gallons of Water Removed	<u>—</u>			

Lower Leak Detection (LLD)

Water Present in LLD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<u>95.82</u>			
Depth to Water in LLD (ft)	<u>95.62</u>			
Height of Water in LLD	<u>0.2</u>			
Gallons of Water Removed	<u>—</u>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Not enough water to remove

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) James McDaniel

Date 7/30/2020

Name (Signature) [Signature]

Company Enduring