

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 copy to
appropriate
District Office
and 1 copy to
the Santa Fe Office

(Revised 3/9/94)

PIT REMEDIATION AND CLOSURE REPORT

30-045-12174

Operator: ConocoPhillips

Telephone: (505) 599-3400


Address: 5525 US Hwy. 64, Farmington, NM 87401

Well Name: Farmington C Com 1

Location: Unit or Qtr/Qtr Sec: Unit L Sec 15 T 29N R 13W County San Juan, NM

Pit Type: Separator X Dehydrator X Other Excavation 1

Land Type: BLM , State , Fee Other Private



Pit Location: Pit dimensions: length 50', width 30', depth 7'
(Attach diagram)

Reference: wellhead X, other

Footage from reference: Approximately 55'

Direction from reference: Approximately 20 Degrees West of South

Depth To Ground Water (Vertical distance from contaminants to seasonal high water elevation of ground water.)	Less than 50 feet	Yes	(20 points)
	50 feet to 99 feet		(10 points)
	Greater than 100 feet		(0 points) <u>20</u>
Wellhead Protection Area: (Less than 200 feet from a private domestic water source, or; less than 1000 feet from all other water sources.)			NO (20 points) (0 points) <u>0</u>
Distance To Surface Water: (Horizontal distance to perennial lakes, ponds, rivers, streams, creeks, irrigation canals and ditches.)	Less than 200 feet		(20 points)
	200 feet to 1000 feet		(10 points)
	Greater than 1000 feet	Yes	(0 points) <u>0</u>

RANKING SCORE (TOTAL POINTS): 20

Date Remediation Started: 1997 Date completed 9/17/02

Remediation Method: Excavation X Approx. cubic yards 226 +

(Check all appropriate
sections.)

Landfarmed

Insitu Bioremediation

Other Disposed at Envirotech OCD landfarm

Remediation Location: Onsite _____ Offsite: X
(i.e. landfarmed onsite,
name and location of
offsite facility) Envirotech Landfarm #2

General Description of Remedial Action: The pit was excavated and approximately 226 cubic yards of contaminated soil was removed from the site, and disposed of properly. The excavation was backfilled with clean imported material. Monitoring wells were installed to monitor ground water quality. Refer to Conoco Annual Ground Water Report for 2002 for final ground water sample results.

Ground Water Encountered: No _____ Yes: X Depth: Approximately seven feet.

Final Pit:
Closure Sampling:
(if multiple samples,
attach sample results
and diagram of sample
locations and depths)

Sample location: Refer to Farmington C Com #1 Excavation Summary. On Site Technologies, 11/26/97 for soil sample results and ConocoPhillips Annual Groundwater Report for 2002 for ground water sample results..

Sample depth _____

Sample Date _____ Sample time _____

Sample Results

Benzene(ppm) _____

Total BTEX(ppm) _____

Field headspace(ppm) _____


Ground Water Sample: TPH _____

Yes X No _____ (If yes, attach sample results)


I hereby certify that the information above is true and complete to the best of my knowledge and belief.


Date: 2/26/03


Signature




Printed Name: Neal Goates
and Title: RM&R Site Manager



FARMINGTON "C" COM #1 Unit L, S15, T29W, R13W SAN JUAN BASIN, NM		SITE SKETCH	 ON SITE TECHNOLOGIES, LTD. P.O. BOX 2606, FARMINGTON, NM 87499 (505) 325-5667
		DRWN: 11-03-97	
		DRWN BY: MKL	
PROJECT NO: 4-1373			
FIGURE: A-1	FILE: 41303S4.CAD	PROJECT: SITE RECLAMATION	



FARMINGTON "C" COM #1 Unit L, S15, T29W, R13W SAN JUAN BASIN, NM		SITE SKETCH		 ON SITE TECHNOLOGIES, LTD. P.O. BOX 2606, FARMINGTON, NM 87499 (505) 325-5667
		DRWN: 11-03-97		
PROJECT NO: 4-1373		DRWN BY: MKL		
FIGURE: A-1	FILE: 41303S4.CAD	PROJECT: SITE RECLAMATION		