

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 copy to
appropriate
District Office
and 1 copy to
the Santa Fe Office

(Revised 3/9/94)

PIT REMEDIATION AND CLOSURE REPORT

30-045-12174

Operator: ConocoPhillips

Telephone: (505) 599-3400

Address: 5525 US Hwy. 64, Farmington, NM 87401

Well Name: Farmington C Com 1

Location: Unit or Qtr/Qtr Sec: Unit L Sec 15 T 29N R 13W County San Juan, NM

Pit Type: Separator _____ Dehydrator _____ Other Tank Drain Pit Excavation 3
Land Type: BLM _____, State _____, Fee _____ Other Private

Pit Location: Pit dimensions: length 40', width 25', depth 7'
(Attach diagram)

Reference: wellhead X, other _____

Footage from reference: Approximately 55'

Direction from reference: Approximately 45 Degrees East of North

Depth To Ground Water (Vertical distance from contaminants to seasonal high water elevation of ground water.)	Less than 50 feet Yes (20 points) 50 feet to 99 feet (10 points) Greater than 100 feet (0 points) <u>20</u>
Wellhead Protection Area: (Less than 200 feet from a private domestic water source, or; less than 1000 feet from all other water sources.)	NO (20 points) (0 points) <u>0</u>
Distance To Surface Water: (Horizontal distance to perennial lakes, ponds, rivers, streams, creeks, irrigation canals and ditches.)	Less than 200 feet (20 points) 200 feet to 1000 feet (10 points) Greater than 1000 feet Yes (0 points) <u>0</u>

RANKING SCORE (TOTAL POINTS): 20

Date Remediation Started: 1997 Date completed 9/17/02

Remediation Method: Excavation X Approx. cubic yards 179

(Check all appropriate
sections.)

Landfarmed _____

Insitu Bioremediation _____

Other Disposed at Envirotech OCD landfarm

Remediation Location: Onsite _____ Offsite: ☒
(i.e. landfarmed onsite,
name and location of
offsite facility) Envirotech Landfarm #2

General Description of Remedial Action: The tank drain pit was excavated and approximately 179^{gph} cubic yards of contaminated soil was removed from the site, and disposed of it properly. The excavation was backfilled with clean imported material. Monitoring wells were installed to monitor ground water quality. Refer to Conoco Annual Ground Water Report 2002 for ground water sample results

Ground Water Encountered: No _____ Yes: ☒ Depth: Approximately seven feet.

Final Pit:
Closure Sampling:
(if multiple samples,
attach sample results
and diagram of sample
locations and depths)

Sample location: Refer to Farmington C Com #1 Excavation Summary. (On Site Technologies, 11/26/97 for soil sample results. Refer to Conoco Annual Ground Water Report 2002 for ground water sample results

Sample depth _____

Sample Date _____ Sample time _____

Sample Results

Benzene(ppm) _____

Total BTEX(ppm) _____

Field headspace(ppm) _____

Ground Water Sample:


TPH _____

Yes ☒ No _____ (If yes, attach sample results)


I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Date: 2/26/03

Signature



Printed Name: Neal Goates
and Title: RM&R Site Manager



FARMINGTON "C" COM #1
Unit L, S15, T29W, R13W
SAN JUAN BASIN, NM

SITE SKETCH

DRWN: 11-03-97

DRWN BY: MKL

PROJECT: SITE RECLAMATION


PROJECT NO: 4-1373


FIGURE: A-1

FILE: 4130384.CAD

ON SITE TECHNOLOGIES, LTD.

P.O. BOX 2606, FARMINGTON, NM 87499
(505) 325-5667



FARMINGTON "C" COM #1 Unit L, S15, T29W, R13W SAN JUAN BASIN, NM		SITE SKETCH		 ON SITE TECHNOLOGIES, LTD. P.O. BOX 2606, FARMINGTON, NM 87499 (505) 325-5667
PROJECT NO: 4-1373		DRWN: 11-03-97		
FIGURE: A-1		DRWN BY: MKL		
FILE: 41303S4.CAD		PROJECT: SITE RECLAMATION		