Submit 3 Copies To Appropriate District	State of	f New Me	xico		Form C-	103
Office District I	Energy, Minerals	s and Natu	ral Resources		Revised March 25,	1999
1625 N. French Dr., Hobbs, NM 88240				WELL API NO.		
<u>District II</u> 811 South First, Artesia, NM 88210	OIL CONSER	VATION	DIVISION		-045-22748	
District III	1220 Sout	th St. Fran	icis Dr.	5. Indicate Type		i
1000 Rio Brazos Rd., Aztec, NM 87410		e, NM 87		STATE 6. State Oil & C	FEE Gas Lease No.	
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Suma 1	0, 1111 07	303	6. State Off & C	jas Lease No.	1
87505			£6780x		,	
	ICES AND REPORTS (		A CONTRACTOR	7. Lease Name of	r Unit Agreement Na	me:
(DO NOT USE THIS FORM FOR PROPODIFFERENT RESERVOIR. USE "APPLIED TO THE PROPORTION OF THE PROPORTION OF THE PROPORTION OF THE PROPERTY OF THE	OSALS TO DRILL OR TO DE	EPEN OR PLU	JG BACK TO A	<u>,                                    </u>		
PROPOSALS.)	ICATION FOR FERMIT (FO	KWI 6-101) FC	JAN 5003 =		Varren LS	
1. Type of Well:		T.	Contract (Children	•	Form 3160-5 Federal Le	ease
Oil Well Gas Well	X Other		NO.DW.	⊼ <b>§</b> F - 077123)		
2. Name of Operator		<u> </u>		2/ 2/8. Well No.	•••	
BP America Production Company	Attn: Mary Cor	lev	(8)	76. WEILING.	2 <b>A</b>	
3. Address of Operator	Atti. iliary ooi	, (c)	220 12217	9. Pool name or		
P.O. Box 3092 Houston, TX 77253		•	Cally Man	Blanco Mesaverde		
4. Well Location						
Unit LetterO	_800 feet from the	South lir	ne and1800fee	t from the East	line	į
			· · · · · · · · · · · · · · · · · · ·			
Section 12	Township 28N	Range		MPM San Juan	County	
	10. Elevation (Show					
	ğ	5753'		3.80		
	Appropriate Box to In	ndicate Na				
	NTENTION TO:		SUB	SEQUENT RE	PORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDO	N $\square$	REMEDIAL WOR	<	ALTERING CASIN	G □
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRI	LUNC ODNE	PLUG AND	
TEMPORARILY ABANDON	3 CHANGE PLANS	I	COMMENCE DRI	LLING OPNS. []	ABANDONMENT	
PULL OR ALTER CASING	MULTIPLE		CASING TEST AN	ID 🗆		
	COMPLETION		CEMENT JOB			
OTHER: Downhole Comming	lo.	X	OTHER:			
12. Describe proposed or comple				ivo nortinont datas	including actions to d	data
of starting any proposed work	Ned operations. (Clearly	state an per r Multiple (	Timent details, and g	ive perunent dates,	of proposed complet	date ion
or recompilation.	.). SEE ROLE 1103. PO	i widilipie C	ompletions. Attaci	i welloofe diagram	or proposed complet	1011
BP America Production Company r	equest permission to con	vert the sub	iect well from a dual	string to a single st	tring and commingle	
production downhole from the Blar						
•				- <b>p</b>		
The Blanco Mesaverde (72319) & th	e Blanco Pictured Cliffs (	(72359) Pool	s are Pre-Approved	<b>Pools for Downhole</b>	Commingling per	
NMOCD order R-11363. The worki	ng and overriding royalty	interest owr	ners in the proposed	commingled pools	are identical, therefore	e no
further notification of this application	on is required.					
<b>.</b>						
Production is proposed to be allocated and a	ated based on actual prod	uction from	both the Mesaverde	and Pictured Cliffs	Pools as reflected on	the
attached allocation chart.						
Commingling Production Downhole	s in the cubicat well from	tha nrancaa	d Doolo with not rod	uaa tha walua af tha	total remaining	
		ille propose	u roois with not rea	uce the value of the	total remaining	
UNCIVE	. ,, .					
I hereby certify that the information	on above is true and comp	olete to the	best of my knowled	ge and belief.		
SIGNATURE MAIN	lash.					
SIGNATURE // / // //		TITLE_SI	: Regulatory Analys		01/02/2003	
Type or print name Man Corlo	ey //		Tele	phone No. 281-36	6-4491	
(This space for State use)	(1/ 1		DEPUTY OR R CAC	IMPECTOD SUCT	38 JAN - 62	0 -
ADDDDOVED BY	+ Nearly	-TITLE	CND G Com	ned solver, MM.	39 AUN - 6.5	4003
APPPROVED BY		IIILE			DATE	
Conditions of approval, if any:	11 /				<del>-</del>	

## Warren LS #2A Commingling Procedure

dure:

- 1. Check anchors. MIRU workover rig.
- 2. Check and record tubing, casing, and bradenhead pressures.
- 3. Blow down wellhead. Kill with 2% KCL water ONLY if necessary.
- 4. Nipple down WH. NU BOPs.
- 5. TOH and LD 1-1/4" short string production tubing currently set at 2188'.
- 6. TOH with 2-3/8" long string production tubing currently set at 4740'.
- 7. Mill slip elements and retrieve 7" Baker Model 'D' packer set at 2310'.
- 8. TIH and tag for fill. If necessary, cleanout fill to PBTD at 4819'. Blow well dry at PBTD.
- 9. TIH with 4-1/2" casing scraper. Work casing scraper across Mesaverde interval from 3700' 4772'. TOH.
  - 10. Rabbit tubing and RIH with 2-3/8" production tubing.
  - 11. Land 2-3/8" production tubing at 4740'.
- 12. ND BOP's. NU WH. Test well for air. Return well to production and downhole commingle Mesaverde and Pictured Cliffs production.

Allocation Based on Year 2002 Prodution to Date							
Pool	Gas	%	Oil	%			
Pictured Cliffs	26259	32%	0	0%			
Mesaverde	56353	68%	87	100%			

Proce

# Warren LS #2A Commingling Procedure


#### **Procedure:**

- 1. Check anchors. MIRU workover rig.
- 2. Check and record tubing, casing, and bradenhead pressures.
- 3. Blow down wellhead. Kill with 2% KCL water ONLY if necessary.
- 4. Nipple down WH. NU BOPs.
- 5. TOH and LD 1-1/4" short string production tubing currently set at 2188'.
- 6. TOH with 2-3/8" long string production tubing currently set at 4740'.
- 7. Mill slip elements and retrieve 7" Baker Model 'D' packer set at 2310'.
- 8. TIH and tag for fill. If necessary, cleanout fill to PBTD at 4819'. Blow well dry at PBTD.
- 9. TIH with 4-1/2" casing scraper. Work casing scraper across Mesaverde interval from 3700' 4772'. TOH.
- 10. Rabbit tubing and RIH with 2-3/8" production tubing.
- 11. Land 2-3/8" production tubing at 4740'.
- 12. ND BOP's. NU WH. Test well for air. Return well to production and downhole commingle Mesaverde and Pictured Cliffs production.

Allocation Based on Year 2002 Prodution to Date							
Pool	Gas	%	Oil	%			
Pictured Cliffs	26259	32%	0	0%			
Mesaverde	56353	68%	87	100%			

### Warren LS #2A

Sec 12, T28N, R9W API # 30-045-22748



#### NOTES:

 During PC recompletion, original Model 'D' packer became stuck and required milling out. A cone was also lost in the hole. Several days of milling around the liner top were necessary to remove the junk.

updated: 9/11/2002 jad