Office	State of New Mexico Energy, Minerals and Natural Resources		Form C-103 May 27, 2004	
District I 1625 N. French Dr., Hobbs, NM 87240			WELL API NO.	
District II	OIL CONSERVATION DIVISION		30-045-32536	
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.		5. Indicate Type of Lea	ase
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM	77.6	STATE 🗀	FEE 😠
1220 S. St. Francis Dr., Santa Fe, NM 87505		No.	6. State Oil & Gas Lea	se No.
SUNDRY NOTICES AND REPORTS ON WELLS 2008 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name: Santa Rosa 32	
1. Type of Well:	to the second se	i saria	8. Well Number	
Oil Well Gas Well X	Other		2 0. OCDID N	
2. Name of Operator		CIAIE DE NOME	9. OGRID Number	
Energen Resources Corporation 3. Address of Operator	.on		162928 10. Pool name or Wild	loat
2198 Bloomfield Highway - Farmington, NM 87401			Basin Fruitland Coal	
4. Well Location	anningwii, iei Orioi		<u> </u>	
Unit Letter 0 ::	840 feet from the	South line and	1855 feet from the	eline
Section 32	Township 30N	Range 09W	NMPM C	County San Juan
1.0	11. Elevation (Show wheth			
		5702' GL		
Pit or Below-grade Tank Application				
Pit type Depth to Groundwater _				ater
Pit Liner Thickness: mil	Below-Grade Tank: Volu	nebbls; Construction	on Material	
12. Check Ap NOTICE OF INTE	ppropriate Box to Indica	1	• •	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		LTERING CASING
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK COMMENCE DRILL	☐ A ING OPNS. ☐ P	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	☐ A ING OPNS. ☐ P	LITERING CASING PLUG AND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS MULTIPLE	REMEDIAL WORK COMMENCE DRILLI CASING TEST AND	ING OPNS. P	LITERING CASING PLUG AND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION operations. (Clearly state all	REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER: set casin pertinent details, and giv	ING OPNS. PA	LITERING CASING DELUG AND ABANDONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION operations. (Clearly state all SEE RULE 1103. For Mult :2446' Ran 57 jts. 5. z, 6% gel, 2% CaCl2, 10 gilsonite (923 cu.ft.).	REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER: set casin pertinent details, and giv iple Completions: Attach 50" 15.5# casing, set #sk gilsonite, 1/4#,	A A A A A A A A A A A A A A A A A A A	PLUG AND ABANDONMENT X Ing estimated date oposed completion iburton. Cement by 160 sks Class
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 11/11/04 TD:2499' PBTD with 370 sks 65/35 std. po B, 1/4#/sk flocele, 5#/sk	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION operations. (Clearly state all SEE RULE 1103. For Mult :2446' Ran 57 jts. 5. z, 6% gel, 2% CaCl2, 10 gilsonite (923 cu.ft.).	REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER: set casin pertinent details, and giv iple Completions: Attach 50" 15.5# casing, set #sk gilsonite, 1/4#,	A A A A A A A A A A A A A A A A A A A	PLUG AND ABANDONMENT X Ing estimated date oposed completion iburton. Cement by 160 sks Class
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 11/11/04 TD:2499' PBTD with 370 sks 65/35 std. po B, 1/4#/sk flocele, 5#/sk	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION operations. (Clearly state all SEE RULE 1103. For Mult :2446' Ran 57 jts. 5. z, 6% gel, 2% CaCl2, 10 gilsonite (923 cu.ft.).	REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER: set casin pertinent details, and giv iple Completions: Attach 50" 15.5# casing, set #sk gilsonite, 1/4#,	A A A A A A A A A A A A A A A A A A A	PLUG AND ABANDONMENT X Ing estimated date oposed completion iburton. Cement by 160 sks Class
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR ALTER CASING THER: 13. Describe proposed or completed of starting any proposed work). Or recompletion. 11/11/04 TD:2499' PBTD with 370 sks 65/35 std. po B, 1/4#/sk flocele, 5#/sk to surface. RD Halliburton	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Operations. (Clearly state all SEE RULE 1103. For Mult :2446' Ran 57 jts. 5. z, 6% gel, 2% CaCl2, 10 gilsonite (923 cu.ft.). ND BOP. RDMO rig.	REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER: set casin pertinent details, and giv iple Completions: Attach 50" 15.5# casing, set #sk gilsonite, 1/4#, Plug down @ 9:30 pm	A A A A A A A A A A A A A A A A A A A	PLUG AND ABANDONMENT X Ing estimated date Oposed completion iburton. Cement y 160 sks Class e 35 bbls cement
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 11/11/04 TD:2499 PBTD with 370 sks 65/35 std. po B, 1/4#/sk flocele, 5#/sk to surface. RD Halliburton Director RD Halliburton Director RD Halliburton Director RD Halliburton RD	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Operations. (Clearly state all SEE RULE 1103. For Mult :2446' Ran 57 jts. 5. z, 6% gel, 2% Cacl2, 10 gilsonite (923 cu.ft.). ND BOP. RDMO rig. ove is true and complete to topsed according to NMOCD guide	REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER: set casin pertinent details, and giv iple Completions: Attach 50" 15.5# casing, set #sk gilsonite, 1/4#/ Plug down @ 9:30 pm	ang e pertinent dates, including wellbore diagram of product (2491'. RU Halle'sk flocele tailed by a 11/11/04. Circulate and belief. I further certification of an (attached) alternation	LTERING CASING CLUG AND CHARANDONMENT EXAMPLE AND CHARACTER CHARACTER C
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR A	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Operations. (Clearly state all SEE RULE 1103. For Mult :2446' Ran 57 jts. 5. z, 6% gel, 2% CaCl2, 10 gilsonite (923 cu.ft.). ND BOP. RDMO rig.	REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER: set casin pertinent details, and giv iple Completions: Attach 50" 15.5# casing, set #sk gilsonite, 1/4#/ Plug down @ 9:30 pm	A A Assistant DA Volonagha@energen.co	DLUG AND ABANDONMENT IN THE STATE OF THE ST
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THER: 13. Describe proposed or completed of starting any proposed work). Or recompletion. 11/11/04 TD:2499' PBTD with 370 sks 65/35 std. po B, 1/4#/sk flocele, 5#/sk to surface. RD Halliburton Thereby certify that the information ab grade tank has been/will be constructed or cl SIGNATURE	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Operations. (Clearly state all SEE RULE 1103. For Mult :2446' Ran 57 jts. 5. z, 6% gel, 2% CaCl2, 10 gilsonite (923 cu.ft.). ND BOP. RDMO rig.	REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER: set casin pertinent details, and giv iple Completions: Attach 50" 15.5# casing, se #sk gilsonite, 1/4#/ Plug down @ 9:30 pm he best of my knowledge lines, a general permit TITLE	and belief. I further certing or an (attached) alternation Assistant DA vdonaghe@energen.co	DLUG AND ABANDONMENT IN THE STATE OF THE ST
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 11/11/04 TD:2499' PBTD with 370 sks 65/35 std. po B, 1/4#/sk flocele, 5#/sk to surface. RD Halliburton I hereby certify that the information ab grade tank has been/will be constructed or cl SIGNATURE Type or print name Vicki Donaghey	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Operations. (Clearly state all SEE RULE 1103. For Mult 2446' Ran 57 jts. 5. z, 6% gel, 2% CaCl2, 10 gilsonite (923 cu.ft.). ND BOP. RDMO rig.	REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER: set casin pertinent details, and giv iple Completions: Attach 50" 15.5# casing, se #sk gilsonite, 1/4#, Plug down @ 9:30 pm he best of my knowledge lines, a general permit TILEProductio	ING OPNS. PA PA ING OPNS. PA Ing e pertinent dates, including the wellbore diagram of product (2491'. RU Halls/sk flocele tailed by a 11/11/04. Circulate parameter of an (attached) alternation Assistant DA vdonaghe@energen.com Telephon	LITERING CASING CLUG AND CHARANDONMENT IN THE CONTROL