Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED OMB No. 1004-0137 Expires: March 31, 200

5. Lease Serial No.

Jicarilla	C14	10
	Cont	TW

		PD) for such proposals.	Jicarilla-Dulce, N.M.	
SI IRMIT IN TO	IPI ICATE- Other instri	uctions on reverse side.	7. If Unit or CA/Agreement, Name and/or No.	
I. Type of Well	Gas Well Other	F	RECEIVED	
2. Name of Operator COX RIO, L	ac —	070 F/	8. Well Name and No. Rearible Contract C #4E 9. API Well No.	
3a. Address		3b. Phone No. (include area code)	30-039-22298	
4801 N. Butler, Suite 2000, Far		505-326-3003	10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec.,	T., R., M., or Survey Description)		Dakota-Mesaverde 11. County or Parish. State	
790' FSL & 990 FWL Unit M, Sec 24, T26N, R5W	Rio Arriba, NM			
12. CHECK A	PPROPRIATE BOX(ES) TO I	INDICATE NATURE OF NOTICE,	REPORT, OR OTHER DATA	
TYPE OF SUBMISSION		TYPE OF ACTION		
Notice of Intent	Acidize Alter Casing	Deepen Production (S Fracture Treat Reclamation	Start/Resume) Water Shut-Off Well Integrity	
Subsequent Report	Classing Repair	New Construction Recomplete	Cother	
Final Abandonment Notice	Change Plans Convert to Injection	Plug and Abandon Temporarily A Plug Back Water Disposa		
1. Run bit and casing scra			A CAN COM	
2. Run GR/CBL log across 3. Cement squeeze as nece 4. Set 4 1/2" CIBP at 5550" 5. Pressure test casing to 3 6. Fracture stimulate Poin 7. Flowback frac and allov 8. Set 4 1/2" BP at 5000". 9. Fracture stimulate Cliff 10. Flowback frac and allo 11. Drill out bridge plugs. 12. Cleanout and test Mess	s Mesaverde. ssary (notify the BLM before an (100° below lowest MV perf). i,000 psi. If pressure holds, frac it Lookout and Lower Menefee (w well to log off. Release packer house and Upper Menefee (4775 ow well to log off. Release packer averde and Dakota for allocation	down casing, else, repair leak and frac 5180-5420, 25 shots). , POOH. 5-4925, 25 shots). r POOH.	down tubing.	
2. Run GR/CBL log across 3. Cement squeeze as nece 4. Set 4 ½" CIBP at 5550 5. Pressure test casing to 3 6. Fracture stimulate Poin 7. Flowback frac and allov 8. Set 4 1/2" BP at 5000'. 9. Fracture stimulate Cliff 10. Flowback frac and allo 11. Drill out bridge plugs. 12. Cleanout and test Mess 13. Run tubing and place of	s Mesaverde. ssary (notify the BLM before ar (100° below lowest MV perf). (100° psi. If pressure holds, frac at Lookout and Lower Menefee (w well to log off. Release packer house and Upper Menefee (4775 w well to log off. Release packer averde and Dakota for allocation production as a Blanco Mesa	down casing, else, repair leak and frac (5180-5420, 25 shots). , POOH. 5-4925, 25 shots). er POOH. in purposes. verde and Basin Dakota producer.	COSTATE STATE	
2. Run GR/CBL log across 3. Cement squeeze as nece 4. Set 4 ½" CIBP at 5550 5. Pressure test casing to 3 6. Fracture stimulate Poin 7. Flowback frac and allov 8. Set 4 1/2" BP at 5000'. 9. Fracture stimulate Cliff 10. Flowback frac and allo 11. Drill out bridge plugs. 12. Cleanout and test Mess 13. Run tubing and place of	s Mesaverde. ssary (notify the BLM before ar (100° below lowest MV perf). f,000 psi. If pressure holds, frac at Lookout and Lower Menefee (www.) wwell to log off. Release packer thouse and Upper Menefee (4775 www.) wwell to log off. Release packer averde and Dakota for allocation on production as a Blanco Mesa-	down casing, else, repair leak and frac 5180-5420, 25 shots). , POOH. 5-4925, 25 shots). rr POOH. n purposes.	CONTRACTION OF	
2. Run GR/CBL log across 3. Cement squeeze as nece 4. Set 4 ½" CIBP at 5550 5. Pressure test casing to 3 6. Fracture stimulate Poin 7. Flowback frac and allov 8. Set 4 1/2" BP at 5000'. 9. Fracture stimulate Cliff 10. Flowback frac and allo 11. Drill out bridge plugs. 12. Cleanout and test Mess 13. Run tubing and place of 14. I hereby certify that the fore Name (Printed/Typed)	s Mesaverde. ssary (notify the BLM before ar (100° below lowest MV perf). f,000 psi. If pressure holds, frac at Lookout and Lower Menefee (www.) wwell to log off. Release packer thouse and Upper Menefee (4775 www.) wwell to log off. Release packer averde and Dakota for allocation on production as a Blanco Mesa-	down casing, else, repair leak and frac 5180-5420, 25 shots). 5-4925, 25 shots). 12 POOH. 13 purposes. 14 purposes. 15 purposes. 16 purposes. 16 purposes.	Flowsack TANK ON THIS	
2. Run GR/CBL log across 3. Cement squeeze as nece 4. Set 4 ½" CIBP at 5550" 5. Pressure test casing to 3 6. Fracture stimulate Poin 7. Flowback frac and allov 8. Set 4 1/2" BP at 5000'. 9. Fracture stimulate Cliff 10. Flowback frac and allo 11. Drill out bridge plugs. 12. Cleanout and test Mess 13. Run tubing and place of	s Mesaverde. ssary (notify the BLM before ar (100° below lowest MV perf). f,000 psi. If pressure holds, frac at Lookout and Lower Menefee (www.) wwell to log off. Release packer thouse and Upper Menefee (4775 www.) wwell to log off. Release packer averde and Dakota for allocation on production as a Blanco Mesa-	down casing, else, repair leak and frac 5180-5420, 25 shots). 5-4925, 25 shots). 10 r POOH. 11 n purposes. 12 verde and Basin Dakota producer. 13 Title Production Engineer	FlowBACK TANK ON THIS	
2. Run GR/CBL log across 3. Cement squeeze as nece 4. Set 4 ½" CIBP at 5550 5. Pressure test casing to 3 6. Fracture stimulate Poin 7. Flowback frac and allov 8. Set 4 1/2" BP at 5000'. 9. Fracture stimulate Cliff 10. Flowback frac and allo 11. Drill out bridge plugs. 12. Cleanout and test Mess 13. Run tubing and place of 14. I hereby certify that the fore Name (Printed/Typed)	s Mesaverde. ssary (notify the BLM before ar (100° below lowest MV perf). f,000 psi. If pressure holds, frac at Lookout and Lower Menefee (www.) wwell to log off. Release packer thouse and Upper Menefee (4775 www.) wwell to log off. Release packer averde and Dakota for allocation on production as a Blanco Mesa-	down casing, else, repair leak and frac 5180-5420, 25 shots). 5-4925, 25 shots). 10 r POOH. 11 n purposes. 12 verde and Basin Dakota producer. 13 Title Production Engineer	Flowsack TANK ON THIS	
2. Run GR/CBL log across 3. Cement squeeze as nece 4. Set 4 ½" CIBP at 5550 5. Pressure test casing to 3 6. Fracture stimulate Poin 7. Flowback frac and allov 8. Set 4 1/2" BP at 5000'. 9. Fracture stimulate Cliff 10. Flowback frac and allo 11. Drill out bridge plugs. 12. Cleanout and test Mess 13. Run tubing and place of 14. I hereby certify that the fore Name (Printed/Typed) David C. Smith	s Mesaverde. ssary (notify the BLM before ar (100° below lowest MV perf). (100° below lowest MV perf). to Lookout and Lower Menefee (w well to log off. Release packer thouse and Upper Menefee (4775 w well to log off. Release packer averde and Dakota for allocation on production as a Blanco Mesa- going is true and correct	down casing, else, repair leak and frac (5180-5420, 25 shots). 5-4925, 25 shots). r POOH. n purposes. verde and Basin Dakota producer. THE WALL HAVE A	FlowBACK TANK ON THIS	
2. Run GR/CBL log across 3. Cement squeeze as nece 4. Set 4 ½" CIBP at 5550 5. Pressure test casing to 3 6. Fracture stimulate Poin 7. Flowback frac and allov 8. Set 4 1/2" BP at 5000'. 9. Fracture stimulate Cliff 10. Flowback frac and allo 11. Drill out bridge plugs. 12. Cleanout and test Mess 13. Run tubing and place of 14. I hereby certify that the fore Name (Printed/Typed) David C. Smith	s Mesaverde. ssary (notify the BLM before ar (100° below lowest MV perf). house in the Lower Menefee (at Lookout and Lower Menefee (at Lookout and Lower Menefee (at the Lookout and Upper Menefee (at the Lookout	down casing, else, repair leak and frac (5180-5420, 25 shots). 5-4925, 25 shots). THEY WILL HAVE A Title Production Engineer Date Title Production Engineer	FlowBACK TANK ON THIS	

(Instructions on page 2)

AFWSS

NOV 2 9 2004

NWOCD

District i

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

State of New Mexico

Energy, Minerals & Natural Resources Department

Revised June 10, 2003 Submit to Appropriate District Office

OIL CONSERVATION DIVISION NOV 19

State Lease - 4 Copies
Fee Lease - 3 Copies

Form C-102

1220 South St. Francis Dr.

Santa Fe, NM 87505

RECEIVE

1220 S. St. Francis Dr., Santa Fe, NM 87505 WELL LOCATION AND							070 FADU	- IV C.D.	J AME	ENDED REPORT	
		$_{-}$ WE	LL LC	CATIO	N AND ACE	REAGE DEDIC	CATION PL	ATETON	HM		
API Number Pool Code					³ Pool Name						
3	30-039-22298 71599 / 72319 BLANCO MESAVERDE & B				& BASIN DA	BASIN DAKOTA					
⁴ Property Code ⁵				⁵ Property	roperty Name				Well Number		
JICARII				JICARILLA CO	LA CONTRACT C				4E		
OGRID !	No.	Operator Name						'Elevation			
222374]	CDX RI				K RIO, LLC				6578 GR	
	_				¹⁰ Surface	Location					
UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the			County	
M	24	26N	R5W		790	SOUTH	990			RIO ARRIBA	
			¹¹ Bo	ttom Hol	e Location I	f Different Fro	m Surface				
UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line		County	
¹² Dedicated Acres	3 Joint or	r Infill 14 Con	asolidation	Code 15 Or	der No.	L					

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION **OPERATOR CERTIFICATION** I hereby certify that the information contained herein is true and complete Robert Lemmons Title and E-mail Address Operations Engineer, rob.lemmons@cdxgas.com Date 8/20/04 18SURVEYOR CERTIFICATION I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief. October 26, 1979 Date of Survey Signature and Seal of Professional Surveyor 990' ON FILE 790' Certificate Number 3950