

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 87210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. <b>30-045-09937</b>
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator <b>PLATA Minerals &amp; Energy</b>		6. State Oil & Gas Lease No.
3. Address of Operator <b>% care of OCD AZTEC</b>		7. Lease Name or Unit Agreement Name: <b>Horseshoe 6A Unit</b>
4. Well Location Unit Letter <b>2</b> : <b>291</b> feet from the <b>N</b> line and <b>331</b> feet from the <b>W</b> line Section <b>2</b> Township <b>30N</b> Range <b>16W</b> NMPM County		8. Well No. <b>239</b>
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. Pool name or Wildcat

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐


COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

See Attachment



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Charles J. Peltz TITLE \_\_\_\_\_ DATE \_\_\_\_\_

Type or print name \_\_\_\_\_ Telephone No. \_\_\_\_\_

(This space for State use)

APPROVED BY Charles J. Peltz TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE JUN - 5 2003

Conditions of approval, if any:

API WELL #	Well Name	Well #	Operator Name	Type	Stat	County	Surf Owner	UL	Sec	Twp	N/S	Rng	W/E	Feet	NS	Ft	EW	Order_No
30-045-09937	HORSESHOE GALLUP UNIT	239	PLAYA MINERALS & ENERGY INC	O	A	San Juan	S	E	2	30	N	16	W	2191	N	331	W	

CO	8 5/8	215	70S			4 1/2	1728	85S			2 3/8	1719	1567-1718
----	-------	-----	-----	--	--	-------	------	-----	--	--	-------	------	-----------

#### Procedure

MIRU, NUBOPE,

POOH Lay Down Rods & Tubing if present,

RIH with Gauge ring,

Pick up work string, Run Scraper if required,

RIH Set CIBP 1500 ', cap with 200 ' cement .

Test casing.

POOH lay down tubing.

RU wire line RIH, perforate @ 265 ' + - 50' under surface casing shoe or Mesa Verde base whichever is lower..

Establish Circulation; circulate cement to surface inside and outside casing

Cut off well head and install P&A marker

Cut off anchors 2' below ground

Clean and level location