Form 3160-5 (August 1999)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	/ OMB NO. 100
	Expires: November
5/	Lease Serial No.
V	NMNM0606

	TORM ALTROVED
/	OMB NO. 1004-0135
	Expires: November 30, 2000
se S	Serial No.

FORM APPROVED

^	
4	
O	

**SUNDRY NOTICES AND REPORTS ON WELLS** 

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.		
<ol> <li>Type of Well</li> <li>Oil Well</li></ol>	ner				8. Well Name and No ATLANTIC A LS		
2. Name of Operator Contact: MARY CORLES BP AMERICA PRODUCTION CO E-Mail: corley in Contact: Contact: MARY CORLES CONTACT: CONTACT: MARY CORLES CONTACT: MAR					9. API Well No. 30-045-23280		
3a. Address HOUSTON, TX 77253	3b. Phone No. (include area code) Ph: 281-366-4491			10. Field and Pool, or Exploratory BLANCO PICTURED CLIFFS			
4. Location of Well (Footage, Sec., 1 Sec 27 T31N R10W NWSE 1		OBT. S ON		11. County or Parish, and State SAN JUAN COUNTY, NM			
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE	A YATE OF	MOTICE, RI	EPORT, OR OTHE	ER DATA	
TYPE OF SUBMISSION							
Notice of Intent  ☐ Subsequent Report ☐ Final Abandonment Notice	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	□ New  ▶ Plug	ure Treat Construction and Abandon	Reclama	olete arily Abandon	☐ Water Shut-Off ☐ Well Integrity ☐ Other	
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final Atdetermined that the site is ready for final BP is in the processes of attee this attempt prove to be unsure wellbore as follows:  Contact Federal and State ag x16 and BLM Jim Lovato 505. Check location for anchors. In MIRU. Check and record tubin Blow down well and kill, if nec ND wellhead, NU BOP.  Spot 8 sack cement plug 292. Spot 8 sack cement plug 2552.	rk will be performed or provided operations. If the operation rebandonment Notices shall be final inspection.)  Impting to restore the subccessful, we request performed as prior to starting Properties of the performance of	e the Bond No. on soults in a multiple led only after all reject well to pronission to procexA work (NMO) on 505-599-636 nchors.	file with BLM/B completion or requirements, including duction, howe eed to plug are CD Charlie Pe	IA. Required suscentible in a uding reclamation of the completion in a uding reclamation of the completion of the completion in the completion of the comple	bsequent reports shall b new interval, a Form 31 n, have been completed	e filed within 30 days 60-4 shall be filed once	
14. Thereby certify that the foregoing is  Name (Printed/Typed) MARY CC	Electronic Submission # For BP AMERICA	#54050 verified A PRODUCTION	l ČO, sent to t	he Farmingtor	System RESENTATIVE		
Signature (Electronic S	Submission)		Date <b>02/14</b> /	<b>/</b> 2005			
	THIS SPACE FO	OR FEDERAL	OR STATE	OFFICE US	SE .		
Approved By Conditions of approved, if any, are attached certify that the applicant holds legal or equivalent to apply the conditions of approved the conditions to apply the	uitable title to those rights in th	s not warrant or le subject lease	Title /	GO		FEB. 1 4 2005	
which would entitle the applicant to condu- Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a	a crime for any per s to any matter wit	Office rson knowingly a thin its jurisdiction	nd willfully to mon.	ake to any department o	or agency of the United	

## Additional data for EC transaction #54050 that would not fit on the form

## 32. Additional remarks, continued

Spot 16 sack cement plug 1535' - 1735' to isolate Kirtland/Ojo Alamo. In the round of the 4 h (to any Perforate squeeze hole at 263'. Squeeze with 78 sacks cement and attempt to circulate to surface. Leave 21 sacks inside casing from 263' to surface to isolate the surface casing shoe. ND BOP. RDMO. Cut off wellhead and casing. Install PxA marker. Provide work order to Vance Norton or Don Brooks for surface reclamation.