Submit 3 Copies To Appropriate District	State of New Mexi	co /	Form C-103
Office District I	Energy, Minerals and Natura	Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		/ 1	API NO.
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION D	DIVISION $\frac{30-045-}{5}$	
District III	1220 South St. Franci	3. High	ate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 875	<u> </u>	TATE FEE X
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa 1 C, 14141 075	6. State	Oil & Gas Lease No.
87505		CT 11 17 10 10	
SUNDRY NOTION	CES AND REPORTS ON WELLS 🔨		e Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOS	ALS TO DRILL OR TO DEEPEN OR PLUG ATION FOR PERMIT" (FORM C-1019) FOR	BACK TO A STEDJI	E GAS COM
PROPOSALS.)	ATION FOR FERMIT (FORM C-101) FOR		
1. Type of Well: Oil Well	Gas Well 🛛 Other 🔝 🧀	Well	Number #1
2. Name of Operator	. 0	99 OGR	ID Number
XTO ENERGY INC.	· ·	-william.	167067
3. Address of Operator	w.	~ i 13	ol name or Wildcat
2700 FARMINGTON AVE, SUITE K-1, FARMINGTON, NM 874016 BASIN DK / BLANCO MV			
4. Well Location			
Unit Letter F: 1730	feet from the <u>NORTH</u> line a	nd 1770 feet from the	e <u>WEST</u> line
Section 27 Town		NMPM	County SAN JUAN
	11. Elevation (Show whether DR, R		
	11, Bievanen (Snow whether Bit, 1	112, 111, 311, 610.	
Pit or Below-grade Tank Application X or	Closure		Lattick Lauranter commentation food in information representation of all the page 1 th contributions have a mini-
Pit type WKO Depth to Group	ndwater_< <u>100'</u> Distance from nearest fre	sh water well <1000' Distance	from nearest surface water <1000'
	v-Grade Tank: Volume	bbls; Construction Material	
12. Check A	ppropriate Box to Indicate Nat	ure of Notice, Report of	or Other Data
NOTICE OF IN	TENTION TO:	CLIDGEOLIE	INT DEDODT OF
			ENT REPORT OF:
PERFORM REMEDIAL WORK	- 1	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OF	PNS. PANDA 🗆
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT JOB	
OTHER: Sauceze MV Porfs Par B	4 8: D/MOD 🔽 (THER:	П
OTHER: Squeeze MV Perfs, Rpr B		OTHER:	tinent dates, including estimated date
13. Describe proposed or compl	eted operations. (Clearly state all per	rtinent details, and give per	
13. Describe proposed or compl of starting any proposed wo		rtinent details, and give per	
 Describe proposed or compl of starting any proposed wo or recompletion. 	eted operations. (Clearly state all perk). SEE RULE 1103. For Multiple	tinent details, and give per Completions: Attach well	pore diagram of proposed completion
13. Describe proposed or compl of starting any proposed wo	eted operations. (Clearly state all perk). SEE RULE 1103. For Multiple	tinent details, and give per Completions: Attach well	pore diagram of proposed completion
 Describe proposed or compl of starting any proposed wo or recompletion. 	eted operations. (Clearly state all perk). SEE RULE 1103. For Multiple	tinent details, and give per Completions: Attach well	pore diagram of proposed completion
13. Describe proposed or compl of starting any proposed wo or recompletion. XTO Energy Inc. proposes to repair	eted operations. (Clearly state all perk). SEE RULE 1103. For Multiple	tinent details, and give per Completions: Attach well	pore diagram of proposed completion
13. Describe proposed or complete of starting any proposed wo or recompletion.XTO Energy Inc. proposes to repair 1MIRU.	eted operations. (Clearly state all perk). SEE RULE 1103. For Multiple	tinent details, and give per Completions: Attach well	pore diagram of proposed completion
 13. Describe proposed or complete of starting any proposed wo or recompletion. XTO Energy Inc. proposes to repair 1 1) MIRU. 2) ND WH. NU BOP. 	eted operations. (Clearly state all perck). SEE RULE 1103. For Multiple oradenhead, squeeze Mesaverde & PV	tinent details, and give per Completions: Attach well	pore diagram of proposed completion
 Describe proposed or complete of starting any proposed wo or recompletion. TO Energy Inc. proposes to repair 1 MIRU. ND WH. NU BOP. MIRU AFU. 	eted operations. (Clearly state all perck). SEE RULE 1103. For Multiple oradenhead, squeeze Mesaverde & PV	tinent details, and give per Completions: Attach well	pore diagram of proposed completion
 Describe proposed or complete of starting any proposed wo or recompletion. XTO Energy Inc. proposes to repair 1 MIRU. ND WH. NU BOP. MIRU AFU. Mill out Model D pkr @ 60 	eted operations. (Clearly state all perck). SEE RULE 1103. For Multiple oradenhead, squeeze Mesaverde & PV	tinent details, and give per Completions: Attach well	pore diagram of proposed completion
13. Describe proposed or complete of starting any proposed we or recompletion. XTO Energy Inc. proposes to repair 1 1) MIRU. 2) ND WH. NU BOP. 3) MIRU AFU. 4) Mill out Model D pkr @ 60 5) TIH & set 7" CIBP @ appro	eted operations. (Clearly state all perck). SEE RULE 1103. For Multiple oradenhead, squeeze Mesaverde & PV	tinent details, and give per Completions: Attach well	pore diagram of proposed completion
13. Describe proposed or complor of starting any proposed wo or recompletion. XTO Energy Inc. proposes to repair 1 1) MIRU. 2) ND WH. NU BOP. 3) MIRU AFU. 4) Mill out Model D pkr @ 60 5) TIH & set 7" CIBP @ appropring the set 7" CIBP @ appropring to the set 7" MIRU cmt trks.	eted operations. (Clearly state all perck). SEE RULE 1103. For Multiple oradenhead, squeeze Mesaverde & PV 18' ox 3450'. ations.	tinent details, and give per Completions: Attach wellt WOP in the following man	pore diagram of proposed completion
13. Describe proposed or complor of starting any proposed wo or recompletion. XTO Energy Inc. proposes to repair 1 1) MIRU. 2) ND WH. NU BOP. 3) MIRU AFU. 4) Mill out Model D pkr @ 60 5) TIH & set 7" CIBP @ approximately approximately approximately approximately 100 per 100 p	eted operations. (Clearly state all perck). SEE RULE 1103. For Multiple oradenhead, squeeze Mesaverde & PV ox 3450'. ations.	tinent details, and give per Completions: Attach wellt WOP in the following man	pore diagram of proposed completion
13. Describe proposed or complete of starting any proposed wo or recompletion. XTO Energy Inc. proposes to repair 1 1) MIRU. 2) ND WH. NU BOP. 3) MIRU AFU. 4) Mill out Model D pkr @ 60 5) TIH & set 7" CIBP @ approximate	eted operations. (Clearly state all perck). SEE RULE 1103. For Multiple oradenhead, squeeze Mesaverde & PV ox 3450'. ations. 9' - 3318' w/approx 75 sx Class B cx 600 psig.	tinent details, and give per Completions: Attach wellt WOP in the following man	pore diagram of proposed completion
13. Describe proposed or complete of starting any proposed wo or recompletion. XTO Energy Inc. proposes to repair 1 1) MIRU. 2) ND WH. NU BOP. 3) MIRU AFU. 4) Mill out Model D pkr @ 60 5) TIH & set 7" CIBP @ approx 6) Notify NMOCD of sqz oper 7) MIRU cmt trks. 8) Sqz MV perfs fr/approx 329 9) PT sqz'd MV perfs to approx 10) Repair BH leak d.sc-s	eted operations. (Clearly state all perck). SEE RULE 1103. For Multiple oradenhead, squeeze Mesaverde & PV ox 3450'. ations. 9' - 3318' w/approx 75 sx Class B cx 600 psig.	tinent details, and give per Completions: Attach welll WOP in the following man	pore diagram of proposed completion
13. Describe proposed or complete of starting any proposed wo or recompletion. XTO Energy Inc. proposes to repair 1 1) MIRU. 2) ND WH. NU BOP. 3) MIRU AFU. 4) Mill out Model D pkr @ 60 5) TIH & set 7" CIBP @ approx 6) Notify NMOCD of sqz oper 7) MIRU cmt trks. 8) Sqz MV perfs fr/approx 329 9) PT sqz'd MV perfs to approx 10) Repair BH leak d.sc-s	eted operations. (Clearly state all perck). SEE RULE 1103. For Multiple oradenhead, squeeze Mesaverde & Proceedings of the Procedure of the Pr	tinent details, and give per Completions: Attach welll WOP in the following man	pore diagram of proposed completion
13. Describe proposed or complete of starting any proposed wo or recompletion. XTO Energy Inc. proposes to repair 1 1) MIRU. 2) ND WH. NU BOP. 3) MIRU AFU. 4) Mill out Model D pkr @ 60 5) TIH & set 7" CIBP @ approx 6) Notify NMOCD of sqz oper 7) MIRU cmt trks. 8) Sqz MV perfs fr/approx 329 9) PT sqz'd MV perfs to approx 10) Repair BH leak disces 11) TIH w/SOPMA, tbg, pmp, reserved.	eted operations. (Clearly state all perck). SEE RULE 1103. For Multiple oradenhead, squeeze Mesaverde & Proceedings of the Procedure of the Pr	tinent details, and give per Completions: Attach welll WOP in the following man	pore diagram of proposed completion
13. Describe proposed or complor of starting any proposed wo or recompletion. XTO Energy Inc. proposes to repair 1 1) MIRU. 2) ND WH. NU BOP. 3) MIRU AFU. 4) Mill out Model D pkr @ 60 5) TIH & set 7" CIBP @ appropriate a	eted operations. (Clearly state all perck). SEE RULE 1103. For Multiple oradenhead, squeeze Mesaverde & Provided Provide	tinent details, and give per Completions: Attach welll WOP in the following man	pore diagram of proposed completion
13. Describe proposed or complete of starting any proposed wo or recompletion. XTO Energy Inc. proposes to repair 1 1) MIRU. 2) ND WH. NU BOP. 3) MIRU AFU. 4) Mill out Model D pkr @ 60 5) TIH & set 7" CIBP @ approprious approprious of the set of the s	eted operations. (Clearly state all perck). SEE RULE 1103. For Multiple oradenhead, squeeze Mesaverde & Provided Provide	tinent details, and give per Completions: Attach welll WOP in the following man	pore diagram of proposed completion
13. Describe proposed or complete of starting any proposed wo or recompletion. XTO Energy Inc. proposes to repair 1 1) MIRU. 2) ND WH. NU BOP. 3) MIRU AFU. 4) Mill out Model D pkr @ 60 5) TIH & set 7" CIBP @ approprious of sqz oper 7) MIRU cmt trks. 8) Sqz MV perfs fr/approx 329 9) PT sqz'd MV perfs to approprious 10) Repair BH leak d.sc-s 11) TIH w/SOPMA, tbg, pmp, r 12) Set ppg ut w/gas engine. 13) RWTP	eted operations. (Clearly state all perk). SEE RULE 1103. For Multiple oradenhead, squeeze Mesaverde & Proceedings of the Procedure of the Pro	tinent details, and give per Completions: Attach well WOP in the following manner of the following man	pore diagram of proposed completion ner:
13. Describe proposed or complete of starting any proposed wo or recompletion. XTO Energy Inc. proposes to repair 1 1) MIRU. 2) ND WH. NU BOP. 3) MIRU AFU. 4) Mill out Model D pkr @ 60 5) TIH & set 7" CIBP @ approproper of the set of the se	eted operations. (Clearly state all perck). SEE RULE 1103. For Multiple oradenhead, squeeze Mesaverde & PV 18' ox 3450'. ations. 9' - 3318' w/approx 75 sx Class B cx 600 psig. The colors, TAC. Set TAC. Land tbg in William ork and remove per NMOCD guidelies over its true and complete to the best	rtinent details, and give per Completions: Attach wellt WOP in the following manner. The second of the following manner. The second of my knowledge and believed the second of my knowledge and believed.	ed.
13. Describe proposed or complete of starting any proposed wo or recompletion. XTO Energy Inc. proposes to repair 1 1) MIRU. 2) ND WH. NU BOP. 3) MIRU AFU. 4) Mill out Model D pkr @ 60 5) TIH & set 7" CIBP @ approprious of sqz oper 7) MIRU cmt trks. 8) Sqz MV perfs fr/approx 329 9) PT sqz'd MV perfs to approprious 10) Repair BH leak d.sc-s 11) TIH w/SOPMA, tbg, pmp, r 12) Set ppg ut w/gas engine. 13) RWTP	eted operations. (Clearly state all perck). SEE RULE 1103. For Multiple oradenhead, squeeze Mesaverde & Proposition of the Prop	rtinent details, and give per Completions: Attach wellt WOP in the following manner. The second of the following manner. The second of my knowledge and believed the second of my knowledge and believed.	ed.
13. Describe proposed or complete of starting any proposed wo or recompletion. XTO Energy Inc. proposes to repair 1 1) MIRU. 2) ND WH. NU BOP. 3) MIRU AFU. 4) Mill out Model D pkr @ 60 5) TIH & set 7" CIBP @ approprious of sqz oper 7) MIRU cmt trks. 8) Sqz MV perfs fr/approx 329 9) PT sqz'd MV perfs to approprious 10) Repair BH leak discussions 11) TIH w/SOPMA, tbg, pmp, roughly 12) Set ppg ut w/gas engine. 13) RWTP XTO will install a lined pit for this we hereby certify that the information a grade tank has been/will beconstructed or 10.	eted operations. (Clearly state all perck). SEE RULE 1103. For Multiple oradenhead, squeeze Mesaverde & PV 18' ox 3450'. ations. 9' - 3318' w/approx 75 sx Class B cx 600 psig. ods, TAC. Set TAC. Land tbg in William ork and remove per NMOCD guidelines and complete to the best closed according to NMOCD guidelines X, at 18' or 18'	tinent details, and give per Completions: Attach well work in the following manner. The mes when work is completed of my knowledge and belief general permit or an (attached) or an (attached).	ed. St. I further certify that any pit or below-hed) alternative OCD-approved plan □.
13. Describe proposed or complete of starting any proposed wo or recompletion. XTO Energy Inc. proposes to repair 1 1) MIRU. 2) ND WH. NU BOP. 3) MIRU AFU. 4) Mill out Model D pkr @ 60 5) TIH & set 7" CIBP @ approproper of the set of the se	eted operations. (Clearly state all perck). SEE RULE 1103. For Multiple oradenhead, squeeze Mesaverde & PV 18' ox 3450'. ations. 9' - 3318' w/approx 75 sx Class B cx 600 psig. ods, TAC. Set TAC. Land tbg in William ork and remove per NMOCD guidelines and complete to the best closed according to NMOCD guidelines X, at 18' or 18'	tinent details, and give per Completions: Attach well work in the following manner. The mes when work is completed of my knowledge and belief general permit or an (attached) or an (attached).	ed.
13. Describe proposed or complete of starting any proposed wo or recompletion. XTO Energy Inc. proposes to repair 1 1) MIRU. 2) ND WH. NU BOP. 3) MIRU AFU. 4) Mill out Model D pkr @ 60 5) TIH & set 7" CIBP @ approx 329 6) Notify NMOCD of sqz oper 7) MIRU cmt trks. 8) Sqz MV perfs fr/approx 329 9) PT sqz'd MV perfs to approx 10) Repair BH leak d.sc-s 11) TIH w/SOPMA, tbg, pmp, r 12) Set ppg ut w/gas engine. 13) RWTP XTO will install a lined pit for this whereby certify that the information a grade tank has been/will beconstructed or SIGNATURE	eted operations. (Clearly state all perck). SEE RULE 1103. For Multiple bradenhead, squeeze Mesaverde & PV 18' ox 3450'. ations. 9' - 3318' w/approx 75 sx Class B c ox 600 psig. ods, TAC. Set TAC. Land tbg in William or and remove per NMOCD guidelines and complete to the best closed according to NMOCD guidelines X, a TITLE REC	Tinent details, and give per Completions: Attach well work in the following manner. The mes when work is completed of my knowledge and belief general permit or an (attack gulatory complete).	ed. St. I further certify that any pit or below-hed) alternative OCD-approved plan CE TECH_DATE 3/16/05
13. Describe proposed or complete of starting any proposed wo or recompletion. XTO Energy Inc. proposes to repair 1 1) MIRU. 2) ND WH. NU BOP. 3) MIRU AFU. 4) Mill out Model D pkr @ 60 5) TIH & set 7" CIBP @ approprious of sqz oper 7) MIRU cmt trks. 8) Sqz MV perfs fr/approx 329 9) PT sqz'd MV perfs to approprious 10) Repair BH leak discussions 11) TIH w/SOPMA, tbg, pmp, roughly 12) Set ppg ut w/gas engine. 13) RWTP XTO will install a lined pit for this we hereby certify that the information a grade tank has been/will beconstructed or 10.	eted operations. (Clearly state all perck). SEE RULE 1103. For Multiple oradenhead, squeeze Mesaverde & PV 18' ox 3450'. ations. 9' - 3318' w/approx 75 sx Class B c x 600 psig. ods, TAC. Set TAC. Land tbg in Whork and remove per NMOCD guidelines and complete to the best closed according to NMOCD guidelines X, a TITLE REC	tinent details, and give per Completions: Attach well work in the following manner. The mes when work is completed of my knowledge and belief general permit or an (attack gulatorny completed) or an (attack gulatorny completed) with the completed of the complet	ed. ef. I further certify that any pit or below-hed) alternative OCD-approved plan CE TECH_DATE 3/16/05 No.505-324-1090
13. Describe proposed or complete of starting any proposed wo or recompletion. XTO Energy Inc. proposes to repair 1 1) MIRU. 2) ND WH. NU BOP. 3) MIRU AFU. 4) Mill out Model D pkr @ 60 5) TIH & set 7" CIBP @ approfection of the set of the s	eted operations. (Clearly state all perck). SEE RULE 1103. For Multiple oradenhead, squeeze Mesaverde & PV 18' ox 3450'. ations. 9' - 3318' w/approx 75 sx Class B c x 600 psig. ods, TAC. Set TAC. Land tbg in Whork and remove per NMOCD guidelines and complete to the best closed according to NMOCD guidelines X, a TITLE REC	Tinent details, and give per Completions: Attach well work in the following manner. The mes when work is completed of my knowledge and belief general permit or an (attack gulatory complete).	ed. ef. I further certify that any pit or below-hed) alternative OCD-approved plan CE TECH_DATE 3/16/05 No.505-324-1090
13. Describe proposed or complos of starting any proposed wo or recompletion. XTO Energy Inc. proposes to repair 1 1) MIRU. 2) ND WH. NU BOP. 3) MIRU AFU. 4) Mill out Model D pkr @ 60 5) TIH & set 7" CIBP @ approx 6) Notify NMOCD of sqz oper 7) MIRU cmt trks. 8) Sqz MV perfs fr/approx 329 9) PT sqz'd MV perfs to approx 10) Repair BH leak d.sc-s 11) TIH w/SOPMA, tbg, pmp, r 12) Set ppg ut w/gas engine. 13) RWTP XTO will install a lined pit for this whereby certify that the information a grade tank has been/will beconstructed or SIGNATURE Type or print name HOLLY C. PERI	eted operations. (Clearly state all perck). SEE RULE 1103. For Multiple oradenhead, squeeze Mesaverde & PV 18' ox 3450'. ations. 9' - 3318' w/approx 75 sx Class B c x 600 psig. ods, TAC. Set TAC. Land tbg in Whork and remove per NMOCD guidelines and complete to the best closed according to NMOCD guidelines X, a TITLE REC	tinent details, and give per Completions: Attach well work in the following manner. The mes when work is completed of my knowledge and belief general permit or an (attack gulatorny completed) or an (attack gulatorny completed) with the completed of the complet	ed. ef. I further certify that any pit or belowhed) alternative OCD-approved plan □. CE TECH_DATE 3/16/05 No.505-324-1090