

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

SEP 14 2012

FORM APPROVED
OMB No 1004-0137
Expires October 31, 2014

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1 Type of Well

☒ Oil Well ☐ Gas Well ☐ Other2 Name of Operator
Four Star Oil & Gas Company3a. Address
ATTN: Regulatory Specialist
332 Road 3100 Aztec New Mexico 874103b. Phone No. (include area code)
505-333-19414 Location of Well (Footage, Sec., T., R., M., or Survey Description)
Unit O-19-25N-03W 840 FSL 1820 FEL

5 Lease Serial No.

6 If Indian, Allottee or Tribe Name

7 If Unit of CA/Agreement Name and/or No.

8 Well Name and No.
Lydia Rentz #119 API Well No.
30-039-2530310 Field and Pool or Exploratory Area
Lindrith Gallup West/Blanco Mesaverde11 County or Parish, State
Rio Arriba

12 CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other Pump repair
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

Pump repair project scheduled for October 2012.

1. PULL OUT OF HOLE WITH ROD STRING, PUMP AND TUBING
2. TAG FOR FILL AND CLEANOUT TO PBTD @ 8190'.
3. RUN PRODUCTION TUBING AND LAND AT ~ 8095'.
4. RUN ROD STRING AND PUMP.

See attached wellbore diagram.

RCVD SEP 19 '12

OIL CONS. DIV.

DIST. 3

14 I hereby certify that the foregoing is true and correct Name (Printed/Typed)

April E. Pohl

Title Regulatory Specialist

Signature

April E Pohl

Date

9-13-12

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Original Signed: Stephen Mason

Title

Date

SEP 16 2012

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

NMOCD



Lydia Rentz 11

Rio Arriba County, New Mexico

Sec 19 – T 25N – R 3W

Field: Basin

API: 30-039-25303

1. PULL OUT OF HOLE WITH ROD STRING, PUMP AND TUBING.
2. TAG FOR FILL AND CLEANOUT TO PBTD @ 8190'.
3. RUN PRODUCTION TUBING AND LAND AT ~ 8095'.
4. RUN ROD STRING AND PUMP.

See Current Wellbore Diagram:

