

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
March 4, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

PN

WELL API NO. 2005-045-09347
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Blancett
8. Well Number 1
9. OGRID Number 013998
10. Pool name or Wildcat Aztec PC

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☒ Other

2. Name of Operator
Maralex Resources, Inc.

3. Address of Operator
P.O. Box 338, Ignacio, CO 81137

4. Well Location
Unit Letter G : 2230 feet from the North line and 2000 feet from the East line
Section 24 Township 30N Range 12W NMPM County San Juan

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
5544 GL

Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)

Pit Location: UL G Sect 24 Twp 30N Rng 12W Pit type Prod. Depth to Groundwater _____ Distance from nearest fresh water well 200'?
Distance from nearest surface water 500' Below-grade Tank Location UL _____ Sect _____ Twp _____ Rng _____ ;
_____ feet from the _____ line and _____ feet from the _____ line

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Well was plugged on July 22, 2004. Details are attached.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Carla S. Shaw TITLE Production Technician DATE 08/20/04

Type or print name Carla S. Shaw E-mail address: maralex@westernet.net Telephone No. 970/563-4000

(This space for State use)

APPROVED BY H. Villanueva TITLE DEPUTY OIL & GAS INSPECTOR, DIST. 2 DATE JUL 12 2005
Conditions of approval, if any: 7-12-05

ATTACHMENT TO FORM C-103

MARALEX RESOURCES, INC.

**PLUG & ABANDONMENT
BLANCETT # 1
2230' FNL; 2000' FEL (SWNE)
SECTION 24-T30N-R12W
SAN JUAN COUNTY, NM**

On 7/21/04, trip in hole to plug back depth of 2133'. **Pump 75 sx Class B Neat cement down tubing and displace with 2.5 BBls water.** Trip out of hole and lay down 23 joints of tubing. Reverse out cement at 1400'. Tally out of hole and make sure tubing is clean. Trip in hole to 900'. Shut down and wait on cement.

On 7/22/04, load hole with water and pressure test casing and cement plug to 500 psi. Trip in hole and tag top of cement plug at 1395'. PU hole, lay down 16 joints of 2-3/8" tubing. Set tubing at 900'. Rig up cementers and **pump 75 sacks of Class B Neat cement from 900' to surface.** Trip out of hole, lay down all tubing, clean cement out of BOP and wellhead. Rig down floor. Nipple down BOP and wellhead. Dig out around wellhead so welder can cut off below ground level. Rig down rig.

On 7/27/04, cut off 8-5/8" casing and 4-1/2" casing below ground level. Weld up cap on top of casing. Make up sign showing operator, well name and location. Weld to top of cap. Call State and request inspection.

Installed an above-ground P&A marker.