Submit 3 Copies To Appropriate District				
000-	State of New M	1exico /		Form C-103
Office District I	Energy, Minerals and Na	itural Resources		May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	525 N. French Dr., Hobbs, NM 88240		WELL API NO.	
District II			30-045-32765	
1301 W. Grand Ave., Artesia, NM 88210 District III	W. Gland Ave., Autosia, 1111 00210		5. Indicate Type of	
1000 Rio Brazos Rd., Aztec, NM 87410	Dunna Dd. Agtas NM 97410		STATE	FEE 🛛
District IV	Santa Fe, NM	8/303 /	6. State Oil & Gas	Lease No.
1220 S. St. Francis Dr., Santa Fe, NM				1
87505 SUNDRY NOTIC	ES AND REPORTS ON WELL	LS	7. Lease Name or I	Jnit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		Tecumseh		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		1000000		
PROPOSALS.)		8. Well Number #	1E	
1. Type of Well: Oil Well Gas Well Other				
2. Name of Operator San Juan Re	sources of Colorado		9. OGRID Number	
			020208	
3. Address of Operator c/o Walsh		1	10. Pool name or V	l l
7415 East Main Street, Farmington,	NM 8/402		Blanco Mesa Verde	e / Basin Dakota
4. Well Location				ļ
Unit Letter E 1470'	feet from the SOUTH line at	nd 1095' feet from th	ne West line	
Section 18	Township 30N	Range 11W N	MPM Count	y San Juan
The second secon	11. Elevation (Show whether L			
	5538' GR	71, 141 D , 111, G11, cic.)		
Pit or Below-grade Tank Application or				200,037
Pit typeDepth to Groundwa	ter Distance from nearest fres	h water well Dist	ance from nearest surfac	e water 3727 CO CI (8)
1				7-1 1-
THE THICKNESS.	Below-Grade Tank: Volume ppropriate Box to Indicate FENTION TO:	bbis, Co	distruction Material	A SEP
12. Check A	ppropriate Box to Indicate	Nature of Notice,	Report or Other I	Data Of ECE 2000
				E CONVEY
	CENITIONI TO.	CLID	CECHENT DED	
				"AYD " AL
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🔲	REMEDIAL WOR	K 🗆 /	ALTERNIG CASING DI
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON	REMEDIAL WORI	K □ A LLING OPNS.□ F	"AYD " AL
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🔲	REMEDIAL WOR	K □ A LLING OPNS.□ F	ALTERNIG CASING DI
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON	REMEDIAL WORI COMMENCE DRI CASING/CEMENT	K □ A LLING OPNS.□ F	ALTERNIG CASING DI
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL	REMEDIAL WORI COMMENCE DRI CASING/CEMENT	K □ / LLING OPNS.□ F F JOB ⊠	ALTERNG CASING PA
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL CHEET COMPL CHEET CHANGE PLANS CHANGE	REMEDIAL WORI COMMENCE DRI CASING/CEMENT OTHER: Il pertinent details, and	K	ALTERING CASING AND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL	REMEDIAL WORI COMMENCE DRI CASING/CEMENT OTHER: Il pertinent details, and	K	ALTERING CASING AND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL CHEET COMPL CHEET CHANGE PLANS CHANGE	REMEDIAL WORI COMMENCE DRI CASING/CEMENT OTHER: Il pertinent details, and	K	ALTERING CASING AND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or completion or recompletion.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL CHANGE PLANS MULTIPLE COMPL CHANGE PLANS CHANGE PLA	REMEDIAL WORK COMMENCE DRI CASING/CEMENT OTHER: Il pertinent details, and tiple Completions: At	K	ALTERNG CASING AND CASING AND CASING
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 04/24/05 Spud 12 1/4" surface hole. Dother During Describe Proposed work or recompletion.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Ceted operations. (Clearly state a k). SEE RULE 1103. For Multiplication of the ceted to 245°. Ran 5 jts (222.35°)	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Ill pertinent details, and tiple Completions: At 5') of 9 5/8", 36#, J-55	K	ALTERNG CASING AND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or completion or recompletion.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Ceted operations. (Clearly state a k). SEE RULE 1103. For Multiplication of the ceted to 245°. Ran 5 jts (222.35°)	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Ill pertinent details, and tiple Completions: At 5') of 9 5/8", 36#, J-55	K	ALTERNG CASING AND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 04/24/05 Spud 12 1/4" surface hole. Dother During Describe Proposed work or recompletion.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Ceted operations. (Clearly state a k). SEE RULE 1103. For Multiplication of the complete to 245°. Ran 5 jts (222.33°.) Cl "B" cement with 2 % CaCl ₂ and Cl "B" cement with 2 % CaCl ₂ and Cl "B" cement with 2 % CaCl ₂ and Cl "B" cement with 2 % CaCl ₂ and Cl "B" cement with 2 % CaCl ₂ and Cl "B" cement with 2 % CaCl ₂ and Cl "B" cement with 2 % CaCl ₂ and Cl "B" cement with 2 % CaCl ₂ and Cl "B" cement with 2 % CaCl ₂ and Cl "B" cement with 2 % CaCl ₂ and Cl "B" cement with 2 % CaCl ₂ and Cl "B" cement with 2 % CaCl ₂ and Cl "B" cement with 2 % CaCl ₂ and Cl "B" cement with 2 % CaCl ₂ and Cl "B" cement with 2 % CaCl ₂ and C	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Ill pertinent details, and tiple Completions: At 5') of 9 5/8", 36#, J-55	K	ALTERNG CASING AND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 04/24/05 Spud 12 1/4" surface hole. Describe with 250 sx (295 cu.ft.) of 04/25/05 Nippled up the BOP. Pressi	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Ceted operations. (Clearly state a k). SEE RULE 1103. For Multiplication of the state of the ceted operations of the ceted operations of the ceted operations. (Clearly state a k). SEE RULE 1103. For Multiplication of the ceted operations of the ceted operations of the ceted operations. (Clearly state a k). SEE RULE 1103. For Multiplication of the ceted operations of	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Ill pertinent details, and tiple Completions: At 5') of 9 5/8", 36#, J-5: and ½ #/sk. flocele. Reference of the completion of	K	ALTERING CASING AND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 04/24/05 Spud 12 ¼" surface hole. Describe with 250 sx (295 cu.ft.) of 04/25/05 Nippled up the BOP. Presson Duly 104/29/05 Ran 104 jts (3772.89") of 7"	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Ceted operations. (Clearly state a k). SEE RULE 1103. For Multiplication of the Research of the Carlo o	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Ill pertinent details, and tiple Completions: At 5') of 9 5/8", 36#, J-5: and ¼ #/sk. flocele. Remaind landed at 3785'. In	K	ALTERING CASING AND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 04/24/05 Spud 12 ¼" surface hole. Describe with 250 sx (295 cu.ft.) of 04/25/05 Nippled up the BOP. Presson Described by the BOP. Described by the BOP. Presson Described by the BOP. Described by the	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL CHEE operations. (Clearly state a k). SEE RULE 1103. For Multiplication of the complete of the co	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Ill pertinent details, and tiple Completions: At 15') of 9 5/8", 36#, J-53 and ½ #/sk. flocele. Remaind landed at 3785'. In ponite, 1/4 #sk celloflak	K	ALTERING CASING AND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 04/24/05 Spud 12 ¼" surface hole. Describe with 250 sx (295 cu.ft.) of 04/25/05 Nippled up the BOP. Presson Duly 104/29/05 Ran 104 jts (3772.89") of 7"	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL CHEE operations. (Clearly state a k). SEE RULE 1103. For Multiplication of the complete of the co	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Ill pertinent details, and tiple Completions: At 15') of 9 5/8", 36#, J-53 and ½ #/sk. flocele. Remaind landed at 3785'. In ponite, 1/4 #sk celloflak	K	ALTERING CASING AND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 04/24/05 Spud 12 ¼" surface hole. Describe Describe proposed work or recompletion. 04/24/05 Spud 12 ½" surface hole. Describe De	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL CHEE operations. (Clearly state a k). SEE RULE 1103. For Multiplication of the complete of the co	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Ill pertinent details, and tiple Completions: At 15') of 9 5/8", 36#, J-5; and 1/4 #/sk. flocele. Remaind landed at 3785'. In the point of	LLING OPNS. FILLING OPNS. FILL	ALTERING CASING AND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 04/24/05 Spud 12 ¼" surface hole. Describe Describe proposed work or recompletion. 04/25/05 Spud 12 ½" surface hole. Describe Des	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Completed operations. (Clearly state a k). SEE RULE 1103. For Multiplication of the complete to 245°. Ran 5 jts (222.33°. Cl "B" cement with 2 % CaCl ₂ are test the casing to 600 psi. Complete to 245°. ST&C new casing a pozymith 2% CaCl ₂ , 5#/sk gilsone. Bumped plug to 1500 psi. FKB. Ran 159 jts (6598.56°) of	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Ill pertinent details, and tiple Completions: At and 1/4 #/sk. flocele. Remaind landed at 3785'. In onite, 1/4 #sk celloflak float held OK. 4 1/2", 11.6#, j-55, L	LLING OPNS. FILLING OPNS. FILL	and set at 237' KB. ment to the surface. Cemented with 525 sx ed by 100 sx (118 cu.ft)
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 04/24/05 Spud 12 ¼" surface hole. Describe proposed work or recompletion. 04/25/05 Nippled up the BOP. Presson Describe proposed work of the proposed	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Cated operations. (Clearly state as k). SEE RULE 1103. For Multiplication of the case of the	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Ill pertinent details, and tiple Completions: At and 1/4 #/sk. flocele. Remaind landed at 3785'. In onite, 1/4 #sk celloflak float held OK. 4 1/2", 11.6#, j-55, L	LLING OPNS. FILLING OPNS. FILL	and set at 237' KB. ment to the surface. Cemented with 525 sx ed by 100 sx (118 cu.ft)
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 04/24/05 Spud 12 ¼" surface hole. Describe Describe proposed work or recompletion. 04/25/05 Spud 12 ½" surface hole. Describe Des	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL CHEE operations. (Clearly state a k). SEE RULE 1103. For Multiplication of the complete of the co	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Ill pertinent details, and tiple Completions: At and 1/4 #/sk. flocele. Remained at 3785'. In the content of the content o	LLING OPNS. FILLING OPNS. FILL	ALTERING CASING AND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 04/24/05 Spud 12 ¼" surface hole. Describe proposed work or recompletion. 04/25/05 Nippled up the BOP. Presson Describe proposed work of the proposed	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL CHEE operations. (Clearly state a k). SEE RULE 1103. For Multiplication of the complete of the co	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Ill pertinent details, and tiple Completions: At and 1/4 #/sk. flocele. Remained at 3785'. In the content of the content o	LLING OPNS. FILLING OPNS. FILL	ALTERING CASING AND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 04/24/05 Spud 12 ¼" surface hole. Describe proposed work or recompletion. 04/25/05 Nippled up the BOP. Presson Describe proposed work of the proposed	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL CHEE operations. (Clearly state a k). SEE RULE 1103. For Multiplication of the complete of the co	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Ill pertinent details, and tiple Completions: At and 1/4 #/sk. flocele. Remaind landed at 3785'. In onite, 1/4 #sk celloflak float held OK. 4 1/2", 11.6#, j-55, L	LLING OPNS. FILLING OPNS. FILL	ALTERING CASING AND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 04/24/05 Spud 12 ¼" surface hole. Describe proposed work or recompletion. 04/25/05 Nippled up the BOP. Presson Describe proposed work of the proposed	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Completed operations. (Clearly state a k). SEE RULE 1103. For Multiplication of the complete to 245°. Ran 5 jts (222.33°. Cl "B" cement with 2 % CaCl ₂ are test the casing to 600 psi. Complete to 245°. ST&C new casing a population of the complete to 1500 psi. For Multiplication of the complete to the co	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Ill pertinent details, and tiple Completions: At the completions of 9 5/8", 36#, J-55 and 1/4 #/sk. flocele. Remainded at 3785'. In the content of the	LLING OPNS. FILLING OPNS. FILL	ALTERING CASING AND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 04/24/05 Spud 12 ¼" surface hole. Describe proposed work or recompletion. 04/24/05 Spud 12 ¼" surface hole. Describe proposed work of recompletion. 04/25/05 Nippled up the BOP. Presson of 25/05 Nippled up the BOP. Presson of 25/05 Ran 104 jts (3772.89") of 7" (1029 cu.ft.) of Halliburton Lite 65/33 of class "B" neat with ½#/sk celloflak 05/02/05 TD well 6 ¼" hole to 6598" Float collar is at 6575" KB. Cemente flocele. Bumped plug to 1600 psi, for the collar is at 6575 to 1600 psi, for	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Completed operations. (Clearly state a k). SEE RULE 1103. For Multiplication of the complete to 245°. Ran 5 jts (222.33°. Cl "B" cement with 2 % CaCl ₂ are test the casing to 600 psi. Complete to 245°. ST&C new casing a population of the complete to 1500 psi. For Multiplication of the complete to the co	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Ill pertinent details, and tiple Completions: At the completions of 9 5/8", 36#, J-55 and 1/4 #/sk. flocele. Remainded at 3785'. In the content of the	LLING OPNS. FILLING OPNS. FILL	ALTERING CASING AND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 04/24/05 Spud 12 ¼" surface hole. Defended with 250 sx (295 cu.ft.) of 04/25/05 Nippled up the BOP. Presson 04/29/05 Ran 104 jts (3772.89') of 7" (1029 cu.ft.) of Halliburton Lite 65/33 of class "B" neat with ¼#/sk celloflak 05/02/05 TD well 6 ¼" hole to 6598' Float collar is at 6575' KB. Cemente flocele. Bumped plug to 1600 psi, for the start of the surface of	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Completed operations. (Clearly state as k). SEE RULE 1103. For Multiplication of the complete to 245°. Ran 5 jts (222.33°. Cl "B" cement with 2 % CaCl ₂ and the casing to 600 psi. Complete to 245°. ST&C new casing a pozymith 2% CaCl ₂ , 5#/sk gilson. Bumped plug to 1500 psi. For KB. Ran 159 jts (6598.56°) of d with 360 sx (526 cu. ft.) 50/50 doubtheld ok.	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Ill pertinent details, and tiple Completions: At tiple Completions: At the completions of the completions of the completions of the completion	LLING OPNS. To Find the stack wellbore diagram 5, ST&C new casing eturned 15bbls of cerusert float at 3747'. One and 6% gel, follow To Find To Find the stack wellbore diagram 10% Halad 9, 1/10% of the stack wellbore diagram To Find the stack well by the stack wellbore diagram 10% Halad 9, 1/10% of the stack well by the stack well	ALTERING CASING AND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 04/24/05 Spud 12 ¼" surface hole. Describe proposed work or recompletion. 04/25/05 Nippled up the BOP. Presson Describe proposed work of the proposed	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Completed operations. (Clearly state a k). SEE RULE 1103. For Multiplication of the complete to 245°. Ran 5 jts (222.33°. Cl "B" cement with 2 % CaCl ₂ are test the casing to 600 psi. Complete to 245°. ST&C new casing a population of the complete to 1500 psi. For Multiplication of the complete to the co	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Ill pertinent details, and tiple Completions: At the completions of 9 5/8", 36#, J-55 and 1/4 #/sk. flocele. Remainded at 3785'. In the completion of 1/4 #/sk celloflak float held OK to the completion of 1/2", 11.6#, J-55, LOSTD/POZ, 3%gel, 6/10 ORT CENTER OF THE COMPLET CENTER OF THE CENTER OF THE COMPLET CENTER OF THE CENTER OF	LLING OPNS. To Find the stack wellbore diagram 5, ST&C new casing eturned 15bbls of cerusert float at 3747'. One and 6% gel, follow To Find To Find the stack wellbore diagram 10% Halad 9, 1/10% of the stack wellbore diagram To Find the stack well by the stack wellbore diagram 10% Halad 9, 1/10% of the stack well by the stack well	ALTERING CASING AND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 04/24/05 Spud 12 ¼" surface hole. Describe proposed work or recompletion. 04/25/05 Spud 12 ¼" surface hole. Describe proposed work or recompletion. 04/25/05 Nippled up the BOP. Presson O4/29/05 Ran 104 jts (3772.89") of 7" (1029 cu.ft.) of Halliburton Lite 65/3: of class "B" neat with ¼#/sk celloflate 05/02/05 TD well 6 ¼" hole to 6598". Float collar is at 6575" KB. Cemente flocele. Bumped plug to 1600 psi, for the surface of the sur	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL cted operations. (Clearly state a k). SEE RULE 1103. For Multiplication of the complete to 245°. Ran 5 jts (222.33°. Cl "B" cement with 2 % CaCl ₂ are test the casing to 600 psi. cted operations. (Clearly state a k). SEE RULE 1103. For Multiplication of the complete to 425°. Ran 5 jts (222.33°. Cl "B" cement with 2 % CaCl ₂ are test the casing to 600 psi. cted operations. (Clearly state a k). See RULE 1103. For Multiplication of the complete to the complete to the closed according to NMOCD guideline. TITLE	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Ill pertinent details, and tiple Completions: At tiple Completions: At the second of the sec	LLING OPNS. FILLING OPNS. FILL	including estimated date of proposed completion and set at 237' KB. ment to the surface. Cemented with 525 sx ed by 100 sx (118 cu.ft) Assing set at 6397' KB. CFR3, 5# gilsonite, 1/4# Certify that any pit or belowive OCD-approved plan DATE 09/22/05
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 04/24/05 Spud 12 ¼" surface hole. Describe with 250 sx (295 cu.ft.) of 04/25/05 Nippled up the BOP. Presson 04/29/05 Ran 104 jts (3772.89") of 7" (1029 cu.ft.) of Halliburton Lite 65/3: of class "B" neat with ¼#/sk celloflak 05/02/05 TD well 6 ¼" hole to 6598". Float collar is at 6575" KB. Cemente flocele. Bumped plug to 1600 psi, for the surface of the surface	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL cted operations. (Clearly state a k). SEE RULE 1103. For Multiplication of the complete to 245°. Ran 5 jts (222.33°. Cl "B" cement with 2 % CaCl ₂ are test the casing to 600 psi. cted operations. (Clearly state a k). SEE RULE 1103. For Multiplication of the complete to 425°. Ran 5 jts (222.33°. Cl "B" cement with 2 % CaCl ₂ are test the casing to 600 psi. cted operations. (Clearly state a k). See RULE 1103. For Multiplication of the complete to the complete to the closed according to NMOCD guideline. TITLE	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Ill pertinent details, and tiple Completions: At tiple Completions: At the second of the sec	LLING OPNS. FILLING OPNS. FILL	ALTERING CASING AND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 04/24/05 Spud 12 ¼" surface hole. Describe proposed work or recompletion. 04/25/05 Spud 12 ¼" surface hole. Describe proposed work or recompletion. 04/25/05 Nippled up the BOP. Presson O4/29/05 Ran 104 jts (3772.89") of 7" (1029 cu.ft.) of Halliburton Lite 65/3: of class "B" neat with ¼#/sk celloflate 05/02/05 TD well 6 ¼" hole to 6598". Float collar is at 6575" KB. Cemente flocele. Bumped plug to 1600 psi, for the surface of the sur	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL eted operations. (Clearly state a k). SEE RULE 1103. For Multiplication of the complete to 245°. Ran 5 jts (222.35°. Cl "B" cement with 2 % CaCl ₂ and the casing to 600 psi. 7, 20#, J-55, ST&C new casing a complete to the complete to t	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Ill pertinent details, and tiple Completions: At the completions of the completion of the completi	LLING OPNS. To For Jobs. In Jobs.	including estimated date of proposed completion and set at 237' KB. ment to the surface. Cemented with 525 sx ed by 100 sx (118 cu.ft) asing set at 6397' KB. CFR3, 5# gilsonite, 1/4# Certify that any pit or belowive OCD-approved plan DATE 09/22/05 b. 505-327-4892
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 04/24/05 Spud 12 ¼" surface hole. Describe with 250 sx (295 cu.ft.) of 04/25/05 Nippled up the BOP. Presson 04/29/05 Ran 104 jts (3772.89") of 7" (1029 cu.ft.) of Halliburton Lite 65/3: of class "B" neat with ¼#/sk celloflak 05/02/05 TD well 6 ¼" hole to 6598". Float collar is at 6575" KB. Cemente flocele. Bumped plug to 1600 psi, for the surface of the surface	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL eted operations. (Clearly state a k). SEE RULE 1103. For Multiplication of the complete to 245°. Ran 5 jts (222.35°. Cl "B" cement with 2 % CaCl ₂ and the casing to 600 psi. 7, 20#, J-55, ST&C new casing a complete to the complete to t	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: Ill pertinent details, and tiple Completions: At tiple Completions: At the second of the sec	LLING OPNS. To For Jobs. In Jobs.	including estimated date of proposed completion and set at 237' KB. ment to the surface. Cemented with 525 sx ed by 100 sx (118 cu.ft) Assing set at 6397' KB. CFR3, 5# gilsonite, 1/4# Certify that any pit or belowive OCD-approved plan DATE 09/22/05