er e be							
Form 3160-5 (August 1999)	UNITED STATES DEPARTMENT OF THE INTERIOR		FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000				
A SUNDR	BUREAU OF LAND MA			5. Lease:	Serial No. 20 - 1003 - 5	85	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.			en E	6. If Indian, Allottee or Tribe Name			
abandoned well. Use Full 3160-3 (AFD) for such proposals.					Navajo Tribal		
SUBMIT IN TRIPLICATE - Other instructions on reverse side					or CA/Agreement, Nan	ne and/or No.	
1. Type of Well		· · · · · · · · · · · · · · · · · · ·					
Oil Well Gas Well Other					8. Well Name and No. NOW 9: API Well No.		
12. Name of Operator Hart Oil of Chas; Inc.							
3a. Address SOON (Ap. of N. HWA (USA)) N HRHY 372-1037-10334					5/09 7500 and Pool, or Exploratory	<u>51</u>	
4. Location of Well (Footage, Sec.	T. R. M. or Survey Descrip)37	J 1/1	eshue Gal	WD	
990' FNL 2 990 FUL TUPICAT LGEILON SEC DTR			11. County or Parish, State				
31N 17W	10 NWNH	J		Jan	Juan, N	. M.	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
TYPE OF SUBMISSION		TY	PE OF ACTION				
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Production (Start	/Resume)	Water Shut-Off Well Integrity		
Subsequent Report	Casing Repair Change Plans	New Construction Plug and Abandon	Recomplete Temporarily Ab	andon	Other		
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal				
13. Describe Proposed or Complete If the proposal is to deepen dire Attach the Bond under which It following completion of the investing has been completed. Fit determined that the site is ready OF PER OBAMA ONE	ctionally or recomplete horizon ne work will be performed or olved operations. If the opera nal Abandonment Notices sha	ntally, give subsurface location provide the Bond No. on file tion results in a multiple com Il be filed only after all requi	ns and measured and trewith BLM/BIA. Requipelition or recompletion rements, including reclased by the plant of the plant o	e vertical depred subsequer in a new inter mation, have	pths of all pertinent man nt reports shall be filed rval, a Form 3160-4 sha been completed, and t	kers and zones. within 30 days all be filed once	

Name (Printed/Typed) Title Date ACCEPTED FOR RECORD THIS SPACE FOR FEDERAL OR STATE OFFICE USE OCT 19 2005 Approved by Title Date Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. FARMINGTON FIELD OFFICE BY Office

14. I hereby certify that the foregoing is true and correct

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

	5.	Lease Number BIA #14-20-603-2034				
1.	Type of Well 6.	If Indian, All. or Tribe Name				
	Water Supply Well 7.	Unit Agreement Name				
2.	Name of Operator	om / groomon rumo				
	Hart Oil and Gas, Inc.	Well Name & Number				
3.		Navajo TI "F" #1				
	500 Capital Texas Highway, North, Austin, TX, 78746 (512) 637-6334 9.	API Well No . 30-045-1097500S1				
4.	Location of Well, Footage, Sec., T, R, M					
	990' FNL and 990' FWL, Section 10, T-31-N, R-17-W,	Horseshoe Gallup County & State San Juan County, NM				
12.	. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER	DATA				
	Type of Submission Type of Action Notice of Intent X Abandonment Change of Plans					
	Notice of Intent _X_ Abandonment Change of Plans New Construction	14.0-20 34 14.1-2034				
	X Subsequent Report Plugging Back Non-Routine Fracturing					
	Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection Other -	e a dame				
40	— Describe Brancod or Completed Or continue					
13.	 Describe Proposed or Completed Operations A-Plus Well Service Plugged and Abandoned this well on September 7, 200 	5 per the following:				
8/3	s1/05 MOL and RU rig. Well pressures: 0# tubing, 0# casing, 0# bradenhead. Pull on rods and					
	31 – ¾" rods, 3 – 4' subs and pump. Shut in well.	S 1284				
9/1/	NU BOP on 10.75" companion flange. TOH and LD 25 joints 2.875" tubing. TIH w workstring. Tag unknown object in casing at 885'. Circulate casing clean with 70 bbls of approved setting CR. TOH with 2.375" tubing. RIH with 8.625" gauge ring to 883'. RIH at 875'. TIH with 27 joints 2.375" tubing and 2 - 10' subs. Sting into CR. Attempt to establis up to 600#. Pressure would bleed off to 0# in 5 minutes. Sting out of CR. Plug #1 with 9 cf) inside the casing from 875' up to 534' to isolate the Gallup interval. TOH with tubing. S	water. Steve Mason, BLM, nd set 8.625" wireline CR at h rate under CR, pressured: 4 05 sxs Type III cement (125				
9/2/	TIH and tag cement at 522'. Circulate casing clean. Attempt to pressure test casing, water started circulating around wellhead. Shut in well. Dig down 4.5' and found another wellhead flange with the bradenhead. TOH and LD 2.375" tubing. Perforate 3 holes at 168'. Attempt to circulate out BH, established circulation immediately. TIH with 7 joints 2.375" tubing to 221'. Shut in casing valve. Circulate oil out BH with 8 bbls of water. Plug #2 with 100 sxs Type III cement (132 cf) inside the casing from 221' to surface with 47 sxs cement, then fill BH annulus with 53 sxs from 168'					
9/6/	to surface, circulate good cement out BH. TOH and LD all tubing. Shut in well and WOC. ND BOP and flange with spool. Dig out around wellhead. Cut off wellhead. Found cement at down 10' in the casing and at surface in the annulus. Mix 15 sxs cement to fill casing & annulus and then install P&A marker. RD and MOL. Val Jameson, Navajo Nation Minerals, was on location.					
SIG	GNATURE September 3	30. 2005				
	William F. Clark	010				
(Th	nis space for Federal or State Office use)	Plas				
ΔΡΙ	PROVED BY Title	Date				
	ONDITION OF APPROVAL, if any:	Date				