			. /			
 Submit 3 Copies To Appropriate Dis Office 		State of New Me				orm C-103
District I		linerals and Natu	iral Resources	WELL API NO		March 4, 200
1625 N. French Dr., Hobbs, NM 882 District II				30-045-25028	•	
1301 W. Grand Ave., Artesia, NM 88		NSERVATION		5. Indicate Typ	e of Lease	
District III 1000 Rio Brazos Rd., Aztec, NM 874	410	0 South St. Fra		STATE		\boxtimes
District IV 1220 S. St. Francis Dr., Santa Fe, NM	2	Santa Fe, NM 8'	7505.	6. State Oil & (Gas Lease No.	
87505						
SUNDRY	NOTICES AND REPO	ORTS ON WELLS		7. Lease Name	or Unit Agreer	nent Name
(DO NOT USE THIS FORM FOR P DIFFERENT RESERVOIR. USE "A	ROPOSALS TO DRILL OF	R TO DEEPEN OR PL	UG BACK TO A			
PROPOSALS.)				Kirtland 8. Well Numbe		
1. Type of Well: Oil Well Gas Wel	1 M Other	DE DE	EC 2004	8	1	
			55	0.00000		
2. Name of Operator	2000	SE OR C		9. OGRID Nun 019219	nber	
Richardson Operating Corr 3. Address of Operator	ipany		NARTH CONT	10. Pool name of	or Wildcat	
3100 La Plata Highway, Fa	arminaton, NM 8740	1 200	. SI	Cha Cha Gallu		
4. Well Location			20,057		P	
			Calle Callander			
Unit Letter O	:510feet	from theSouth	line and192	20feet from	m theEast_	line
	_		·			
Section 11			Range 15W		County	San Juan
		Show whether DR,	. RKB, RT, GR, etc.)			
Pit or Below-grade Tank Application	5126' GL	tank closures a form	C 144 must be attached			
				_		
Pit Location: UL Sect 7	FwpRngPit	typeD	epth to Groundwater	Distance from	nearest fresh wat	er well
Distance from nearest surface wat	ter Below-grade	Tank Location 11	~ —	E.		
			Sect Two	Rng	:	
			SectTwp_	Kng	;	
feet from theline			SectTwp_	Kng	;	
feet from theline :			SectTwp_	Kng	;	
	andfeet from the	eline		·		
12. Che	andfeet from the eck Appropriate Bo	eline	ature of Notice, I	Report or Othe	r Data	
12. Che NOTICE O	andfeet from the eck Appropriate Bo F INTENTION TO	eline ox to Indicate N O:	ature of Notice, I	Report or Othe SEQUENT RE	r Data EPORT OF	
12. Che	andfeet from the eck Appropriate Bo F INTENTION TO	eline ox to Indicate N O:	ature of Notice, I	Report or Othe SEQUENT RE	r Data	
12. Che NOTICE O	andfeet from the eck Appropriate Bo F INTENTION TO	eline ox to Indicate N O: BANDON []	ature of Notice, I	Report or Othe SEQUENT RE	r Data EPORT OF ALTERING (PLUG AND	
12. Che NOTICE OI PERFORM REMEDIAL WORF TEMPORARILY ABANDON	andfeet from the eck Appropriate Bo F INTENTION TO K PLUG AND AB	eline Dx to Indicate N D: BANDON [] NS []	ature of Notice, J SUBS REMEDIAL WORK COMMENCE DRIL	Report or Othe SEQUENT RE	r Data EPORT OF ALTERING (
12. Che NOTICE OI PERFORM REMEDIAL WORK	andfeet from the eck Appropriate Bo F INTENTION TO K PLUG AND AB	eline Dx to Indicate N D: BANDON [] NS [] []	ature of Notice, J SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN	Report or Othe SEQUENT RE	r Data EPORT OF ALTERING (PLUG AND	
12. Che NOTICE OI PERFORM REMEDIAL WORF TEMPORARILY ABANDON	andfeet from the eck Appropriate Bo F INTENTION TO K PLUG AND AB	eline Dx to Indicate N D: BANDON [] NS [] []	ature of Notice, J SUBS REMEDIAL WORK COMMENCE DRIL	Report or Othe SEQUENT RE	r Data EPORT OF ALTERING (PLUG AND	
12. Che NOTICE OI PERFORM REMEDIAL WORF TEMPORARILY ABANDON	andfeet from the eck Appropriate Bo F INTENTION TO K PLUG AND AB	eline Dx to Indicate N D: BANDON [] NS [] []	ature of Notice, J SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN	Report or Othe SEQUENT RE	r Data EPORT OF ALTERING (PLUG AND	
12. Che NOTICE OI PERFORM REMEDIAL WORF TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or c	andfeet from the eck Appropriate Bo F INTENTION TO K PLUG AND AB CHANGE PLAI MULTIPLE COMPLETION	eline Dox to Indicate N D: BANDON NS D (Clearly state all p	ature of Notice, J SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: pertinent details, and	Report or Othe SEQUENT RE LING OPNS. D	r Data EPORT OF ALTERING (PLUG AND ABANDONN	
12. Che NOTICE OI PERFORM REMEDIAL WORF TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	andfeet from the eck Appropriate Bo F INTENTION TO K PLUG AND AB CHANGE PLAI MULTIPLE COMPLETION	eline Dox to Indicate N D: BANDON NS D (Clearly state all p	ature of Notice, J SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: pertinent details, and	Report or Othe SEQUENT RE LING OPNS. D	r Data EPORT OF ALTERING (PLUG AND ABANDONN	
12. Che NOTICE OI PERFORM REMEDIAL WORF TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or c	andfeet from the eck Appropriate Bo F INTENTION TO K PLUG AND AB CHANGE PLAI MULTIPLE COMPLETION	eline Dox to Indicate N D: BANDON NS D (Clearly state all p	ature of Notice, J SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: pertinent details, and	Report or Othe SEQUENT RE LING OPNS. D	r Data EPORT OF ALTERING (PLUG AND ABANDONN	
12. Che NOTICE OI PERFORM REMEDIAL WORF TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or c of starting any propose or recompletion.	andfeet from the eck Appropriate Bo F INTENTION TO K PLUG AND AB CHANGE PLAN CHANGE PLAN MULTIPLE COMPLETION completed operations. ed work). SEE RULE	eline Dox to Indicate N D: BANDON NS D (Clearly state all p	ature of Notice, J SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: pertinent details, and	Report or Othe SEQUENT RE LING OPNS. D	r Data EPORT OF ALTERING (PLUG AND ABANDONN	
12. Che NOTICE OI PERFORM REMEDIAL WORF TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or co of starting any propose	andfeet from the eck Appropriate Bo F INTENTION TO K PLUG AND AB CHANGE PLAN CHANGE PLAN MULTIPLE COMPLETION completed operations. ed work). SEE RULE	eline Dox to Indicate N D: BANDON NS D (Clearly state all p	ature of Notice, J SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: pertinent details, and	Report or Othe SEQUENT RE LING OPNS. D	r Data EPORT OF ALTERING (PLUG AND ABANDONN	
12. Che NOTICE OI PERFORM REMEDIAL WORF TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or c of starting any propose or recompletion.	andfeet from the eck Appropriate Bo F INTENTION TO K PLUG AND AB CHANGE PLAN CHANGE PLAN MULTIPLE COMPLETION completed operations. ed work). SEE RULE	eline Dox to Indicate N D: BANDON NS D (Clearly state all p	ature of Notice, J SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: pertinent details, and	Report or Othe SEQUENT RE LING OPNS. D	r Data EPORT OF ALTERING (PLUG AND ABANDONN	
12. Che NOTICE OI PERFORM REMEDIAL WORF TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or c of starting any propose or recompletion.	andfeet from the eck Appropriate Bo F INTENTION TO K PLUG AND AB CHANGE PLAN CHANGE PLAN MULTIPLE COMPLETION completed operations. ed work). SEE RULE	eline Dox to Indicate N D: BANDON NS D (Clearly state all p	ature of Notice, J SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: pertinent details, and	Report or Othe SEQUENT RE LING OPNS. D	r Data EPORT OF ALTERING (PLUG AND ABANDONN	
12. Che NOTICE OI PERFORM REMEDIAL WORF TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or c of starting any propose or recompletion.	andfeet from the eck Appropriate Bo F INTENTION TO K PLUG AND AB CHANGE PLAN CHANGE PLAN MULTIPLE COMPLETION completed operations. ed work). SEE RULE	eline Dox to Indicate N D: BANDON NS D (Clearly state all p	ature of Notice, J SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: pertinent details, and	Report or Othe SEQUENT RE LING OPNS. D	r Data EPORT OF ALTERING (PLUG AND ABANDONN	
12. Che NOTICE OI PERFORM REMEDIAL WORF TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or c of starting any propose or recompletion. Well was plugged per attache	andfeet from the eck Appropriate Bo F INTENTION TO K PLUG AND AB CHANGE PLAN MULTIPLE COMPLETION completed operations. ed work). SEE RULE ed procedure.	eline Dx to Indicate N D: BANDON NS (Clearly state all p 1103. For Multipl	ature of Notice, I SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: pertinent details, and e Completions: Atta	Report or Othe SEQUENT RE LING OPNS. D	r Data EPORT OF ALTERING (PLUG AND ABANDONM tes, including e ram of propose	CASING
12. Che NOTICE OI PERFORM REMEDIAL WORF TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or c of starting any propose or recompletion.	andfeet from the eck Appropriate Bo F INTENTION TO K PLUG AND AB CHANGE PLAN CHANGE PLAN MULTIPLE COMPLETION completed operations. ed work). SEE RULE ed procedure.	eline Dx to Indicate N D: BANDON NS Clearly state all p 1103. For Multipl	ature of Notice, I SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: pertinent details, and e Completions: Atta	Report or Othe SEQUENT RE LING OPNS. D	r Data EPORT OF ALTERING (PLUG AND ABANDONM tes, including e ram of propose	ASING The second
12. Che NOTICE OI PERFORM REMEDIAL WORF TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or c of starting any propose or recompletion. Well was plugged per attache	andfeet from the eck Appropriate Bo F INTENTION TO K PLUG AND AB CHANGE PLAN MULTIPLE COMPLETION completed operations. ed work). SEE RULE ed procedure.	e line Dx to Indicate N D: BANDON NS Clearly state all p 1103. For Multiple complete to the be NMOCD guidelines	ature of Notice, I SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: pertinent details, and e Completions: Atta	Report or Othe SEQUENT RE LING OPNS. D give pertinent da ach wellbore diag	r Data EPORT OF ALTERING O PLUG AND ABANDONW tes, including e ram of propose	PENT
12. Che NOTICE OI PERFORM REMEDIAL WORF TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or c of starting any propose or recompletion. Well was plugged per attache	andfeet from the eck Appropriate Bo F INTENTION TO K PLUG AND AB CHANGE PLAN MULTIPLE COMPLETION completed operations. ed work). SEE RULE ed procedure.	e line Dx to Indicate N D: BANDON NS Clearly state all p 1103. For Multiple complete to the be NMOCD guidelines	ature of Notice, I SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: pertinent details, and e Completions: Atta	Report or Othe SEQUENT RE LING OPNS. D give pertinent da ach wellbore diag	r Data EPORT OF ALTERING (PLUG AND ABANDONM tes, including e ram of propose	v pit or below-oved plan .
12. Che NOTICE OI PERFORM REMEDIAL WORF TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or c of starting any propose or recompletion. Well was plugged per attache I hereby certify that the informa grade tank has been/will be construct SIGNATURE <u>Prov</u>	andfeet from the eck Appropriate Bo F INTENTION TO K PLUG AND AB CHANGE PLAN MULTIPLE COMPLETION completed operations. ed work). SEE RULE ed procedure.	eline Dx to Indicate N D: BANDON NS Clearly state all p 1103. For Multiple complete to the be NMOCD guidelines TITLE_E	ature of Notice, I SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: pertinent details, and e Completions: Atta	Report or Othe SEQUENT RE LING OPNS. D D give pertinent da ach wellbore diag	r Data EPORT OF ALTERING (PLUG AND ABANDONM tes, including e ram of propose her certify that an native OCD-appr ATE_12/8/04	v pit or below- oved plan
12. Che NOTICE OI PERFORM REMEDIAL WORF TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or c of starting any propose or recompletion. Well was plugged per attache	andfeet from the eck Appropriate Bo F INTENTION TO K PLUG AND AB CHANGE PLAN MULTIPLE COMPLETION completed operations. ed work). SEE RULE ed procedure.	eline Dx to Indicate N D: BANDON NS Clearly state all p 1103. For Multiple complete to the be NMOCD guidelines TITLE_E	ature of Notice, I SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: pertinent details, and e Completions: Atta	Report or Othe SEQUENT RE LING OPNS. D give pertinent da ach wellbore diag	r Data EPORT OF ALTERING O PLUG AND ABANDONW tes, including e ram of propose	PENT
12. Che NOTICE OI PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or co of starting any propose or recompletion. Well was plugged per attached I hereby certify that the informa grade tank has been/will be construct SIGNATURE <u>P</u> <u>P</u> Type or print name Ryan Brui	andfeet from the eck Appropriate Bo F INTENTION TO K PLUG AND AB CHANGE PLAN MULTIPLE COMPLETION completed operations. ed work). SEE RULE ed procedure.	eline Dx to Indicate N D: BANDON NS Clearly state all p 1103. For Multiple complete to the be NMOCD guidelines TITLE_E	ature of Notice, I SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: pertinent details, and e Completions: Atta	Report or Othe SEQUENT RE LING OPNS. D give pertinent da ach wellbore diag	r Data EPORT OF ALTERING (PLUG AND ABANDONM tes, including e ram of propose her certify that an native OCD-appr ATE_12/8/04	PENT
12. Che NOTICE OI PERFORM REMEDIAL WORF TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or c of starting any propose or recompletion. Well was plugged per attache I hereby certify that the informa grade tank has been/will be construct SIGNATURE <u>Prov</u>	andfeet from the eck Appropriate Bo F INTENTION TO K PLUG AND AB CHANGE PLAN MULTIPLE COMPLETION completed operations. ed work). SEE RULE ed procedure.	eline Dx to Indicate N D: BANDON NS Clearly state all p 1103. For Multiple complete to the be NMOCD guidelines TITLE_E	ature of Notice, I SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: pertinent details, and e Completions: Atta	Report or Othe SEQUENT RE LING OPNS. D give pertinent da ach wellbore diag	r Data EPORT OF ALTERING (PLUG AND ABANDONM tes, including e ram of propose her certify that an native OCD-appr ATE_12/8/04	v pit or below- oved plan

Kirtland #8 P&A Procedure

7/27/2004: MIRU. Lay down tbg.

7/28/2004: TIH w/ tbg. to 4625'. Circulate hole clean. Mix and pump 70sx Class B cement , 15.6ppg. Spot plug 4625'-3779'. TOH to 2500'.

7/29/2004: TIH w/ tbg. Tag cement top at 3779'. Pressure test to 500psi, held ok. TOH w/ tbg. Run CBL. TOC @ 600'. Shoot squeeze holes @ 550'. Pump 9bbl water. Locked up. TIH to 595'.

7/30/2004: Mix and pump 12sx Class B cement, 15.6ppg. Plug from 595'-395'. TOH to 400'. Circulate hole clean. TOH. Shoot squeeze holes @ 375'. Could not pump into hole. TIH to 395'. Mix and pump 55sx Class B cement, 15.6ppg. Bring cement to surface. Cut off wellhead, no cement in surface pipe. TIH in surface pipe to 64'.

7/31/2004: Tbg at 64' in surface pipe. Mix and pump 36sx Class B cement, 15.6ppg. Bring cement to surface. TOH.

8/2/2004: Install P&A marker.

