



OCT 14 2015

Ground Elevation 5774'
KB Measurement 5779'**GALLEGOS CANYON UNIT 335**

Fruitland Sand/Pictured Cliffs

API #30-045-2544700

Unit I - Sec 14 - T28N - R12W

San Juan County, NM

Well History

12/14/83: Spud date

4/7/1997: Well Servicing

6/9/98: Well Seivicing

8/2/00: Changed out 26 jts of tubing. Tubing was rod cut and pump failed. Cleaned out and ran new pump.

2/26/02: Well Servicing: Changed rods. Found hole in bottom joint in tubing. Ran new tubing, rods, and pump.

4/16/2002: Recompleted Fruitland sand and commingled downhole

11/5/04: Well Servicing.

Formation Tops

Ojo Alamo	406
Kirtland	502
Fruitland	1348
Pictured Cliff	1630

TOC: Circulated to surface

Surface Casing Data

9 7/8" hole

7 5/8" K55 26.4# casing to 129'

Cement w/ 75 sx Class B

TOC: Circulated to surface

Rod Details

	<u>Length</u>
POLISHED ROD 1.25"	16
POLISHED ROD 0.75", PONY ROD	4
ROD 0.75" D	1325.53
ROD PUMP 2"	9

Tubing Details

	<u>Length</u>
TUBING PUP JOINT 2.375"	4
TUBING JOINTS 2.375" J55 4.7	1332.38
PROFILE NIPPLE 2.375" N80 4.7	1.1
TUBING JOINTS 2.375" J55 4.7	14.7

End of Tubing at 1361.55'

Fruitland Sand Data

1364-1394

Frac'ed w/ 56389# 16/30 brady sand

Frac'e w/ 26000 gals 70Q foam w/ 40000# 10/20 sand

Pictured Cliffs Data

1634-1656'

Breakdown w/ 1000 gals of Pictured Cliffs wtr w/ 20 ball s

Frac'e w/ 26000 gals 70Q foam w/ 40000# 10/20 sand

Production Casing Data

6 1/4 hole

4 1/2" K55 10.5# to 1806'

Cement w/ 350 sx

PBTD 1772'
Total Depth 1815'