Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160 - 3 (APD) for such proposals.

FORM APPROVED OM BING, 1004-0137 Expires: March 31, 200	

5. Lease Serial No. MDA 701980013 Tract 4

If Indian, Allottee or Tribe Name

licarilla A	Apache	Nation
-------------	--------	--------

					Jicarma Apacne Nation		
SUBMIT IN TRIPLICATE- Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well Gas Well Other					32537 8. Well Name and No. Jicarilla 29-02-21 #1		
2. Name of Operator Black Hills Gas Resources, Inc.							
					9. API Well No. 30-039-27463		
3a. Address 350 Indiana Street, Suite 400,	3b. Phone No. (include 720-210-1338	area code)					
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					Pool, or Exploratory Area		
NW/NW Sec. 21, 29N-02W, Unit D 560' FNL and 865' FWL					11. County or Parish, State Rio Arriba Co., New Mexico		
12. CHECK A	PPROPRIATE BOX(ES) TO	INDICATE NATUR	E OF NOTICE, RE	EPORT, OR	OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION						
✓ Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Star Reclamation Recomplete Temporarily Aba Water Disposal	,	Water Shut-Off Well Integrity Other		
If the proposal is to deepen dire		y, give subsurface location	is and measured and true	vertical depths	k and approximate duration thereof. of all pertinent markers and zones.		

Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Black Hills Gas Resources, Inc. recomends to temporarily abandon this well pending the production results of recent completions in offset wells.

Attached are the prodecures to TA this well along with the wellbore diagram.

Notify OCD to witness

 I hereby certify that the foregoing is true and correlation Name (Printed/Typed) 	
Julie Stifflear	

Title Engineering Production Tech

fflier

3-28-2006

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Original Signed: Stephen Mason Approved by

Title

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

Date

Black Hills Gas Resources

New Completion Procedure For the

JICARILLA 29-02-21 #1

API # 30-039-27463

NW NW Sec 21, T29N, R2W Rio Arriba County, New Mexico

GL=7123', KB=7138', TD=3783', PBTD= 3735'

Surface casing:

8-5/8", 24 lb/ft, K-55 LTC @ 280', TOC = surf

Production casing:

 $5\frac{1}{2}$ " 15.5lb/ft, J-55, @ 3743', **TOC** = **Surf**

Current Perforations:

Fruitland Coal: 3456-3480 (Milled casing, Open Hole)

Proposed Work: Temporarily abandon the well bore.

- 1. Conduct safety meeting with all personnel to discuss the scope of this completion.
- 2. MIRU completion rig, ND WH, NU BOP.
- TOOH with 2 3/8" tubing. MU CIBP, TIH with 2 3/8" tubing and set CIBP @ +/- 3400'. 3.
- MIRU pump truck, circulate hole with 2% KCl water containing a biocide. 4.
- 5. TOOH. Lay down pipe and have sent to Tuboscope for inspection.
- 6. Pressure test casing to 500 psi, monitor and record pressure for 30 minutes with the BLM and/or State inspectors to witness the MIT.

Initiated by:

Loren Diede, 3-16-2006

Approved by:

J.T. Albi

First call for services will be:

Perforating/Logging:

none

Frac:

Key PPS

325-4192

Tools:

open

Trucking:


L&G

Jicarilla 29-02-21 #1

TA Wellbore Diagram API # 30-039-27463

UNIT D NW NW Sec 21, T29N, R02W Rio Arriba, NM Spud Date 7-20-03

Elev. GL= 7123' Elev. KB= 7138 '



Prepared: 16-Mar-06