

State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

Ken McQueen
Cabinet Secretary

Matthias Sayer
Deputy Cabinet Secretary

David R. Catanach, Division Director
Oil Conservation Division



September 29, 2017

Hilcorp Energy Company
Attn: Jodi-Lyn Curtis
1111 Travis Street
Houston, TX 77002-7002

Re: Bradenhead Test
Well: Turner 1, UL A Sec 28 Twn 30N Rge 9W, API # 30-045-09226

Dear Ms. Curtis:

The 2017 Bradenhead test was not complete. Remarks on form state that there are no ports for the intermediate string. Wellbore schematic was received on June 27, 2017, and shows that an intermediate exists. The Bradenhead Test Memorandum dated February 14, 2017, states in item 1 "Each casing string valve, surface, **intermediate**, and production must be dug out, plumbed to surface and verified to be in working order **before** testing begins." In order to comply with the Bradenhead Test Memorandum Item #1, you are hereby directed to submit a plan of action and initiate remedial activity before **October 29, 2017**. Once remedial work has been completed, contact this office to set up a date and time to verify valves on all strings and to witness bradenhead test.

Reference: **RBDMS MPK1720943235** on future correspondence for this issue.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 123.

Sincerely yours,

Monica Kuehling
Deputy Oil and Gas Inspector
District III - Aztec

CC: Well File