, 4,						
Form 3160-5 (June 2015) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			OMB N	FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018		
SUNDRY NOTICES AND REPORTS ON WELLS				NMSF078926		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				6. If Indian, Allottee	6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agree	ement, Name and/or No.	
1. Type of Well Oil Well S Gas Well Other					8. Well Name and No. GALLEGOS CANYON UNIT 363	
2. Name of Operator Contact: TOYA COLVIN BP AMERICA PRODUCTION CO E-Mail: Toya.Colvin@bp.com				9. API Well No. 30-045-26882-(9. API Well No. 30-045-26882-00-S1	
3a. Address3b. Phone No. (include area code)200 ENERGY COURTPh: 281.366.7148FARMINGTON, NM 87401Ph: 281.366.7148				BASIN FRUITL	10. Field and Pool or Exploratory Area BASIN FRUITLAND COAL WEST KUTZ PICTURED CLIFFS	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish,	11. County or Parish, State	
Sec 26 T29N R13W NWNE 1265FNL 1805FEL 36.701140 N Lat, 108.172230 W Lon				SAN JUAN CO	SAN JUAN COUNTY, NM	
12. CHECK THE AN	PPROPRIATE BOX(ES) TO) INDICATE NATU	JRE OF N	OTICE, REPORT, OR OTI	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	Acidize	Deepen	C] Production (Start/Resume)	Water Shut-Off	
— .	Alter Casing	Hydraulic Frac	turing	Reclamation	Well Integrity	
Subsequent Report	Casing Repair	New Construct		Recomplete	Other	
□ Final Abandonment Notice	Change Plans] Temporarily Abandon		
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of			Water Disposal	<u></u>		
Attach the Bond under which the wo following completion of the involved testing has been completed. Final At determined that the site is ready for f BP requests to P&A the subje In accordance with NMOCD P operations.	l operations. If the operation results pandonment Notices must be filed of inal inspection. Ct well. Please see the attack	s in a multiple completion only after all requirement hed P&A procedure	n or recompl s, including i and wellbo	etion in a new interval, a Form 316 reclamation, have been completed ore diagram.	60-4 must be filed once and the operator has	
*Please note this well is private surface and does not require reclamation plans. JUH 1 2013						
Notify NMOCD 24 hrs DISTRICT III prior to beginning operations						
<u></u>			• 			
14. I hereby certify that the foregoing is true and correct. Electronic Submission #413608 verified by the BLM Well Information System For BP AMERICA PRODUCTION CO, sent to the Farmington Committed to AFMSS for processing by JACK SAVAGE on 05/22/2018 (18JWS0102SE) Name (Printed/Typed) TOYA COLVIN Title REGULATORY ANALYST						
Signature (Electronic Submission)		Date 0	Date 05/04/2018			
	THIS SPACE FOR	FEDERAL OR ST	TATE OF	FICE USE		
Approved By JACK SAVAGE		TitleDET		ENGINEER	Date 05/22/2018	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			armington			
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent		ne for any person knowin	ngly and will	fully to make to any department or	agency of the United	
(Instructions on page 2) ** BLM REV	ISED ** BLM REVISED **	* BLM REVISED *	* BLM R	EVISED ** BLM REVISE	D **	
NMOCD						

5

ß

BP America

Plug And Abandonment Procedure

GCU 363

1265' FNL & 1805' FEL, Section 26, T29N, R13W

San Juan County, NM / API 30-045-26882

1. Hold pre-job safety meeting. Comply with all NMOCD, BLM safety and environmental regulations. Test rig anchors prior to moving in rig if not rigged to base beam.

2. Check casing, tubing, and bradenhead pressures.

3. Remove existing piping on casing valve. RU blow lines from casing valves and begin blowing down casing pressure. Kill well as necessary. Ensure well is dead or on a vacuum.

4. ND wellhead and NU BOP. Function test BOP.

5. P/U 4-1/2" bit or casing scraper on 2-3/8" workstring and round trip as deep as possible above top perforation at 1514'.

6. P/U 4-1/2" CR, RIH and set CR at +/- 1464'. Pressure test tubing to 1000 psi. Sting out of CR. Load hole, and pressure test casing to 800 psi. If casing does not test, then spot or tag subsequent plugs as appropriate. POOH w/ tubing.

7. RU wireline and run CBL with 500 psi on casing from CR at 1464' to surface to identify TOC. Adjust plugs as necessary for new TOC. Email log copy to Jack Savage (BLM) at <u>iwsavage@blm.gov</u> and Brandon Powell at <u>Brandon.powell@state.nm.us</u> upon completions of logging operations. 8. Rig up to pump cement down tubing. Pump water to establish rate down tubing.

NOTE: All Plugs Include 100% excess outside casing and 50% Excess inside casing

9. Plug 1 (Pictured Cliffs Interval, Fruitland Formation Top 1464'-1086', 35 Sacks Class B Cement)

Mix 35 sx Class B cement and spot a balanced plug inside casing to cover Pictured Cliffs interval and Fruitland formation top.

10. Plug 2 (Kirtland, Ojo Alamo Formation Tops and Surface Shoe 334'surface, 70 Sacks Class B Cement)

Attempt to pressure test the bradenhead annulus to 300 psi; note the volume to load. If BH annulus holds pressure, then establish circulation out casing valve with water. Mix approximately 70 sx Class B cement and spot a balanced plug from 334' to surface, circulate good cement out of casing valve. TOH and LD tubing. Shut well in and WOC. If BH annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface filling the casing from 334' and the annulus from the squeeze holes to surface. Shut in well and WOC.

11. ND cementing valves and cut off wellhead. Fill annuli with cement as necessary. Install P&A marker to comply with regulations. Record GPS coordinate for P&A marker on tower report. Photograph P&A marker in place. RD, MOL and restore location per BLM stipulations.

Wellbore Diagram Gallegos Canyon Unit 363 API #: 3004526882 San Juan, New Mexico

<u>Surface Casing</u> 7" 20# @ 125 ft

<u>Plug 2</u> 334 feet - Surface 334 feet plug 70 sacks of Class B Cement

<u>Plug 1</u> 1464 feet - 1086 feet 378 feet plug 35 sacks of Class B Cement

Perforations 1514 feet - 1560 feet <u>Formation</u> Ojo Alamo - 204 feet Kirtland - 284 feet Fruitland Coal - 1186 feet

Retainer @ 1464 feet

Production Casing 4.5" 10.5# @ 1675 ft

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE 6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: GCU #363

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."

2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

Operator will run a CBL to verify cement top. Submit the electronic copy of the log for verification to the following addresses: <u>aelmadani@blm.gov</u>. <u>brandon powell@state.nm.us</u>

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.