

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised April 3, 2017

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company LOGOS Operating, LLC	Contact: Larissa Farrell
Address 2010 Afton Place	Telephone No. (505) 787-2027
Facility Name: Heros 2308 09L 2H & Com 4H	Facility Type: Well
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-045-35687; 30-045-35847	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	09	23N	08W	1216	South	30	East	San Juan

Latitude 36.237710 Longitude -107.695149 NAD83

NATURE OF RELEASE

Type of Release: Flowback	Volume of Release 120 BBLS	Volume Recovered 0 BBLS
Source of Release Water Truck	Date and Hour of Occurrence 7/25/2018 1:00am	Date and Hour of Discovery 7/25/2018 1:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD @ 8:34am & BLM 9:44am	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse. 120 BBL	

If a Watercourse was Impacted, Describe Fully.*

Water truck rolled into arroyo after leaving location. The back latch was broken off and the flowback fluid was released into arroyo. The arroyo was not flowing at the time of incident. There was no standing water in arroyo when the incident took place.

Describe Cause of Problem and Remedial Action Taken.*

Water truck slipped off of the road after leaving location and rolled into arroyo. The back latch was broken off and 120 BBL of flowback fluid released into arroyo. Hydrovac truck was on location to pull up as much as possible. Crews were laying soaker pads and hand-digging the contaminated soil and hauling off.

Describe Area Affected and Cleanup Action Taken.*



The release was contained in the arroyo. Hand-digging and equipment will be used to remove contaminated soil. Soil will be taken to Envirotech landfarm. Working with consultant for remaining remediation. Sampling will be completed as required. BLM required archeologist to be onsite for cleanup. Archeologist will provide Class 3 survey final report.

NMOCD

JUL 26 2018

DISTRICT III

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Larissa Farrell	Approved by Environmental Specialist: 	
Title: Regulatory/Environmental Technician	Approval Date: 8/1/2018	Expiration Date:
E-mail Address: lfarrell@logosresourcesllc.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7/26/2018	Phone: 505-419-1100	

* Attach Additional Sheets If Necessary

NUR 1820751135

1